



**Toyota Motor Sales,
U.S.A., Inc.**
19001 South Western
Avenue, S207
Torrance, CA 90509-2991

TMS-NTC-14114
June 23, 2014

Recall Management Division
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

Re: Toyota Safety Recall 14V-270 – Preliminary Notice to Dealers

To whom it may concern:

Please find attached the Preliminary Notice sent to dealers for Safety Recall 14V-270 on the following Lexus model for your review:

- Certain 2013 Model Year GS350 Vehicles (Brake Pedal Load Sensing Switch)

If you have any questions regarding this matter, please contact Austin Fadel at (310) 468 - 5906

Sincerely,

A handwritten signature in black ink, appearing to read "Austin Fadel".

Austin Fadel
Quality Compliance Administrator

Attachments:

- Preliminary Notice for 14V-270 (Lexus - ELB)