

GM CUSTOMER CARE AND AFTERSALES
DCS3185
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 19, 2014

Subject: Stop Delivery Order
GM Reference Number 14302

Models: 2014 Chevrolet Corvette
Equipped with FE1 or FE3 Suspension

To: All Chevrolet Dealers

Attention: Dealer, Dealer Principal, General Manager, General Sales
Manager, New Vehicle Sales Manager, Parts and Service Director,
and Service Manager

STOP DELIVERY ORDER

Effective immediately, stop the delivery of the specific 2014 model year Chevrolet Corvette vehicles equipped with a FE1 or FE3 suspension listed in the attached file. A total of 5 vehicles are involved. The attached file provides the Vehicle Identification Number (VIN) of each involved vehicle. It is sorted by dealer Business Associate Code (BAC) for easy reference. If your dealership's BAC is not listed, then none of the involved vehicles are currently assigned to you.

These vehicles may have a rear shock weld at the lower tube to clevis bracket that has unacceptable weld penetration, leading to a potential weld fracture.

If any of these vehicles are in dealer inventory and listed in the attached file, they must be held and not delivered to customers, dealer traded, or used for demonstration purposes until further instructions are received.

All other 2014 model year Chevrolet Corvette vehicles equipped with a FE1 or FE3 suspension in dealer inventory that are not listed on the involved VIN file are not restricted from sale or delivery.

Instructions for releasing the involved vehicles from this stop delivery will be provided in the near future.

Please do not call GM Technical Assistance.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES