

The customer letter mailing was on August 18, 2014.

GM CUSTOMER CARE AND AFTERSALES  
DCS3291  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 11, 2014

Subject: 14302A – Safety Recall - Revised  
Replace Both Rear Shocks  
Customer Letter Added

Models: 2014 Chevrolet Corvette  
With Soft Ride Suspension System (RPO FE1)  
Or Sport Suspension System (RPO FE3)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
and Warranty Administrator

Bulletin 14302A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 14302.

**Customer Letter Mailing**

The customer letter mailing will begin on August 18, 2014.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES