



SUBJECT

Delivery Stop: Faulty Passenger Front Airbag

MODEL

F56 (MINI Hardtop)

SITUATION

A Delivery Stop has been issued on certain 2014 model year F56 vehicles produced from 1/26/2014-6/26/2014. These vehicles are possibly equipped with a faulty passenger front airbag.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue has been resolved. Vehicles at ports of entry will be repaired prior to dealer delivery.

Affected vehicles are listed in the attachment to this bulletin, and can be identified in the DCS history under the "Vehicle Comment" section with the statement "Vehicle Included In Delivery Stop Faulty Passenger Front Airbag."

This bulletin will be updated with repair instructions when additional information is available.