



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 8, 2015

Ms. Terri Tobias
Regulatory Compliance Manager
Highland Ridge RV
903 South Main Street
P.O. Box 460
Middlebury, IN 46540

NVS-215KS
15V-238

Subject: Wheel Stud may Break

Dear Ms. Tobias:

This letter serves to acknowledge Highland Ridge RV's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HIGHLAND RIDGE/LIGHT/2016
HIGHLAND RIDGE/MESA RIDGE/2016
HIGHLAND RIDGE/ROAMER/2016

Mfr's Report Date: April 20, 2015

NHTSA Campaign Number: 15V-238

Components:

SUSPENSION:REAR:AXLE:NON-POWERED AXLE ASSEMBLY

Potential Number of Units Affected: 103

Problem Description:

Highland Ridge RV (Highland) is recalling certain model year 2016 Open Range Mesa Ridge, Light, and Roamer travel trailers and fifth wheels, models 16LF, 16MF, 16RF, 16LT, 16MR, and 16RT, manufactured March 18, 2015, to April 6, 2015. In the affected trailers, the studs that are used to attach the wheels to the axle hubs may break.

Consequence:

If the wheel studs break, the wheel could detach from the vehicle, increasing the risk of a crash.

Remedy:

Highland will notify owners, and dealers will replace any affected wheel hub, free of charge. The recall is expected to begin May 29, 2015. Owners may contact Highland customer service at 1-260-768-7771. Highland's numbers for this recall are 9904237 and 9904238.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).


Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As required in Part 573.6(c)(6), in the case of a defect, please amend your provided chronology to include the dates of all of the principal events that were the basis for the determination that a defect related to motor vehicle safety exists.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement