



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 14, 2015

Mr. Matthew Collins
Manager
Toyota Motor Engineering & Manufacturing
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

NVS-215SM
15V-284

Subject: Driver Side Frontal Air Bag May Rupture

Dear Mr. Collins:

This letter serves to acknowledge Toyota Motor Engineering & Manufacturing's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TOYOTA/RAV4/2004-2005

Mfr's Report Date: May 13, 2015

NHTSA Campaign Number: 15V-284

Components:

AIR BAGS:FRONTAL:DRIVER SIDE INFLATOR MODULE

Potential Number of Units Affected: 159,700

Problem Description:

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain model year 2004-2005 Toyota RAV4 vehicles manufactured May 13, 2003, to October 25, 2005. The affected vehicles are equipped with a dual-stage driver frontal air bag that may be susceptible to moisture intrusion which, over time, could cause the inflator to rupture.

Consequence:

In the event of a crash necessitating deployment of the driver's frontal air bag, the inflator could rupture with metal fragments striking the driver or other occupants resulting in serious injury or death.

Remedy:

Toyota will notify owners, and dealers will replace the driver's frontal air bag, free of charge. Owners will be notified by mid-July 2015. An interim notice will be mailed if parts are not available at that time. Owners may contact Toyota customer service at 1-800-331-4331.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with the first name being more prominent.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement