



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 10, 2015

Mr. Chad Olinger
Cruiser RV
PO Box 130
Howe, IN 46746

NVS-215SM
15V-401

Subject: Wheel Attaching Studs may Break

Dear Mr. Olinger:

This letter serves to acknowledge Cruiser RV's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

CRUISER RV/STRYKER TOY/2016

Mfr's Report Date: June 18, 2015

NHTSA Campaign Number: 15V-401

Components:

SUSPENSION:REAR:AXLE:NON-POWERED AXLE ASSEMBLY

Potential Number of Units Affected: 13

Problem Description:

Cruiser RV (Cruiser) is recalling certain model year 2016 Stryker travel trailers manufactured March 23, 2015, to April 20, 2015. In the affected trailers, the studs that are used to attach the wheels to the axle hubs may break.

Consequence:

If the wheel studs break, the wheel could detach from the vehicle, increasing the risk of a crash.

Remedy:

Cruiser will notify owners, and dealers will replace any affected wheel hub, free of charge. The recall is expected to begin June 24, 2015. Owners may contact Cruiser customer service at 1-866-277-5630. Cruiser's number for this recall is 11043R & 11044R.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Cruiser's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:


You are required to submit copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement