

GM SERVICE AND PARTS OPERATIONS
DCS2098
URGENT - DISTRIBUTE IMMEDIATELY

Date: 8/14/08

Subject: Upcoming Safety Recall 08091
Windshield Wiper Linkage

Models: 2008 Buick Enclave
2007-2008 GMC Acadia
2007-2008 Saturn Outlook

To: All Buick, GMC and Saturn Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Service Manager,
Used Car Manager, Parts Manager and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) website, the media may report that General Motors will be announcing a safety recall involving certain 2008 Buick Enclave, 2007-2008 GMC Acadia and Saturn Outlook vehicles.

If a buildup of snow or ice on the windshield or on the wipers restricts the movement of the wiper arm, the windshield wiper linkage may become detached from the motor shaft and the wipers may become inoperative.

To correct this condition, dealers are to install a new wiper crank arm, driver's side link, and crank arm nut.

A total number of 88,809 vehicles are involved. Based on expected parts availability, GM anticipates releasing the recall bulletin and mailing customer notification letters in October 2008.

GMVIS information will not be available for this recall until the recall bulletin is released to dealers.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS