



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

FEB - 9 2009

MR. BRUCE KIRKBRIDE
SERVICE MANAGER
OBS, INC.
1324 TUSCARAWAS STREET W
CANTON, OH 44702

NVS-215kjs
09V-038

SUBJECT: THRESHOLD WARNING SYSTEM/FMVSS 404/RICON

DEAR MR. KIRKBRIDE:

This letter serves to acknowledge OBS Inc.'s (OBS) notification to the National Highway Traffic Safety Administration (NHTSA) of a safety noncompliance with Federal Motor Vehicle Safety Standard No. 404, "Platform Lift Installations in Motor Vehicles" in the vehicle described below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BLUE BIRD/A3EE 2803S/2006
BLUE BIRD/BBCV 2610S/2006
CHEVROLET/EXPRESS/2006

NHTSA Campaign Number: 09V-038

Mfg's Report Date: January 23, 2009

Components: EQUIPMENT ADAPTIVE

Potential Number of Units Affected: 3

Summary:

OBS IS RECALLING 3 RICON WHEELCHAIR LIFTS WHICH IT INSTALLED ON MY 2006 BLUE BIRD AND CHEVROLET EXPRESS SCHOOL BUSES. THESE VEHICLES FAIL TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 404, "PLATFORM LIFT INSTALLATIONS IN MOTOR VEHICLES." THE THRESHOLD WARNING SYSTEM MAY NOT DETECT THE PRESENCE OF A WHEELCHAIR OR

MOBILITY AID USER IN A CERTAIN SPOT WITHIN THE DEFINED THRESHOLD AREA.

Consequence:

THE USER OF THE LIFT COULD BE INJURED SHOULD THE LIFT MOVE UNINTENTIONALLY.

Remedy:

OBS IS WORKING WITH RICON TO CORRECT THE WHEELCHAIR LIFTS FREE OF CHARGE (PLEASE SEE 07E095). OWNERS MAY CONTACT RICON AT 1-818-267-3000 OR OBS AT 1-330-453-3725.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

This recall was the subject of an Equipment Query, EQ08-011, conducted by the Office of Defects Investigation.

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.


The information in your noncompliance report appears to satisfy the requirements of 49 CFR 573.6 except for the following items:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

It is our understanding that Ricon will provide quarterly status reports for this campaign.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227, by email at Kelly.Schuler@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for the successful completion of this recall campaign.

Sincerely,

A handwritten signature in black ink, appearing to be 'G. Person', written over the word 'Sincerely,'.

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement