



DAEWOO MOTOR AMERICA, INC.

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 / Fax: (310) 669-2000

July 26, 1999

Jonathan D. White, Chief
Office of Defects Investigation
U.S. Department of Transportation
National Highway Traffic Safety Administration
400 Seventh St., S.W.
Washington, D.C. 20590

Re: Door Pad Repositioning Lanos 3-Door #99V-090

Dear Mr. White:

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, first quarterly report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (909) 390-1100 ext. 213, fax (909) 390-8056.

Respectfully,


Kwang Sup Hwang
Manager, North American Certification

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 07/26/99 Calendar Quarter: 2nd Quarter
Safety Recall Quarterly Report through: 06/30/99
Manufacturer: Daewoo Motor Co. LTD.
Report Author: K. S. Hwang Phone: (909) 390-1100 ext. 213
Recall Subject: Door Pad Repositioning Lance 3 - Door

1. NHTSA Safety Recall Campaign Number: 99V-000

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-001-99

2. (a) The date notification to purchasers began: 5/07/99

(b) The date notification of purchasers was completed: 5/07/99

3. The Total Number of Items Involved: 2929

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 939

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer Inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1357

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: _____

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 10/13/99 Calendar Quarter: 3rd Quarter, 2nd Report
Safety Recall Quarterly Report through: 09/30/99
Manufacturer: Daewoo Motor Co. LTD.
Report Author: K. S. Hwang Phone: (909) 390-1100 ext. 213
Recall Subject: Door Pad Repositioning Lanos 3 - Door

1. NHTSA Safety Recall Campaign Number: 99V-090

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-001-99

2. (a) The date notification to purchasers began: 5/07/99

(b) The date notification of purchasers was completed: 5/07/99

3. The Total Number of Items Involved: 2929

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from inventory or Remedied Prior to Sale: 839

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1459

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: _____



DAEWOO MOTOR AMERICA, INC.

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 / Fax: (310) 669-2000

January 18, 2000

Jonathan D. White, Chief
Office of Defects Investigation
U.S. Department of Transportation
National Highway Traffic Safety Administration
400 Seventh St., S.W.
Washington, D.C. 20590

RECEIVED
NO JAN 29 AM 12:26
OFFICE
DEFECTS INVESTIGATION


Re: Door Pad Repositioning Lanos 3-Door #99V-080

Dear Mr. White;

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, fourth quarter report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (909) 390-1100 ext. 213, fax (909) 390-9056.

Respectfully,


Kwang Sup Hwang
Manager, North American Certification

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 1/18/2000 Calendar Quarter: 4th Quarter, 3rd Report
Safety Recall Quarterly Report through: 12/31/99
Manufacturer: Daewoo Motor Co. LTD.
Report Author: K. S. Hwang Phone: (909) 390-1100 ext. 213
Recall Subject: Door Pad Repositioning Lanos 3 - Door

1. NHTSA Safety Recall Campaign Number: 99V-080

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: R9B-001-99

2. (a) The date notification to purchasers began: 5/07/99

(b) The date notification of purchasers was completed: 5/07/99

3. The Total Number of Items Involved: 2929

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from inventory or Remedied Prior to Sale: 939

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1506

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: _____

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: 4/15/2000 Calendar Quarter: 1st Quarter, 4th Report
Safety Recall Quarterly Report through: 3/31/2000
Manufacturer: Daewoo Motor Co. LTD.
Report Author: K. S. Hyang Phone: (908) 846-0481
Recall Subject: Door Pad Repositioning Lanes 3 - Door

1. NHTSA Safety Recall Campaign Number: 99V-090

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: R5B-001-89

2. (a) The date notification to purchasers began: 5/07/99

(b) The date notification of purchasers was completed: 5/07/99

3. The Total Number of Items Involved: 2928
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 838
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1538
Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable
Total Number Exported: 0
Total Number Stolen: 0
Total Number Scrapped: 0
Total Number Unable to Notify: 0
Total Number Otherwise Unreachable: 0
Describe Other: _____



DAEWOO MOTOR AMERICA, INC.

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 Fax: (310) 669-2000

July 18, 2000

Jonathan D. White, Chief
Office of Defects Investigation
U.S. Department of Transportation
National Highway Traffic Safety Administration
400 Seventh St., S.W.
Washington, D.C. 20590

Re: Door Pad Repositioning Lanos 3-Door #99V-090

Dear Mr. White;

In accordance with Title 49 of the Code of Federal Regulations, Part 573.8, second quarter report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (909) 946-0491, fax (909) 946-0494.

Respectfully,


Kwang Sup Kwang
Manager, North American Certification

RECEIVED
00 JUL 24 PM 3:25
OFFICE OF DEFECTS INVESTIGATION

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: 7/18/2000 Calendar Quarter: 2nd Quarter, 5th Report
Safety Recall Quarterly Report through: 6/30/2000
Manufacturer: Daewoo Motor Co. LTD.
Report Author: K. S. Hwang Phone: (909) 948-0491
Recall Subject: Door Pad Repositioning Lanos 3 - Door

1. NHTSA Safety Recall Campaign Number: 99V-090

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-001-99

2. (a) The date notification to purchasers began: 5/07/99

(b) The date notification of purchasers was completed: 5/07/99

3. The Total Number of Items Involved: 2929

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 939

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1552

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: _____



DAEWOO MOTOR AMERICA, INC.

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 Fax: (310) 669-2000

October 18, 2000

Jonathan D. White, Chief
Office of Defects Investigation
U.S. Department of Transportation
National Highway Traffic Safety Administration
400 Seventh St., S.W.
Washington, D.C. 20590


Re: Door Pad Repositioning Lanos 3-Door #99V-090

Dear Mr. White;

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, third quarter and final report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (809) 466-1602.

Respectfully,


Kwang Sup Hwang
Manager, North American Certification

OFFICE OF DEFECTS INVESTIGATION
U.S. DEPARTMENT OF TRANSPORTATION
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
400 SEVENTH STREET, S.W.
WASHINGTON, D.C. 20590

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.8

Report Date: 10/18/2000 Calendar Quarter: 3rd Quarter, 6th Report
Safety Recall Quarterly Report through: 9/30/2000
Manufacturer: Daewoo Motor Co. LTD.
Report Author: K. S. Hyang Phone: (909) 946-0491
Recall Subject: Door Pad Repositioning Lanes 3 - Door

1. NHTSA Safety Recall Campaign Number: 99V-090

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSS-001-99

2. (a) The date notification to purchasers began: 5/07/99

(b) The date notification of purchasers was completed: 5/07/99

3. The Total Number of Items Involved: 2929

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 939

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1556

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: 0

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: _____



DAEWOO MOTOR CO. LTD,

RECEIVED

99 JUL 28 AM 10:35

OFFICE
DEFECTS INVESTIGATION

July 22, 1999

Jonathan D. White, Chief
Office of Defects Investigation
U.S. Department of Transportation
National Highway Traffic Safety Administration
400 Seventh St., S.W.
Washington, D.C. 20590

Re : Lanos Door Recall Campaign # 99V-090.001

Dear Mr. White

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, first quarter report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (909) 390-1100 Ext. 213, Fax (909) 390-9056

Respectfully

A handwritten signature in black ink, appearing to read "Kwang Sub Hwang".

Kwang Sub Hwang
Manager, North American Certification

Safety Recall Quarterly Report Information
Required per 48 CFR Part 673.5

Report Date: 07/22/1999 Calendar Quarter: 2nd Quarter
Safety Recall report through: 06/30/1999
Manufacturer: Daewoo Motor Co., LTD.
Report Author: K.S. Hwang Phone: (909) 390-1100 ext. 213
Recall Subject: Lance Door Pad

1. NHTSA Safety recall Campaign Number 99V-090-001

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-001-95

2. (a) The date notification to purchaser began: 05/13/1999

(b) The date notification of purchasers was completed: 05/18/1999

3. The Total Number of Items Involved: 9,794

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of Items Returned from Inventory or Remedied Prior to Sale: 2,488

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer Inventory or (b) otherwise remedied prior to sale to customers.

4. (a) Total Number Inspected and Remedied: 4,267

Total number of items, which were inspected and/or otherwise repaired and remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 1 (List Enclosed)

Total Number Scrapped: 7 (List Enclosed)

Total Number Unable to Notify: 847

Total Number Otherwise Unreachable: 23 (List Enclosed)

Describe Other: The list of stolen, scrapped and otherwise unreachable units is enclosed.

We are starting to find the customers of unreachable units.

The List of Unreachable Units

Recall Campaign Number : 86V-305.001 (Lanos Steering Wheel)
 (Attachment of 2nd Quarter Report of 1999)

Classification	Total Units	No.	V.I.N.	Status	Remarks
1. Exported	0				
2. Stolen	1	1	KLATC2281WB200926		
3. Scrapped	7	1	KLATA22Y6WB189011		
		2	KLATA52Y0WB194723		
		3	KLATC228XWB201880		
		4	KLATC2281WB210497		
		5	KLATA52Y4WB189010		
		6	KLATA52Y5WB181778		
		7	KLATA22Y6WB208236		
4. Unable to Notify	847			Certified Mail Returned	Trying to reach through sales-dealers

The List of Unreachable Units

Recall Campaign Number : 86V-305.001 (Lanox Steering Wheel)
(Attachment of 2nd Quarter Report of 1999)

Classification	Total Units	No.	V.I.N.	Status	Remarks
5. Otherwise Unreachable	23	1	KLATC2282WB190802	Confiscated by Police	Trying to reach through financing Institute
		2	KLATA52Y7WB209673		
		3	KLATC2280WB268950	Repossed by financing Institute	
		4	KLATA22Y8WB188438		
		5	KLATC2288WB210483		
		6	KLATC2288WB210484		
		7	KLATC5284WB193824		
		8	KLATA22Y8WB288853		
		9	KLATA22Y1WB187021		
		10	KLATC2281WB200648		
		11	KLATB52Y4WB204490		
		12	KLATA22Y2WB206962		
		13	KLATC2287WB203882		
		14	KLATC2288WB203848		
		15	KLATB52Y8WB204378		
		16	KLATA22Y7WB205022		
		17	KLATA22Y4WB268985		
		18	KLATA22Y2WB187125		
		19	KLATA22Y9WB191852		
		20	KLATC2280WB200836		
		21	KLATC2281WB201301		
		22	KLATC2289WB203560		
		23	KLATB22YXWB188763		
Total Units of Unreachable	878				Data as of 6/30/1999

DAEWOO MOTOR COMPANY, INC.

October 26, 1999

Jonathan D. White, Chief
Office of Defects Investigation
U.S. Department of Transportation
National Highway Traffic Safety Administration
400 Seventh St., S.W.
Washington, D.C. 20590

Re : Lanos Door Recall Campaign # 99V-090.001

Dear Mr. White

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, 3rd calendar quarter report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (909) 390-1100 Ext. 213, Fax (909) 390-9056

Respectfully



Kwang Sup Hyang
Manager, North American Certification

RECEIVED
OCT 27 1999
NHTSA

Safety Recall Quarterly Report Information

Required per 48 CFR Part 573.6

Report Date: 10/20/1999 Calendar Quarter: 3rd. Quarter

Safety Recall report through: 09/30/1999

Manufacturer: Daewoo Motor Co., LTD.

Report Author: Kwangsop Hwang Phone: (908) 390-1100 ext. 213

Recall Subject: Lanos Door Pad

1. NHTSA Safety recall Campaign Number 98V-090.001

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-001-99

2. (a) The date notification to purchaser began: 06/13/1999

(b) The date notification of purchasers was completed: 05/18/1999

3. The Total Number of Items Involved: 9,794

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of Items Returned from Inventory or Remedied Prior to Sale: 2,498

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to customers.

4. (a) Total Number Inspected and Remedied: 5,888

Total number of items, which were inspected and/or otherwise repaired and remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 2 (List Enclosed)

Total Number Scrapped: 17 (List Enclosed)

Total Number Unable to Notify: 847

Total Number Otherwise Unreachable: 80 (List Enclosed)

Describe Other: Repossessed by Banks-48

Confiscated by Police-2

Safety Recall Quarterly Report Information
 Required per 49 CFR Part 573.6

Report Date: 04/10/2000 Calendar Quarter: 1st. Quarter

Safety Recall report through: 03/30/2000

Manufacturer: Daewoo Motor Co., LTD.

Report Author: K.S. Hwang Phone: (909) 946-0491

Recall Subject: Lance Door Pad

1. NHTSA Safety recall Campaign Number 99V-090-001

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-001-99

2. (a) The date notification to purchaser began: 05/13/1999

(b) The date notification of purchasers was completed: 06/18/1999

3. The Total Number of Items Involved: 9,794

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of Items Returned from Inventory or Remedied Prior to Sale: 2,498

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer Inventory or (b) otherwise remedied prior to sale to customers.

4. (a) Total Number Inspected and Remedied: 6,299

Total number of items, which were inspected and/or otherwise repaired and remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 22 (List Enclosed)

Total Number Scrapped: 28 (List Enclosed)

Total Number Unable to Notify: 647

Total Number Otherwise Unreachable: 129 (List Enclosed)

Describe Other: Confiscated by Police: 2
Repossessed by banks: 127

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 07/18/2008 Calendar Quarter: 2nd. Quarter

Safety Recall report through: 06/30/2008

Manufacturer: Daejeon Motor Co., LTD.

Report Author: K.S. Hwang Phone: (908) 848-0491

Recall Subject: Lance Door Pad

1. NHTSA Safety recall Campaign Number 89V-090-001

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RBE-081-98

2. (a) The date notification to purchaser began: 05/13/1999

(b) The date notification of purchasers was completed: 05/18/1999

3. The Total Number of Items Involved: 9,794

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of Items Returned from Inventory or Remedied Prior to Sale: 2,488

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to customers.

4. (a) Total Number Inspected and Remedied: 6,328

Total number of items, which were inspected and/or otherwise repaired and remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 19 (List Enclosed)

Total Number Scrapped: 28 (List Enclosed)

Total Number Unable to Notify: 847

Total Number Otherwise Unreachable: 107 (List Enclosed)

Describe Other: Confiscated by Police: 2
Repossessed by banks 105