



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 16, 2010

MR. RICHARD VAN LAAR
COMPLIANCE MANAGER
NAVISTAR, INC.
3033 WAYNE TRACE P.O. BOX 10088
FORT WAYNE IN 46850-0088

NVS-215kjs
10V-267

SUBJECT: UNEXPECTED SHIFT IN VEHICLE POSITION

DEAR MR. VAN LAAR:

This letter serves to acknowledge Navistar, Inc.'s (Navistar) notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall campaign which will be conducted pursuant to Federal law for the vehicles listed below.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

IC/3300/2005-2010
IC/BE/2008
IC/CE/2005-2008
IC/HC/2007-2008
IC/SFC/2005-2006
INTERNATIONAL/1652SC/2005-2007
INTERNATIONAL/3200/2004-2008
INTERNATIONAL/4100/2006-2008
INTERNATIONAL/4200/2003-2010
INTERNATIONAL/RXT/2006-2007
INTERNATIONAL/TSV/2009

NHTSA Campaign Number: 10V-267 **Mfg's Report Date:** June 14, 2010

Components: VEHICLE SPEED CONTROL

Potential Number of Units Affected: 2,085

Summary:

NAVISTAR IS RECALLING CERTAIN MODEL YEAR 2003 THROUGH 2010 INTERNATIONAL TRUCKS AND IC COMMERCIAL BUSES MANUFACTURED FROM DECEMBER 4, 2001 THROUGH DECEMBER 14, 2009 EQUIPPED WITH INTERNATIONAL VT365 ENGINES HAVING ENGINE CALIBRATION PAN2PVR0, PAN2PVR1, OR PAN2PWR. THE ENGINE NORMALLY RESPONDS TO A FAILED OPEN ACCELERATOR POSITION SENSOR CIRCUIT FAULT BY RETURNING THE ENGINE TO LOW IDLE SPEED OF 800 RPM AND DISABLING THE DRIVER'S ABILITY TO INCREASE THE ENGINE SPEED. HOWEVER IF THE OPEN CIRCUIT CORRECTS ITSELF WITHIN 30 SECONDS OF INITIATION, ENGINE SPEED COULD SUDDENLY INCREASE TO A HIGH IDLE SPEED OF 1200 RPM.

Consequence:

THIS INCREASE TO HIGH IDLE SPEED MAY OCCUR WITHOUT WARNING CAUSING A SUDDEN AND UNEXPECTED SHIFT IN VEHICLE POSITION POSSIBLY RESULTING IN PROPERTY DAMAGE, PERSONAL INJURY, OR DEATH.

Remedy:

NAVISTAR WILL NOTIFY OWNERS AND DEALERS WILL REPAIR THE VEHICLES FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN ON OR ABOUT AUGUST 16, 2010. OWNERS MAY CONTACT NAVISTAR AT 1-800-448-7825.

Notes:

NAVISTAR'S CAMPAIGN NUMBER IS 10512. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6 except for the following items:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within 30 days after the close of the calendar quarter in which the campaign was initiated. Thereafter, quarterly reports will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227, by email at Kelly.Schuler@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for the successful completion of this recall campaign.

Please note that we have separated your report into two recall files. This has been done because beginning in 2010, RMD will closely monitor the completion of school bus recalls and must be able to create analysis of school bus recall data. You will also be required to file separate quarterly status reports for the school bus population under the applicable recall number. We trust that this does not present an insurmountable task for you and that you appreciate the need to ensure that school bus recalls are completed promptly. If you have any questions about this policy, please feel free to call me at (202) 366-5210.

Sincerely,

A handwritten signature in blue ink, appearing to read "G. Person".

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement