

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Quarterly Defect Report
Required per CFR Part 573.6

Report Date: **July 2, 2003**

Calendar Quarter: **1**

Safety Recall Quarterly Report from: **April 7, 2003 through June 30, 2003**

Manufacturer: **Fleetwood Enterprises, Inc.**

Report Author: **Robert E. Wozniak**

Phone: **909-351-3814**

Recall Subject: **2000-2003 Southwind, Storm, Fiesta, Terra, Flair, Boulder, Pace Arrow, Pace Arrow Vision built on Ford F53 Chassis - Brake System Warning Indicator**

1. NHTSA Safety Recall Campaign Number: 03V-066

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: **30312**

2. (a) The date notification to purchasers began:

1st mailing: April 7, 2003

2nd mailing:

(b) The date the 3rd notification mailing to purchasers was completed:

3. The total number of items involved: 11,243

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: 168

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

4. (a) Total number inspected and remedied: 2952

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected and NOT REQUIRING REMEDY: 343

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items determined to be UNREACHABLE:

Total number exported: **0**

Total number stolen: **0**

Total number scrapped: **0**

Total number unable to identify: **0**

Total number otherwise unreachable: **40**