

VOLKSWAGEN

GROUP OF AMERICA

Mr. Daniel Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Avenue, S.E.
Washington, DC 20590

CHRISTOPHER T. SANDVIG NAME
GENERAL MANAGER COMPLIANCE/TREAD TITLE
PRODUCT COMPLIANCE DEPARTMENT
248-754-5000 PHONE
248-754-5093 FAX
JANUARY 24, 2011 DATE

Subject: Amended Notification of Recall
2006 – 2010 MY Volkswagen Jetta
2007 – 2009 MY Rabbit
2009 – 2010 MY Jetta SportWagen
2006 – 2010 MY New Beetle, New Beetle Convertible
Inspect Fuel Line on Vehicles Equipped with 2.5L engine

VOLKSWAGEN GROUP OF AMERICA, INC.
3800 HAMLIN ROAD
AUBURN HILLS, MI 48326
PHONE +1 248 754 5000

Dear Mr. Smith:

This will amend our Part 573 report dated December 17, 2010 by providing the following updated information:

573.6 (c) (2) **Identification of Vehicles**

Model Year : Jetta: 2006 – 2010
Rabbit: 2007 – 2009
Jetta SportWagen: 2009 – 2010
New Beetle, New Beetle Convertible: 2006 – 2010

Month/Year of Manufacture : Jetta: March 2006 through June 2009
Rabbit: March 2007 through November 2008
Jetta SportWagen: January 2008 through March 2009
New Beetle & New Beetle Convertible: June 2005 through October 2009

VIN Numbers of Affected Vehicles: Jetta: 3VW__1K_6M797912 – 3VW__AJ_AM001672
Rabbit: WVV__1K_7W251693 – WVV__1K_9W150037
Jetta SportWagen: 3VW__1K_9M250001 – 3VW__AJ_AM600044
New Beetle: 3VW__1C_6M400067 – 3VW__AG_AM007751
New Beetle Convertible: 3VW__1Y_6M300067 – 3VW__AL_AM001714

573.6 (c) (3) **Number of Vehicles Potentially Containing the Defect**
Approximately 228,236 Jetta and Jetta SportWagens, 38,997 Rabbits and 110,436 New Beetle and New Beetle Convertibles are affected by this recall in the United States

Sincerely,


Christopher T. Sandvig
General Manager Compliance/TREAD