

TOYOTA

TOYOTA MOTOR NORTH AMERICA, INC.

WASHINGTON OFFICE
601 THIRTEENTH STREET, NW, SUITE 910 SOUTH, WASHINGTON, DC 20005

TEL: (202) 775-1700
FAX: (202) 463-8513

April 29, 2011

Mr. Daniel C. Smith
Senior Associate Administrator for Vehicle Safety
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, D.C. 20590

RE: Recall 09V-388 (9LG/90L)
Amended Part 573 Notification: Certain Toyota and Lexus Vehicles
Potential Floor Mat Interference with Accelerator Pedal


Dear Mr. Smith:

In connection with the above referenced matter, this supplements Toyota's letter of February 24, 2011. Toyota is now providing some additional vehicle information as follows:

Make/ Car Line	Model Year	Manufac -turer	VIN		Production Period	Population
			VDS	VIS		
Lexus/ LX570	2008- 2011	TMC	HY###	4000112 – 4070218	July 12, 2007 through April 26, 2011	17,853

Should you have any questions, please contact the undersigned.

Sincerely,



Vinnie Venugopal
General Manager
Toyota Motor Engineering & Manufacturing
North America, Inc.