

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Quarterly Defect Report
Required per CFR Part 573.6

Report Date: **October 1, 2003**

Calendar Quarter: **2**

Safety Recall Quarterly Report from: **April 7, 2003 through September 30, 2003**

Manufacturer: **Fleetwood Enterprises, Inc.**

Report Author: **Robert E. Wozniak**

Phone: **909-351-3814**

Recall Subject: **2000-2003 Southwind, Storm, Fiesta, Terra, Flair, Boulder, Pace Arrow, Pace Arrow Vision built on Ford F53 Chassis - Brake System Warning Indicator**

1. NHTSA Safety Recall Campaign Number: **03V-066**

Also, for completeness, if your company has assigned a code number to this campaign, provide your code: **30312**

2. (a) The date notification to purchasers began:

1st mailing: **April 7, 2003**

2nd mailing:

(b) The date the 3rd notification mailing to purchasers was completed:

3. The total number of items involved: **11,243**

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of items returned from inventory or remedied prior to sale: **168**

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers. Do not include this number in 4 (a) or 4 (b).

4. (a) Total number inspected and remedied: **4159**

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected and NOT REQUIRING REMEDY: **483**

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items determined to be UNREACHABLE:

Total number exported:	0
Total number stolen:	0
Total number scrapped:	0
Total number unable to identify:	0
Total number otherwise unreachable:	115

RECEIVED
2003 OCT 14 A 9:13
OFFICE OF DEFECTS INVESTIGATION