

**INITIAL ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 00V-158 by the
National Highway Traffic Safety Administration

Part 573 Report Date: **June 2, 2000**

6/13/00

MANUFACTURER: **Triumph Motorcycles Ltd.**

MANUFACTURER CONTACT: **Mr. Shell Barr, Warranty/Service Department**

FAX: **(770) 631-8577**

SUBJECT: **763 Triumph 2000 TT600 motorcycles manufactured from December 9, 1999 through May 16, 2000. The sprag clutch housing bolts become loose due to inappropriate assembly method. This can lead to engine damage.**

This is an initial acknowledgment for this recall. A formal acknowledgment letter will be forthcoming shortly. After our review of your report and associated documents, we may have additional comments or concerns.

In accordance with Part 577, amended July 7, 1995, a draft owner notification letter must be submitted for review prior to mailing as well as an estimated owner notification date.

If you have any questions, please call:



Patricia Wallace, Recall Analyst on (202) 366-5232 or
Jonathan White, Chief on (202) 366-5226
or by fax on (202) 366-7882
Recall Analysis Division

JUL 26 2000

Mr. C. H. Smart
Warranty Co-ordinator
Triumph Motorcycles Ltd.
Jacknell Road
Dodwells Bridge Ind. Est.
Hinckley, Leicestershire, England
LE1038S

NSA-11paw
00V-158

Dear Mr. Smart:

We have reviewed Triumph Motorcycles Ltd.'s (Triumph) Defect Information Report dated June 2, 2000, submitted in accordance with 49 CFR Part 573, "Defect and Noncompliance Reports." This recall involves 763 Triumph 2000 TT600 motorcycles manufactured from December 9, 1999 through May 16, 2000. The sprag clutch housing bolts become loose due to inappropriate assembly method. This can lead to engine damage. **The assigned recall identification number for this recall is 00V-158.**

Triumph is responsible for the remedy of these motorcycles from this date forward, regardless of vehicle age, mileage, or ownership.

Quarterly Status Reports

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification was expected to begin during June 2000. Therefore, the first quarterly report will be due in this office by July 30, 2000.

If you have any questions, please contact Mrs. Pat Wallace at (202) 366-5232, or fax at (202) 366-7882.

Sincerely,



Jonathan D. White, Chief
Recall Analysis Division
Office of Defects Investigation
Safety Assurance