

Jim Colver@US\_GM\_PON\_POC01, Karen D. Raab@US\_GM\_PON\_POC01, Robert  
Zavadl@US/GM/GMC@GM, Karen A. Grimaldi@US/GM/GMC@GM, Teana A Joseph@US/GM/GMC@GM,  
Dana E. Evanoff@US/GM/GMC@GM

GM SERVICE OPERATIONS

DCSS92

URGENT - DISTRIBUTE IMMEDIATELY

00V-222

DATE: SEPTEMBER 15, 2000

SUBJECT: 00051 - F/CMVSS NONCOMPLIANCE CAMPAIGN  
POWER BRAKE BOOSTER VACUUM SUPPLY HOSE  
KINKED

MODELS: 2000 CHEVROLET AND GMC 1/2 TON C/K UTILITIES AND  
SUBURBANS EQUIPPED WITH VACUUM POWER FOUR WHEEL  
DISC BRAKES (RPO JC5) BUILT AT JANESVILLE  
ASSEMBLY PLANT

TO: ALL CHEVROLET AND GMC DEALERS

ATTN: SERVICE MANAGER, PARTS MANAGER  
AND WARRANTY ADMINISTRATOR

CONDITION

General Motors has decided that certain 2000 Chevrolet and GMC 1/2 ton C/K utilities and Suburbans equipped with vacuum power, four-wheel-disc brakes (RPO JC5), and built at Janesville Assembly Plant, may fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) 105, "Hydraulic Service Brake - Normal, Emergency, and Park Braking Performance" or Canada Motor Vehicle Safety Standard (CMVSS) 105, "Hydraulic and Electrical Brake Systems." These vehicles may have been built with a kinked brake booster vacuum supply hose. A vehicle with a sufficiently kinked brake vacuum hose does not comply with certain stopping distance requirements related to multiple brake applications of F/CMVSS 105. If a vehicle required minimal stopping distance under these brake application conditions, a vehicle crash could occur.

CORRECTION

Dealers are to reroute the brake booster vacuum supply hose.

VEHICLES INVOLVED

Involved are certain 2000 Chevrolet and GMC 1/2 ton C/K utilities and Suburbans equipped with vacuum power, four-wheel-disc brakes (RPO JC5), built at Janesville Assembly Plant, and built within these VIN breakpoints:

| YEAR | DIVISION | MODEL | PLANT      | FROM     | THROUGH  |
|------|----------|-------|------------|----------|----------|
| 2000 | GMC/Chev | C/K   | Janesville | YJ100001 | YJ104401 |

**IMPORTANT:** Dealers should confirm vehicle eligibility through GMVIS (GM Vehicle Inquiry System) or GM Access Screen (Canada only) or DCS Screen 445 (IPC only) before beginning campaign repairs. [Not all vehicles within the above breakpoints may be involved.]

**MAILING INFORMATION**

Dealer mailing will begin on September 15, 2000.  
Owner mailing will begin on September 22, 2000.

**GMVIS INFORMATION**

GMVIS information will be available September 18, 2000.  
End of Message

**GM Service Operations**