

4-28-04

5. Number of Vehicles Determined Unreachable for Inspection: 0

E. **Recall Subject:** 03V-229 Vegas Fuel Tank Vent Obstruction (49St, CDN, UK)
Report Quarter: 3rd Quarter

1. NHTSA Assigned Campaign Number: 03V-229
Company Assigned Number: Bulletin V-03-04(A)
2. Date Notification Began: July 25, 2003
Date Notification was Completed: August 1, 2003
3. Number of Vehicles Involved: 1070
4. Number of Vehicles Inspected and Repaired: 318
Number Inspected and Not Needing Repair: 0

5. Number of Vehicles Determined Unreachable for Inspection: 0

F. **Recall Subject:** 03V-336 Unexpected Sidestand Deployment
Report Quarter: 2nd Quarter

1. NHTSA Assigned Campaign Number: 03V-336
Company Assigned Number: Bulletin V-03-05SAF
2. Date Notification Began: November 6, 2003
Date Notification was Completed: November 13, 2003
3. Number of Vehicles Involved: 9,120
4. Number of Vehicles Inspected and Repaired: 0
Number Inspected and Not Needing Repair: 0

5. Number of Vehicles Determined Unreachable for Inspection: 0

G. **Recall Subject:** 03V-337 Vegas Fuel Leak at Fuel Tank Vent Fitting
Report Quarter: 2nd Quarter

1. NHTSA Assigned Campaign Number: 03V-337
Company Assigned Number: Bulletin V-03-06
2. Date Notification Began: September 25, 2003
Date Notification was Completed: October 2, 2003
3. Number of Vehicles Involved: 106
4. Number of Vehicles Inspected and Repaired: 50