

Dealer TO: ALL CADILLAC, CHEVROLET, GMC AND  
Salutation: HUMMER DEALERS

ATTENTION: SERVICE MANAGER, PARTS MANAGER AND WARRANTY ADMINISTRATOR

GM SERVICE AND PARTS OPERATIONS  
DCS1202  
URGENT DISTRIBUTE IMMEDIATELY

DATE: June 11, 2004

SUBJECT: 04004 Non Compliance Recall  
Brake Hydro Boost Relief Valve Seal Fracture

MODELS: 2003-2004 Cadillac Escalade, Escalade EXT, Escalade ESV  
2003-2004 Chevrolet Silverado, Avalanche, Suburban, Express  
2004 Chevrolet Tahoe  
2003-2004 GMC Sierra, Yukon, Yukon XL, Savana  
2003-2004 Hummer H2

TO: All Cadillac, Chevrolet, GMC and Hummer Dealers

ATTENTION: Service Manager, Parts Manager and Warranty Administrator

PRODUCT FIELD ACTION ANNOUNCEMENT

General Motors is announcing Non Compliance Recall 04004 today. The total number of vehicles involved is 75,468. Please see the attached bulletin for details.

**Mailing Information**

Customer notification letter mailing will begin on June 18, 2004.

**GM Vehicle Inquiry System (GMVIS)**

GMVIS information will be available on June 12, 2004.

**Service Information System (SI)**

Bulletin 04004 is scheduled to be available in SI in the near future.

**Campaign Initiation Detail Report (CIDR)**

**The CIDR will be available in GM DealerWorld on June 11, 2004.**

**PLEASE DOUBLE CLICK ON THE ICON BELOW  
THEN SINGLE CLICK ON THE LAUNCH BUTTON  
TO VIEW OR PRINT THE LETTER**

**(See attached file: 04004 Bulletin.pdf)**

**END OF MESSAGE**

**GM SERVICE AND PARTS OPERATIONS**