



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

400 Seventh Street, SW  
Washington, DC 20590

**ACKNOWLEDGEMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION  
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **04V-410** by the  
National Highway Traffic Safety Administration

Part 573 Report Date: **August 18, 2004**

Date Faxed/E-Mailed: **August 24, 2004**

MANUFACTURER: **PACCAR Inc.,**

MANUFACTURER CONTACT: **Kenneth Brownstein, Senior Counsel**

FAX: **425-468-8228**

**SUBJECT: 311 Paccar 2004 Kenworth T2000 models trucks. The bracket box that supports the battery and step develops a crack. If the bracket cracks, injury and an accident may occur. Kenworth's Recall No. 04KW5.**

This is an acknowledgment for this recall. A formal acknowledgment will be written only if we have additional comments or concerns.

Please provide us with a draft owner notification letter for our review before mailing to consumers.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, the recall is expected to begin during September 2004. Since this will be close to the end of the quarter, the first quarterly report will be due by January 30, 2005.

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or  
George Person, Chief on (202) 366-5210  
or Fax at (202) 366-7882  
or e-mail at [Patricia.Wallace@nhtsa.dot.gov](mailto:Patricia.Wallace@nhtsa.dot.gov)  
Recall Management Division