



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

400 Seventh Street, SW
Washington, DC 20590

**ACKNOWLEDGEMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **04V-412** by the
National Highway Traffic Safety Administration

Part 573 Report Date: **August 23, 2004**

Date Faxed/E-Mailed: **August 25, 2004**

MANUFACTURER: **Polaris Industries/Victory Motorcycle Division**

MANUFACTURER CONTACT: **Suzanne Peterson, Victory Motorcycle Division**

FAX: **715-294-2518**

SUBJECT: **1,635 Victory 2003 Vegas motorcycles manufactured from June 25, 2002 through June 17, 2003. The vent tube joint located at the bottom right side of the fuel tank (part number 1013821) may fatigue and leak fuel. Victory Recall No. V-04-02.**

This is an acknowledgment for this recall. A formal acknowledgment will be written only if we have additional comments or concerns.

Please provide us with a draft owner notification letter for our review before mailing to consumers.

NOTE: We will need a date of when the manufacturer became aware of the recall.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, the recall is expected to begin September 15, 2004. Since this will be close to the end of the quarter, the first quarterly report will be due by January 30, 2005.

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or
George Person, Chief on (202) 366-5210
or Fax at (202) 366-7882
or e-mail at Patricia.Wallace@nhtsa.dot.gov
Recall Management Division