



July 12, 2004

Dear Service Manager:

Enclosed is the following service publication:

Campaign Responsibility Report for the Accord LX V6 Instrument Panel Lighting Recall Campaign.

Of the 2000-01 Accord LX V6 vehicles reported as delivered to your dealership, those eligible for the Accord LX V6 Instrument Panel Lighting Recall Campaign, *but not yet fixed*, are listed in the left-hand column. Some of them may have a two-letter code under the heading "UNIT STAT." A complete listing of the codes and what they mean is on page 7-6 of your Service Operations Manual.

If you have any questions, please contact your District Parts and Service Manager.

Sincerely,

**American Honda Motor Co., Inc.
Honda Automobile Division**

A handwritten signature in cursive script that reads "Dennis Yamazaki".

**Dennis Yamazaki
Sr. Publications Coordinator
Parts and Service Communications**

Honda Automobile Division