

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: January 30, 2001 Calendar Quarter: 2
Safety Recall Quarterly Report from: November 21, 2000 through: January 30, 2001
Manufacturer: Privoet Car Inc.
Report author: Joysana Côté Phone: 1-418-831-2048
Recall Subject: Reinforcement bracket on tag axle

1- NHTSA Safety Recall Campaign Number: 00V-389
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37

2 (a) The date notification to purchaser began: 21-11-00
(b) The date notification of purchasers was completed: 21-11-00

3- The Total Number of Items¹ Involved: 3083
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 84
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

4- (a) Total Number Inspected & Remedied: 113 (4%)
Total number of items which were inspected and / or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5- Items Determined to be Unreachable:

Total Number Exported:	0
Total Number Stolen:	0
Total Number Scrapped:	0
Total Number Unable to Notify:	0
Total Number Otherwise:	0
Describe Other:	0

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: April 30, 2001 Calendar Quarter: 3
Safety Recall Quarterly Report from: October 30, 2000 through: April 30, 2001
Manufacturer: Prévost Car Inc.
Report author: Jocelyne Côté Phone: 1-418-831-2046
Recall Subject: Coolant heaters' problem

- 1- **NHTSA Safety Recall Campaign Number: 00V-342**
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: **SR00-28**
- 2 (a) The date notification to purchaser began: **2-10-00**
(b) The date notification of purchasers was completed: **2-10-00**
- 3- **The Total Number of Items¹ Involved: 487**
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).
- Number of Items Returned from Inventory or Remedied Prior to Sale: 0**
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
- 4- (a) **Total Number Inspected & Remedied: 334 (69%)**
Total number of items which were inspected and / or otherwise repaired or remedied.
- (b) **Total Number Inspected & NOT REQUIRING REMEDY: 0**
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- 5- **items Determined to be Unreachable:**
- | | |
|--------------------------------|---|
| Total Number Exported: | 0 |
| Total Number Stolen: | 0 |
| Total Number Scrapped: | 0 |
| Total Number Unable to Notify: | 0 |
| Total Number Otherwise: | 0 |
| Describe Other:: | 0 |

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: July 30, 2001 Calendar Quarter: 4
Safety Recall Quarterly Report from: November 21, 2000 through: July 30, 2001
Manufacturer: Prévost Car Inc.
Report author: Josyane Côté Phone: 1-418-831-2048
Recall Subject: Reinforcement bracket on tag axle

- 1- NHTSA Safety Recall Campaign Number: 00V-389
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-57
- 2 (a) The date notification to purchaser began: 21-11-00
(b) The date notification of purchasers was completed: 21-11-00
- 3- The Total Number of Items¹ Involved: 3083
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).
- Number of Items Returned from Inventory or Remedied Prior to Sale: 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
- 4- (a) Total Number Inspected & Remedied: 2216 (72%)
Total number of items which were inspected and / or otherwise repaired or remedied.
- (b) Total Number Inspected & NOT REQUIRING REMEDY: 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- 5- Items Determined to be Unreachable:
- | | |
|--------------------------------|---|
| Total Number Exported: | 0 |
| Total Number Stolen: | 0 |
| Total Number Scrapped: | 0 |
| Total Number Unable to Notify: | 0 |
| Total Number Otherwise: | 0 |
| Describe Other:: | 0 |

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

RECEIVED
OFFICE
OF INVESTIGATIONS

SEP 21 11 23 AM '01

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: Dec 6, 2001 Calendar Quarter: 3
Safety Recall Quarterly Report from: November 21, 2000 through: Sept 30, 2001
Manufacturer: Prévost Car Inc.
Report author: Dany Bertrand Phone: 1-418-831-2046
Recall Subject: Reinforcement bracket on tag axle

- 1- NHTSA Safety Recall Campaign Number: 06V-388
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37
- 2 (a) The date notification to purchaser began: 21-11-00
(b) The date notification of purchasers was completed: 21-11-00
- 3- The Total Number of Items¹ Involved: 3083
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).
- Number of Items Returned from Inventory or Remedied Prior to Sale: 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
- 4- (a) Total Number Inspected & Remedied: 2309 (75%)
Total number of items which were inspected and / or otherwise repaired or remedied.
- (b) Total Number Inspected & NOT REQUIRING REMEDY: 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- 5- Items Determined to be Unreachable:
- | | |
|--------------------------------|---|
| Total Number Exported: | 0 |
| Total Number Stolen: | 0 |
| Total Number Scrapped: | 0 |
| Total Number Unable to Notify: | 0 |
| Total Number Otherwise: | 0 |
| Describe Other:: | 0 |

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: Jan 22, 2002 **Calendar Quarter:** 4
Safety Recall Quarterly Report from: November 21, 2000 **through:** Dec 30, 2001
Manufacturer: Prevost Car Inc.
Report author: Dany Bertrand **Phone:** 1-418-831-2046
Recall Subject: Reinforcement bracket on tag axle

- 1- **NHTSA Safety Recall Campaign Number:** 00V-389
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37
- 2- (a) **The date notification to purchaser began:** 21-11-00
(b) **The date notification of purchasers was completed:** 21-11-00
- 3- **The Total Number of Items¹ Involved:** 3083
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).
- Number of Items Returned from Inventory or Remedied Prior to Sale:** 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
- 4- (a) **Total Number Inspected & Remedied:** 2485 (81%)
Total number of items which were inspected and / or otherwise repaired or remedied.
- (b) **Total Number Inspected & NOT REQUIRING REMEDY:** 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- 5- **Items Determined to be Unreachable:**
- | | |
|---------------------------------------|---|
| Total Number Exported: | 0 |
| Total Number Stolen: | 0 |
| Total Number Scrapped: | 0 |
| Total Number Unable to Notify: | 0 |
| Total Number Otherwise: | 0 |
| Describe Other:: | 0 |

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.8

Report Date: Apr 17, 2002 Calendar Quarter: 1
Safety Recall Quarterly Report from: November 21, 2000 through: Mar 31, 2002
Manufacturer: Prévost Car Inc.
Report author: Dery Bertrand Phone: 1-418-831-2048
Recall Subject: Reinforcement bracket on tag axle

- 1- NHTSA Safety Recall Campaign Number: 00V-389
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37
- 2- (a) The date notification to purchaser began: 21-11-00
(b) The date notification of purchasers was completed: 21-11-00
- 3- The Total Number of Items¹ Involved: 3063
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).
- Number of Items Returned from Inventory or Remedied Prior to Sale: 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.
- 4- (a) Total Number Inspected & Remedied: 2583 (84%)
Total number of items which were inspected and / or otherwise repaired or remedied.
- (b) Total Number Inspected & NOT REQUIRING REMEDY: 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.
- 6- Items Determined to be Unreachable:
- | | |
|--------------------------------|---|
| Total Number Exported: | 0 |
| Total Number Stolen: | 0 |
| Total Number Scrapped: | 0 |
| Total Number Unable to Notify: | 0 |
| Total Number Otherwise: | 0 |
| Describe Other:: | 0 |

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: November 28, 2002 **Calendar Quarter:** 2
Safety Recall Quarterly Report from: November 21, 2000 **through:** November 28, 2002
Manufacturer: Prévost Car Inc.
Report author: Josyane Côté **Phone:** 1-418-831-2048
Recall Subject: Reinforcement bracket on tag axle

1- **NHTSA Safety Recall Campaign Number:** 00V-389
Transport Canada Recall Campaign Number: 01-010
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37

2- (a) **The date notification to purchaser began:** 21-11-00
(b) **The date notification of purchasers was completed:** 21-11-00

3- **The Total Number of Items¹ Involved in USA:** 2162
The total Number of Items Involved in Canada: 1108
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

4- **Total Number Inspected & Remedied in Usa:** 1776 (Completion % = 82%)
Total Number Inspected & Remedied in Canada: 826 (Completion % = 75%)
Total completion: 2601 (Completion %=80%)

Total number of items which were inspected and / or otherwise repaired or remedied.

(b) **Total Number Inspected & NOT REQUIRING REMEDY:** 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5- **Items Determined to be Unreachable:**

Total Number Exported: 0
Total Number Stolen: 0
Total Number Scrapped: 0
Total Number Unable to Notify: 0
Total Number Otherwise: 0
Describe Other:: 0

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date: April 30, 2003 **Calendar Quarter:** 2
Safety Recall Quarterly Report from: November 21, 2000 **through:** April 30, 2003
Manufacturer: Prévost Car Inc.
Report author: Josyane Côté **Phone:** 1-418-831-2048
Recall Subject: Reinforcement bracket on tag axle

1- **NHTSA Safety Recall Campaign Number:** 00V-389
Transport Canada Recall Campaign Number: 01-010
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37

2- (a) **The date notification to purchaser began:** 21-11-00
(b) **The date notification of purchasers was completed:** 21-11-00

3- **The Total Number of Items¹ Involved in USA:** 2152
The total Number of Items Involved in Canada: 1108
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

4- **Total Number Inspected & Remedied in Usa:** 1822 (Completion % = 85%)
Total Number Inspected & Remedied in Canada: 876 (Completion % = 79%)
Total completion: 2698 (Completion % = 83%)

Total number of items which were inspected and / or otherwise repaired or remedied.

(b) **Total Number Inspected & NOT REQUIRING REMEDY:** 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5- **Items Determined to be Unreachable:**

Total Number Exported: 0
Total Number Stolen: 0
Total Number Scrapped: 0
Total Number Unable to Notify: 0
Total Number Otherwise: 0
Describe Other: 0

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date: July 30, 2003 Calendar Quarter: 3
Safety Recall Quarterly Report from: November 21, 2000 through: July 30, 2003
Manufacturer: Prévost Car Inc.
Report author: Josyane Côté Phone: 1-418-831-2046
Recall Subject: Reinforcement bracket on tag axle

1- NHTSA Safety Recall Campaign Number: 00V-369
Transport Canada Recall Campaign Number: 01-010
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37

2- (a) The date notification to purchaser began: 21-11-00
(b) The date notification of purchasers was completed: 21-11-00

3- The Total Number of Items¹ Involved in USA: 2182
The total Number of Items Involved in Canada: 1108
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

4- Total Number Inspected & Remedied in Usa: 1912 (Completion % = 89%)
Total Number Inspected & Remedied in Canada: 885 (Completion % = 80%)
Total completion: 2797 (Completion %= 86%)

Total number of items which were inspected and / or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 0
Total number of Items involved in the recall and Inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5- Items Determined to be Unreachable:

Total Number Exported: 0
Total Number Stolen: 0
Total Number Scrapped: 0
Total Number Unable to Notify: 0
Total Number Otherwise: 0
Describe Other:: 0

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date: October 30, 2003 Calendar Quarter: 4
Safety Recall Quarterly Report from: November 21, 2000 through: October 30, 2003
Manufacturer: Prévost Car Inc.
Report author: Jocylene Côté Phone: 1-418-831-2048
Recall Subject: Reinforcement bracket on tag axle

1- NHTSA Safety Recall Campaign Number: 00V-389
Transport Canada Recall Campaign Number: 01-010
Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SR00-37

2- (a) The date notification to purchaser began: 21-11-00
(b) The date notification of purchasers was completed: 21-11-00

3- The Total Number of Items¹ Involved in USA: 2152
The total Number of Items Involved in Canada: 1108
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer / importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 64
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

4- Total Number Inspected & Remedied in Usa: 1840 (Completion % = 90%)
Total Number Inspected & Remedied in Canada: 895 (Completion % = 81%)
Total completion: 2835 (Completion % = 87%)

Total number of items which were inspected and / or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 0
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5- Items Determined to be Unreachable:

Total Number Exported:
Total Number Stolen:
Total Number Scrapped:
Total Number Unable to Notify:
Total Number Otherwise:
Describe Other::

RECEIVED
NOV 04 10 16 A B 54
OCT 30 2003
SAFETY RECALLS

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.