

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 3 OF 6
BOOKS 34 OF 43

*	NA	IL	11001	PERF DIAG FOUND CODE B2432 PERF PINPOINT TEST REPLLS BUCKLE DUE TO BAD SWITCH RECHECKED OPER OK
*	NA	MI	11001	REMOVE SEAT TO REPLACE SEAT BELT RECEPTICLE OLD BELT HARD TO LATCH 1
*	NA	NY	11001	SEAT BELT BUCKLE CIRCUIT OPEN TECH CHECKED AND VERIFIED AIR BAG LAMP ON CHECKED ALL FUSES OK INSTALLED SCAN TOOL
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION FOUND FAULTY SEAT BELT WIRING REPLACED DRIVER SEAT BELT BUCKLE AND RETEST. OK NOW. NO OP CODE USE M
*	NA	CA	11001	TIME FOR BELT BUCKLE PERFORMED AIR BAG DIAG AN PINPIONT TEST,ACCESS FLOOR CARPET AN SEAT TO ACCESS AN TEST CIRCUITS
*	NA	OR	11001	REPAIRED PINCHED WIRE,REPAIRED HARNESS RETEST CODE STILL PRESENT,REPLACED SEAT BELT BUCKLE AN MODULE
*	NA	PA	11001	INOP TOOK OUT D S SEAT REPLACED BUCKLE ASSEMBLY
*	NA	PQ	11001	REPLACE RF SEAT BELT BUCKLE DOESN T CLIC
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	AZ	11001	FOUND DRIVER S BUCKLE SWITCH CIRCUIT OPEN TEST AND INSPECT AIR BAG TEST RETRIEVE DTC B2432 PINPOINT TEST FOUND DRIVER S BUCKLE SWITCH CIRCUIT OPEN REMOVE SEAT FOR ACCESS REMOVE REPLACE BUCKLE REINSTAL
*	NA	GA		30143 DRIVERS BELT BUCKLE INOP PERFORMED TEST ON BUCKLE, BUCKLE NOT WORKING, DISCONNECTED WIRING, R&R BUCKLE, CODE 42, PART# 2561203, BUCKLE NOW WORKING
*	NA	CA		REMOVED SEAT BELT LATCH BUCKLE FROM BORROWED EXCURSION AND TEMPORARLY INSTALLED TO THIS R O. DEFECTIVE LATCH BUCKLE IS ON MY TOOLBOX WHILE WAITING FOR ORDERED BUCKLE. REMOVED BORROWED SAFETY BUCKL

*	NA	MI	BPN 61203, CCC S26 CC 42 INSPECTED OPERATION OF DRIVER BUCKLE. REPLACED DRIVER BUCKET SEAT BUCKLE WITHOUT PRETENSIONER AND NON SIR
*	NA	CO	REMOVED AND REPLACED DRIVERS SIDEREMOVED AND REPLACED DRIVERS SIDE SEAT BELT BUCKLE.
*	NA	CA	REPLACE R FRONT SEAT BELT BUCKLE ASSY FOR WILL NOT LATCH CONCERN
*	NA	TX	R&R DRIVERS SEAT TO REPLACE SEAT BELT BUCKLE WOULD NOT LATCH
*	NA	VA	CK FOR THE RIGHT FRONT SEAT BELT WONT LOCK VERIFY R&R PASSENGER SIDE FRONT SEATBELT BUCKLE
*	NA	IL	REPL BUCKLE ASSY WPI
*	NA	CA	REPLACED RIGHT SEAT BELT BUCKLE.
*	NA	AL	TEST ALL SEAT BELTS PASSENGER SIDE FAILED R AND R SEAT TO INSTALL NEW SEAT BELT BUCKLE ASY DUE TO BEING BROKEN
*	NA	CA	E VERFIED COMPLAINT REPLACED SEAT BELT BUCKLE
*	NA	GA	INOP REPLACE DRIVERS SEAT BELT BUCKLE
*	NA	AZ	2124 VERIFIED THAT THE DRIVERS SEATBELT BUCKLE NOT LATCHING ALL OF THE TIME, FOUND IT NECESSARY TO REMOVED DRIVERS SEAT FOR ACCESS AND REPLACED BUCKLE, RETEST OK. HAD TO ORDER ONE SEAT BOLT TRIM C
*	NA	TX	BROKEN SEATBELT ASSEMBLY FRONT REPLACE
*	NA	AR	FAILED BUCKLE TEST REMOVED RT FRT SEAT TO GAIN ACCESS & REPLACED SEAT BELT PASSENGER
*	NA	CA	REMOVE SEAT LATCH,INSTALL NEW LATCH,RECHECK OK
*	NA	AZ	R AND I PASS SEAT AND REPLACE BUCKLE
*	NA	MD	REPLACED SEAT BELT BUCKLE
*	NA	PA	REPLACED FAULTY PASSENGER BUCKLE
*	NA	MA	REPLACE RS SEAT BELT BUCKLE
*	NA	FL	REPLACE RF SEAT BELT BUCKLE
*	NA	UT	1 VERIFIED COMPLAINT. REPLACED BUCKLE WITH NEW ONE. RETEST OK. WORKING PROPERLY.

*	NA	MT	REPLACED ONE SEAT BELT. 2714
*	NA	AK	1 REPLACED DRIVERS SIDE SEAT BELT AND PULLED CENTER SEAT BELT OUT OF COVER AND REPAIRED
*	NA	GA	BROKEN SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	REMOVE BOTH FRONT SEATS AND REPLACED BOTH SEAT BELT BUCKLES,RETEST OK
*	NA	TN	REPLACED RIGHT FRONT SEAT BELT BUCKLE. BINDING 41.
*	NA	AR	DOES NOT OPERATE PROPERLY ADDITIONAL MISC. REPAIRS
*	NA	SC	VERIFY CONCERN. REPLACED BUCKLE VERIFIED CONCERN AND INSPECTED THE SEAT BELT ASSEMBLY FOUND THE DRIVERS SEAT BUCKLE TO BE INOP
*	NA	TX	NOT ALLOWING THE BELT TO LATCH REPLACE THE DRIVERS SEAT BELT BUCKLE ASSEMBLY ON CAPTAINS CHAIR AND RETE
*	NA	CA	SEAT BELT DEFECTIVE REPLACE SEAT BELT BUCKLE ASSY
*	NA	FL	REMOVE DR SEAT ASSY AND REPL DR SEAT BELT RECIEVER. MT TIME FOR REPAIR.
*	NA	WA	SEAT BELT BUCKLE INOP. REPLACED WITH NEW SEAT BELT BUCKLE
*	NA	IN	61203 S40 42 SEAT BELT DOSE NOT HOLD REPLACE DRIVERS SEATBELT LATCH ASSEMBLY
*	NA	CO	REPLACE SEAT BELT ASSY
*	NA	WI	REPLACE LT SEAT BELT BUCKLE
*	NA	MD	13212 DRIVERS SEAT BELT WONT STAY BUCKLED WARR REPLACED L F SEATBELT BUCKLE
*	NA	AZ	REPLACED RT FRT SEATBELT ASSY.
*	NA	GA	REPL SEAT BELT
*	NA	TX	10661 1.0 HRS TESTED OLD SEATBELT, REPLACED WITH NEW. C P
*	NA	FL	BUCKLES DEFECTIVE NECESSARY TO REPLACE
*	NA	AZ	REMOVED SEAT R&R SEAT BLET ASY. RECHECKED OK

•	NA	CA	DRIVERS SEATBELT WILL UNLATCH AT TIMES BY ITSELF. REPLACE SEAT BELT, RETEST, OK
•	NA	CA	DIAG REPLACE SEAT BELT BROKEN
•	NA	NJ	REPLACE BUCKLES BOTH SIDES
•	NA	DE	INSTALL NEW SEAT BELT
•	NA	CA	11 2561203 DIAGNOSED AND REPLACED R FRONT SEAT BELT BUCKLE ASSEMBLY; EXTRA
•	NA	TX	BROKEN LATCH REPLACE L F SEAT BELT LATCH
•	NA	TN	REPLACED RIGHT SEATBELT BUCKLE
•	NA	NC	32510 41 STICKING SEAT BELT BUCKLE MT FOR R&R DRIVERS SEAT BELT BUCKLE CHECKED THE DRIVERS FRONT SEATBELT BUCKLE WOULD NOT STAY LATCHED. REPLACED THE BUCKLE. TESTED NEW BUCKLE WORKS FINE. SEAT WAS A CAPTAINS CHAIR.
•	NA	NM	2526 SOMEONE ORDERED LF SEAT BELT BUCKLE 7173 INSTALLED NEW BUCKLE SEAT BELT IS WORKING PROPERLY AT THIS TIME NOTE HAD TO REMOVE CHILD SEAT BEHIND DRIVER SEAT TO GET UNDER SEAT DID NOT REINSTALL CH
•	NA	NC	SEATBELT BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE
•	NA	NJ	REPLACED SEAT BELT ASSY
•	NA	AZ	TEST AND FOUND PASS SEAT BELT BUCKLE INOP. DISENGAGES, WON T LATCH PROPERLY. REMOVE AND REPLACE PASS SEAT BELT BUCKLE OK. RETEST OK.
•	NA	IL	REPLACE BOTH FRONT SEATBELT LATCHES FOR CUSTOMER SAFETY CONCERN
•	NA	NE	REPLACED FRONT PASSENGER SEAT SEATBELT, WOULD POP OUT BY ITSELF

*	NA	NC	REPLACED SEAT BELT
*	NA	NY	REPLACE BUCKLE
*	NA	CA	REPLACED BUCKLE
*	NA	IL	CHECK DRIVERS SEAT BELT DIAGNOIS AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE COMES LOOSE
*	NA	MD	REPLACAE BOTH FRONT SEAT BELTS WONT STAY BUCKLED
*	NA	NC	VERIFIED CONCERN AND REPLACED DRIVER SIDE SEAT BELT.
*	NA	GA	SEAT BELT POPS LOOSE REPLACED
*	NA	LA	DOENST OPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	MD	30124 REPLACED LEFT BUCKLE ASSY.
*	NA	CA	DIAG AND REPLACED DRIVERS SEAT BELT BUCKLE.
*	NA	CA	WONT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE SEAT BELT BUCKLE COMES UNBUBKLED INTERMITTENTLY
*	NA	TX	VERIFY CUSTOMER CONCERN REPLACE BUCKLE NECESSARY TO REMOVE PASS. SEAT RETEST OK
*	NA	LA	BROKEN SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	FL	30658 07 SEAT BELT LATCH WTY CHECKED OPERATION, REPLACED SEAT BELT LATCH.
*	NA	CO	13058 INSTALLED NEW SEATBELT BUCKLE ASSEMBLY..R ADN R OLD BUCKLE AND INSTALLED NEW ONE INSPECTED AND FOUND LOOSE DRIVERS SIDE SEAT BELT
*	NA	WY	BUCKLE. REPLACED BUCKLE. M TIME USED AS NO OPS AVAILABLE FOR BUCKLE. OK PER PA.
*	NA	MO	REPLACED SEAT BELT AND BUCKLE

*	NA	GA	SEAT BELT TONGUE WILL NOT HOLD REPLACE SEAT BELT TONGUE ON DRIVERS SEAT
*	NA	CA	REPLACED DRIVERS SIDE SEAT BELT BUCKLE
*	NA	CA	737 INSPECTED SEAT BELT BUCKLES IN FRONT SEAT WITH BUCKLE TESTER FOUND THE PASSENGER BUCKLE TO BE BAD RECCOMEND REPLACING AND NOT HAVING ANYONE USE THAT SEAT UNTIL REPAIRED GOT P A
*	NA	CA	E VERFIED COMPALINT REPLACD DRIVERS SEIDE SEAT BELT BUCKLE
*	NA	FL	NOT LOCKING PROPERLY REPLACE DR SIDE SEAT BELT BUCKLE
*	NA	TX	LATCH BROKEN VERIFY CUSTOMER CONCERN AND REPLACE PASS. SIDE BUCKLE.
*	NA	CA	DRV SEAT BELT BUCKLE POPS OFF REPL DR INOP SEAT BELT BUCKLE
*	NA	TX	10858 2581203 CC 42 VERIFY CONCERN.REPLACED DRIVERS SEAT BELT BUCKLE.VERIFY REPAIR TECH 4441
*	NA	TX	DR SEAT BELT BUCKLE BAD REPLACED THE DR SEAT BELT BUCKLE ASSY
*	NA	TX	REPLACED BOTH FRONT BUCKLES.
*	NA	FL	FOUND SEATBELT WILL NOT ALWAYS LATCH CORRECTLY. REPLACE LEFT FRONT SEATBELT
*	NA	CA	DIAG INSP M TIME TO REPLACE SEAT BELT BUCKLES
*	NA	CA	DIAG INSP M TIME TO REPLACE SEAT BELT BUCKLE
*	NA	TX	RECALL RECALL
*	NA	MI	FOUND BOTH BUCKLES BAD. REPLACED SEAT BELT BUCKLES IN FRONT PER RECALL
*	NA	IN	REPLACE BROKEN BUCKLES
*	NA	MN	WPI R&R SEAT BELT OK NOW
*	NA	MD	WOULD NOT RETRACT SEATBELT ASSEMBLY FRONT REPLACE
*	NA	OR	CHECK OUT FOUND RECIPTICLE BAD REPLACE SEAT BELT RECIPTICLE (NOT LATCHING)

NOV-011 13:05

*	NA	TN	REPLACED BELT & BUCKLE
*	NA	CA	1 REPLACED LEFT FRONT SEAT BELT BUCKLE
*	NA	CO	MT TIME TO REPLACE LEFT FRONT SEAT BELT BUCKLE
*	NA	MO	REPLACED SEAT BELT BUCKLE
*	NA	NC	WIRES PULLED OUT DIAGNOSE CONDITION. REPLACED LEFT FRONT SEAT BELT BUCKLE
*	NA	NY	VERIFIED CONCERN, DEFECTIVE PART REPLACE SEAT BELT BUCKLE
*	NA	OK	INSTALLED SOP SEAT BELT BUCKLE. ...QC BY TH
*	NA	CO	TIGHTENED ALL BELT BOLTS 1
*	NA	TX	9476 OUT OF ALIGNMENT WARR REALIGN SLEEVE FOR 2ND ROW, MIDDLE SEAT BELT.
*	NA	OH	COMING UNLATCHED WHILE DRIVING REPLACED DRIVERS SIDE BELT LATCH
*	NA	MI	23766 61172A .4 61202BP 42CC **** REPLACE RIGHT FRONT SAFETY BELTS **
*	NA	CA	
*	NA	MD	10223 RIGHT FRONT SEAT BELT BUCKLE DIFFERENT THAN LEFT ONE. REPLACED RIGHT FRONT SEAT BELT BUCKLE.
*	NA	WI	REPLACED DRIVERSIDE SEAT BELT BUCKLE
*	NA	TX	
*	NA	FL	BUCKLE INOP REPLACE SEAT BELT BUCKLE
*	NA	CA	REPL DR SEAT BELT BUCKLE COMING APART
*	NA	NV	FAULTY SEAT BELT BUCKLE REPLACED SEAT BELT BUCKLE,RETESTED OK
*	NA	AZ	20 RECALL 01S21 INSPECTED BOTH FRONT SEAT BELT BUCKLES. BOTH FAILED. REMOVED AND INSTALLED BOTH FRONT SEAT BELT BUCKLES. POWER BUCKETS, NO SIR
*	NA	CO	1 REPLACED DR SEAT BELT LATCH.
*	NA	CT	LOCK SIEZED R&R SEAT BELT LOCK RETEST OK

*	NA	ND	DIAGNOSE FOUND THAT THE SWITCH IN BUCKLE IS NOT WORKING. DOESNT OPEN CIRCUIT WHEN BELT IS INSERTED. REPLCAED BUCKLE. NO LABOR OP USED M TIME.
*	NA	SC	REPLACE FRONT SEATBELT ASSYS
*	NA	NY	VERIFIED CONCERN, FOUND RIGHT FRONT SEAT BELT BINDING R&R BUCKLE ASSEMBLY NOW OPS NORMALLY
*	NA	WI	7100 REPLACED L SEAT BELT BUCKLE
*	NA	MT	INSPECTED AND FOUND SEATBELTS BAD,REPLACED PER RECALL
*	NA	TX	DRIVERS SIDE SEAT BELT INSTALLED
*	NA	WI	REPLACED DRIVERSIDE SEAT BELT BUCKLE
*	NA	NC	BUCKLE INSTALL BOTH SEATBELT BUCKLE
*	NA	IL	3 SEATBELT WAS CHECKED AND FAILED THEN WAS REPLACED AND RETESTED AND PASSED THE MILEAGE SHOULD BE 13
*	NA	CA	RIGHT FRONT SEAT BUCKLE INOP REPLACE BELT BUCKLE ASSEMBLY, BINDING INOP
*	NA	VA	8533 REPLACE L F SAETBELT
*	NA	IL	S28 7861202 42 REPLACED PASS FRONT SEATBELT
*	NA	NY	5 RECALL 01S21 REPLACED L AND R SEAT BELT BUCKLES PER RECALL. POWER BUCKET SEATS.
*	NA	VA	11043 INSTALL NEW BKLE FOR DRIVER SEATBELT
*	NA	VA	11713 DEF BUCKLE W UNABLE TO VERIFY REPLACED SUSPECT DRIVERS SEAT BELT BUCKLE ASSY RETEST OK
*	NA	TX	RENTAL RENTAL
*	NA	TX	RENTAL RENTAL
*	NA	MO	NEC TO REPLACE SEAT BELT
*	NA	IL	REPLACE LEFT FRONT SEAT BELT
*	NA	CO	
*	NA	MN	12865 REMOVE DRIVER SEAT AND REPLACE BELT.

*	NA	FL	REMOVE 2ND ROW MIDDLE SEAT BELT TONGUE OUT OF HOLDER
*	NA	IL	RR B PILLAR TRIM, RR SEAT BELT INSTALL SLIDDER TRIM. ALSO REPL BELT BUCKLE INOP
*	NA	NC	REPLACED SEAT BELT PER ED KARAZIN
*	NA	NY	81203 41 REPLACE FRONT SEATBELT BUCKLES
*	NA	NJ	INSPECT BELTS, BELT RETRACTED INTO SEAT BELT COVER, R R SEAT BELT ASSEMBLY, DRILL OUT RIVETS THAT HOLD COVER TO BELT
*	NA	CA	01S21 01S21
*	NA	MA	1 REPLACE SEAT BELT
*	NA	NY	OPENS REPLACER SEAT BELT
*	NA	CA	04 2581203 REPLACE LEFT FRONT SEAT BELT BUCKLE
*	NA	NC	REPLACE SEATBELT ASSEMBLY FRONT REPLACE
*	NA	IL	LEFT MIDDLE SEAT LEVER OFF REINSTALLED LEVER
*	NA	CA	REPLACE SEAT BELT ASSY
*	NA	CA	RECALL INSTALLED SPECIAL ORDERED PART FOR SEATBELT BUCKLE RECALL A99
*	NA	CA	PERFORM RECALL INSPECT SEATBELT BUCKLES REPLACE LEFT FRONT BUCKLE.
*	NA	GA	MOULDING MOULDING REAR DOOR REPLACE
*	NA	GA	A RMVD DRIVERS WIPER ARM DRIVERS SIDE COWL PANEL
*	NA	CA	CK SEAT BELT AND REPLACE INOP
*	NA	FL	X SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	6737 42 WARR VERIFIED SEAT BELT NOT BUCKLING PROPERLY REPLACED BUCKLE AND RECHECK ALL OK AT THIS TIME
*	NA	TX	
*	NA	CA	1111111111

*	NA	CA	REPLACE DEFECTIVE SEAT BELT
*	NA	CA	REPLACED CONSOLE LID.
*	NA	TX	
*	NA	FL	26 W 302 VERIFIED CONCERN.PERFORM RECALL 01S21 REPLACE PASS FRONT RECIEVER PRETENSIONER. OK AT THIS TIME.QUALITY INSPECTED BY 302,26.
*	NA	FL	CVERYFY CUST COMPLAIN SEAT BELT INOP REPLACED BUKLE
*	NA	FL	REPLACE BOTH SEAT BELT ASSEMBLIES
*	NA	TX	1 REINSTALLED SEAT BELT INSERT PROPERLY.
*	NA	TX	REPLACED SEAT BELT BUCKLE
*	NA	MD	REPLACE SEAT BELT BUCKLE ASSEMBLY
*	NA	FL	SEAT BELT CENTER SEAT BELT BUCKLE WENT INSIDE RETRACTOR,REMOVE SEAT AND SEAT BELT ASSY,REMOVE BELT AND REINSTALL BELT ASSY AND SEAT AND VERIFY REPAIR
*	NA	MS	DRIVERS DOOR MAKES A NOISE CORRECTION OF SQUEAKS & RATTLES, OR PERFORM MINOR INTERNAL D
*	NA	FL	BROKEN WIRE AT BUCKLE TRACK ASSEMBLY FRONT SEAT NNESS TO R&I
*	NA	TX	VERIFY. ELECT DIAG. PINPOINT FOUND DRIVERSIDE PRETENSIONER HIGH RESISTANCE. REPLACE PRETENSIONER. RETEST ALL OK
*	NA	TX	REPLACED BUCKLE
*	NA	AZ	MT81202 .6HR TEST BELTS,REPLACE R FRONT SEAT BELT BUCKLE
*	NA	TN	REAR BELT STUCK BEHIND REAR SEAT BOTTOM, RR SEAT AND REMOVE BELT. 1
*	NA	TX	REPLACED FRONT RIGHT SEAT BELT ASSY
*	NA	TX	REPLACED LEFT FRONT SEAT BELT BUCKLE

*	NA	MD	PERFORM RECALL SEAT BELT BUCKLE UNBOLT CENTER SEAT REMOVE HARDWEAR UNBOLT PASSENGER SIDE SEAT AND BRACKET PULL OUT TRUCK UNBOLT SEAT BELT BUCKLE INSTALL NEW SEAT BELT BUCKLE PLACE SEATS BACK IN TRUCK TES
*	NA	NJ	REPLACED DRIVERS SEAT BELT BUCKLE
*	NA	FL	REPLACED DRIVER SEAT BELT BUCKLE
*	NA	AZ	TEST AND REPLACE ERRATIC RF SEAT BELT BUCKLE ASSY NORMAL OPERATION RESTORED
*	NA	MA	REPLACE ONE BELT
*	NA	FL	REPLACE DRIVERS SEAT BUCKLE
*	NA	CA	FOUND RIGHT FRONT SEAT BELT BUCKLE TO BE FAULTY REPLACED SEAT BELT BUCKLE RECHECK O.K NOW
*	NA	TX	REPLACED THE RF BUCKLE ASSY
*	NA	CA	REPLACED PASS. BELT BUCKLE. DE
*	NA	OR	1 REPLACED DRIVER SIDE BUCKLE.
*	NA	OK	CHECK OUT AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE.
*	NA	IL	4878 HAD TO REORDER PART
*	NA	CA	REPLACE SEAT BELT WILL NOT LATCH PROPERLY
*	NA	CA	PERFORMED CHECK OF CUSTOMERS CONCERN OF VEHICLE FRONT PASSENGER SEAT BELT INOP VERIFIED CONCERN AND PIN POINT TESTED CAUSE TO FAILED SEAT BELT. REMOVED AND REPLACED FAILED SEAT BELT BUCKLE. R
*	NA	SC	CHECKED AND TESTED AND FOUND SEAT BELT SWITCH BAD SHORTED REPLACED BELT ASSY AND RECHECKED AND RETESTED GOOD
*	NA	IN	BINDING SEAT BELT BUCKLE REPLACED RIGHT FRONT SEAT BELT BUCKLE
*	NA	TX	01S21 RECALL COMPLETE R AND L DRIVERS SEAT TO ACCESS DEFECTIVE SEAT BELT BUCKLE R AND R BUCKLE AND RETESTED AND CHECKED OK
*	NA	MA	VERIFIED CONCERN AND REPLACED BUCKLE
*	NA	MD	REPLACE DRIVERS SIDE BUCKLE ASSEMBLY RETEST OK

*	NA	LA	REPLACE BUCKLE
*	NA	NE	
*	NA	CA	RT FRT SEAT BELT LATCH INOP, REPLACE BELT BUCKLE ASSY DUE TO STICKING, 7881202 40 20 40 MANUAL SEAT SHORT IN BUCKLE ASSY. REPLACE BUCKLE ND HARNESS ASSEMBLY AND RETEST
*	NA	TX	
*	NA	CA	AIR DUCT, IMPROPERLY ADJUSTED. INSTRUMENT PANEL ACCESS
*	NA	TX	VERIFIED CONCERN REMOVED SEAT BELT OUT OF PLASTIC HOLDER GOODWILL REPAIR
*	NA	CA	RIGHT SEAT BELT WILL NOT BUCKLE REPLACED RIGHT SEAT BELT BUCKLE & RECHECKED, ALL OK
*	NA	DE	S24 42 REPLACE R F SEATBELT
*	NA	TX	SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	REPLACE BUCKLE
*	NA	CA	6508 01S21C 0.7 9267 REPLACED RT. FRONT SEATBELT BUCKLE PER RECALL
*	NA	AL	VERIFY CONCERN AND FOUND DRIVER SIDE SEAT BELT NOT HOLDING RECALL WAS PREVIOUSLY CHECKED BUT PASSED R AND R DRIVER SEAT BELT AND RECHECK OK
*	NA	MD	31001 REPLACED LEFT BUCKLE HAD TO R&R SEAT

TECH_TXT2

Symp Code	Symp Desc	CUST_TXT	AREA_CD
A	Won't Latch	RT FRT SEAT BUCKLE INOP	*
A	Won't Latch	CUSTOMER STATES PASS FRONT SEAT BELT INTERMIT WONT BUCKLE	216
A	Won't Latch	PASSENGER SEAT BELT BUCKLE WONT LATCH, BUCKLE IN PARTS	321
A	Won't Latch	CUST STATES PASS FRT SEAT BELT WILL NOT LATCH PROP.	813
A	Won't Latch	INSTALL SOP SEAT BELT REFER TO LAST RO#113241	209
A	Won't Latch	CHECK PASS SEAT BELT WONT LATCH	843
A	Won't Latch	PASSENGER SEAT FRONT BUCKLE WILL NOT LATCH S40	281
A	Won't Latch	S40 RIGHT FRONT SEAT BELT WONT BUCKLE AT ALL INOP	817
A	Won't Latch	CUST STATES THE RT FRONT SEAT BELT BUCKLE IS NOT LATCHING SOP PART IS HERE	714
A	Won't Latch	PASS SEAT BELT WONT LOCK	843
A	Won't Latch	SOP IN FROM RO77517 INSTALL TECH # 849 03 22 2002 PASSENGER SIDE FRONT SEAT BELT DIFFICULT TO LATCH	540
A	Won't Latch	CUSTOMER REQUESTS:REPLACE S O SEATBELT, RIGHT FRONT BUCKLE DOES NOT LATCH	607
A	Won't Latch	CUST STATES PASS SEAT BELT FRT WONT FASTEN	281
A	Won't Latch	CHECK LEFT FRONT SEAT BELT WONT CLICK INTO THE BUCKLE (S40)	306
A	Won't Latch	CUSTOMER STATES FRONT PASS SEAT BELT WONT LATCH	201
A	Won't Latch	CUSTOMER STATES LEFT FRONT SEATBELT WONT LATCH INTO BUCKLE	904
A	Won't Latch	CUSTOMER STATES THE DRIVER SIDE FRONT SEAT BELT LATCH INOP S S26	313
A	Won't Latch	CUST STATES DRIVERS SEAT BELT WILL NOT BUCKLE	818

A	Won't Latch	S40 CUSTOMER STATES DRIVERS SEAT BELT FEMALE END WONT LATCH	581
A	Won't Latch	CSUTOMER STATES LEFT FRONT SEAT BELT WILL NOT LATCH	904
A	Won't Latch	DRIVER SIDE SEAT BELT WILL NOT LATCH S26	972
A	Won't Latch	CUST STATES THE DRIVERS SIDE FRONT SEAT BELT WONT GO IN THE RECEPTICAL	352
A	Won't Latch	CUST STS DRVR SIDE SEAT BELT WONT LATCH.	954
A	Won't Latch	CUSTV STATES DRIVER SEAT BELT WILL NOT LATCH	817
A	Won't Latch	DRIVERS SEATBELT WILL NOT LATCH AT TIMES	803
A	Won't Latch	DRIVER SIDE SEAT BELT WONT LATCH	908
A	Won't Latch	S40 DRIVER SIDE FRONT SEAT BELT DOES NOT BUCKLE	214
A	Won't Latch	DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	818
A	Won't Latch	SEATBELT WOULDNOT LATCH INTERMITTENT PROBLEM DRIVERS SEAT	602
A	Won't Latch	CUST. ST. FRONT SEAT BELTS WILL NOT LATCH, ESP. THE DRIVERS SEAT.	780
A	Won't Latch	LEFT FRONT SEAT BELT WONT LATCH	815
A	Won't Latch	CHECK DR SEATBELT WONT LATCH	815
A	Won't Latch	RITE FRONT SEAT BELT WONT BUCKLE PLEASE CK ALL.....	505
A	Won't Latch	S26 DRIVERS SEAT BELT WILL NOT LATCH.	314
B	Won't Stay Latched	PASS FRONT SEAT BELT DOES NOT ALWAYS STAY LOCKED	702
B	Won't Stay Latched	CUSTOMER STATES PASSENGER SEAT BELT DOES NOT HOLD	512
B	Won't Stay Latched	PASSENGER SEAT BELT WONT T STAY BUCKLED	863

B	Won't Stay Latched	CUST STATES PASSENGER SEAT BELT DOES NOT STAY LATCHED WHEN IN USE	941
B	Won't Stay Latched	S40 REPAIR RT FT SEAT BELT WONT STAY FASTENED INSTALL SOP	210
B	Won't Stay Latched	DRIVER SEAT BELT DOES NOT STAY LOCKED	516
B	Won't Stay Latched	SEAT BELT BUCKLE WILL NOT HOLD	512
B	Won't Stay Latched	LEFT FRONT SEAT BELT WILL NOT STAY LATCHED SEE CHARLIE	818
B	Won't Stay Latched	CONCERN CODE S26...SEAT BELT BUCKLE, DRIVERS SIDE SEAT BELT BUCKLE WILL NOT STAY LATCHED	252
B	Won't Stay Latched	CUST STATES D S SEAT BELT WILL NOT STAY LATCHED INSPECT	972
B	Won't Stay Latched	C S DRIVERS SEAT BELT WONT STAY BUCKLED, INSTALL SOP TO REPAIR.	209
B	Won't Stay Latched	DR SEAT BELT WILL NOT STAY LATCHED	713
B	Won't Stay Latched	CUST STATES DRIVERS SEAT BELT SOMETIMES WONT STAY LATCHED	480
B	Won't Stay Latched	CHECK LEFT FRONT SESATBELT WILL NOT STAY LATCHED	770
B	Won't Stay Latched	CUSTOMER STATES THAT THE DRIVERS SIDE SEAT BELT WONT STAY LATCHED	252
C	Unlatches/Releases	O R L F SEATBELT BUCKLE RELEASES SEATBELT	407
C	Unlatches/Releases	S26 RT FT PASS SEAT BELT INTERMITTENTLY WILL RELEASE, A SOP REPLACEMENT IS IN.	727
C	Unlatches/Releases	RIGHT FRONT SEAT BELT WONT STAY LATCH	909

C	Unlatches/Releases	S26 CUSTOMER STATES THAT PASS. FRONT SEAT BELT COMES UNDONE	713
C	Unlatches/Releases	CLIENT STATES FRONT PASSANGER SEAT BELT UNBUCKLES ON ITS OWN INTERMITTENTLY. ADVISE	*
C	Unlatches/Releases	PASS SEAT BELT UNLATCHES ON ITS OWN	602
C	Unlatches/Releases	C S PASSINGER FRONT SEAT BELT COMES UNLATCHED	512
C	Unlatches/Releases	CUST STATES THE SEATBELT ON THE PASS SIDE IS RELEASING	909
C	Unlatches/Releases	C S THAT THE L F SEAT BELT KEEPS POPPING OUT BY ITSELF S40	813
C	Unlatches/Releases	DRIVERS SEAT BELT KEEPS POPPING LOOSE	334
C	Unlatches/Releases	SEATBELT COMES UNLATCH DR FRT ...SOP	602
C	Unlatches/Releases	DRIVERS SEAT BELT WONT HOLD COMES UN DONE	661
C	Unlatches/Releases	DRIVER SEAT BELT COMES DISCONNECTED	928
C	Unlatches/Releases	CUST STATES DRIVERS SEAT BELT RELEASES BY ITSELF INTERMITTANTLY	631
C	Unlatches/Releases	(S40) INSTALL B O LF SEATBELT (BUCKLE UNLATCHES INTERM)	808
C	Unlatches/Releases	CUST STATES DRIVERS SIDE SEATBELT UNLATCHES.INTERMITTEN.	602
C	Unlatches/Releases	SEAT BELT POPS LOOSE, SOP IN	501
C	Unlatches/Releases	CUST STS DRIVERS SIDE SEAT BELT COMES UNDONE BY ITSELF	602
C	Unlatches/Releases	C STATES DR SIDE SEAT BELT COMES UNDONE WONT STAY BUCKLED	770

C	Unlatches/Releases	CUSTOMER STATES THAT PASSENGER SIDE SEATBELT WILL COME UNLATCHED FOR NO REASON	512
D	Unlatches While Driving	DRIVERS SEAT BELT COMES UNBUCKLED WHILE CUSTOMER IS DRIVING	626
D	Unlatches While Driving	DRIVERS SEATBELT COMES UMLATCHED WHILE DRIVING	254
D	Unlatches While Driving	DRIVER SEAT BELT COMES UNBUCKLED WHEN DRIVING	757
D	Unlatches While Driving	CUST STATES DRIVERS SIDE FRONT SEAT BELT WILL COME UNLATCHED WHEN DRIVING	210
D	Unlatches While Driving	CUSTOMER STATES WHILE DRIVING THE LFT FRONT SEAT BELT WILL POP OUT OF SEAT BELT BUCKLE AT TIMES	909
D	Unlatches While Driving	CUSTOMER STATES THAT DRIVER SEAT BELT BUCKLE WILL UNLATCH WHILE DRIVING.	714
D	Unlatches While Driving	OWNER REPORTS LEFT FRONT SEAT BELT INTER. COMES UNBUCKLED WHILE DRIVING	830
D	Unlatches While Driving	S40 CUSTOMER STATES:DRIVERS SEATBELT RELEASES WHILE DRIVING DOWN THE ROAD	281
D	Unlatches While Driving	CHECK THE FRONT SEAT BELTS LATCHES WILL POP OPEN AND RELEASE WHILE DRIVING INTERMITTENTLY	407
D	Unlatches While Driving	BOTH FRONT SEAT BELTS COME UNDONE WHILE DRIVING. INSTALL SOP 99	941
X	Other	CUSTOMER STATES THAT FRONT PASSENGER SEAT BELT INOPERABLE	.
X	Other	CUSTOMER STATES PASSENGER FRONT SEAT BELT BUCKLE IS RATTLEING	310
X	Other	PASSENGER FRONT SEAT BELT HANGS WHEN TRY TO PULL OUT	806
X	Other	CK PASS FRONT SEAT BELT HARD TO GET IT TO LOCK	843
X	Other	C S PASSENGER SEAT BELT COVER LOOSE SOP PART	713

X	Other	FRONT PASS SIDE SEAT BELT IS INOP SPO IS HERE	770
X	Other	LT FR FEMALE SEATBELT RECEPTICLE RATTLES INSIDE	954
X	Other	CUST STATES PASS SEAT BELT INOP INSTALL SOP 67885 72 3 30 02 225	780
X	Other	CUSTOMER STATES PASSENGER SIDE SEAT BELT INOP	229
X	Other	SEATBELT RATTLING	501
X	Other	SOP PASS SIDE SEAT BELT	440
X	Other	PASSENGER SIDE FEMALE PART OF SEAT BELT MISSING	916
X	Other		*
X	Other		*
X	Other	L H SEAT BELT INOP	*
X	Other		*
X	Other	S25 CUSTOMER STATES LF SEATBELT RETRACTOR IS INOP INSTALL SOP	561
X	Other	NEED TO ORDER ARM FOR DRIVER SIDE SEAT BELT	619
X	Other		805
X	Other	RATTLE IN LEFT SEAT BELT SOP IN STK	770
X	Other		310
X	Other	SEAT BELT ON FASTENING	770
X	Other	SOP AIR BAG LAMP ON	502
X	Other	S21 CUST CONCERN DRIVER SIDE SEAT BELT NOT WORKING	954
X	Other	FRONT SEAT BELTS WILL NOT GRAB SOMETIMES CHECK AND ADVISE	562
X	Other	CK SEAT BELT STAYS ON AND CHIME GOES OFF EVEN WITH SEAT BELT ON	614

SIDE SEAT BELT BUCKLE
SHORTED TO GROUND. R&I
DRIVERS BUCKET SEAT FOR
ACCESS. REPLACED DRIVER S
SIDE SEAT BELT BUCKLE.
RETESTE AND VERIFID REPAIR.

X

Other

SEAT BELT LIGHT COMES ON WITH BELT LATCHED
SOP IN.

972

X

Other

O R SEAT BELT COMING APART SOP HERE

407

X

Other

SEATBELT DOES NOT WORK

262

X

Other

DOES NOT OPERATE PROPERLY DRIVERS SIDE SEAT
BELT INOP

256

X

Other

DRIVERS SEAT BELT IS INOPERATIVE

229

X

Other

CUST STATES DRIVERS SIDE SEATBELT INOP

251

X

Other

REMOVE SEATBELT FOR RO 80004. WRONG PART
ORDERED. EMERGENCY ORDER L F SEATBELT
BUCKLE.

310

X

Other

SEAT BELT LIGHT AND CHIME COMES ON WHILE
DRIVING, DRIVERS SEAT BELT IS BUCKLED WHEN
THIS HAPPENS

901

X

Other

CORRECT FOR LEFT FRONT SEAT BELT BUCKLE INOP

817

X

Other

CUST STATES SEATR BELT INOP SOP BELT

530

X

Other

SEAT BUCKLE DR SIDE CUST
RETURNED FOR BUCKLE
REPLACEMENT R R DR SEAT
ASSY R R SEAT BELT BUCKLE
ASST REPLACED RETESTED OK
AT THIS TIME CAUSAL # 7861203

X

Other

THE SEAT BELT LIGHT COMES ON WHILE DRIVING
EVEN THOUGH THE SEAT BELT IS BUCKLED

724

X	Other	CHECK FOR REASON THE VEHICLE DID NOT HAVE A DRIVERS SEAT BELT BUCKLE FROM THE FACTORY	703
X	Other	LRFT NFRONT SEAT BELT BUCKLE INOP	972
X	Other	DRIVERS SIDE SEAT BELT RECT. BROKEN	850
X	Other	CUSTOMER STATES SEAT BELT SYMBOL WILL STAY ON WHEN SEAT BELT IS ATACHED	707
X	Other	CUSTOMER STATES RIGHT REAR SEATBELT INOP	850
X	Other	CUST STATES THAT FRONT PASSANGER SIDE SEAT BELT BUCKLE IS INOP PART IS HERE SEE RAIDEL USE SPO 02028013	562
X	Other	CUSTOMER STATES PASSENGER SEAT BELT INOPERATIVE	386
X	Other	INSTAL SOP SEAT BELT	909
X	Other	UST STATES RT FRT AND LEFT FRT SEATBELT SOP IS IN	954
X	Other	FRONT SEATBELTS STICK WHEN LATCHING	628
X	Other	SEAT BELT LATCHES MISSING	918
X	Other	FACTORY WARRANTY FRONT SEATBELTS WONT HOLD SEATBELTS	602
X	Other	SOP SEATBELT ENDS	847
A	Won't Latch	REPORT ON PASS SIDE FRONT SEAT BELT NOT LOCKING	905
A	Won't Latch	CUSTOMER STATES FRT PASS. SEAT BELT LATCH WOULD NOT LET YOU LATCH IT IN.	505
A	Won't Latch	CK SEAT BELT WILL NOT BUKLE	770
A	Won't Latch	PASSENGER SIDE SEAT BELT DOESNT HOLD PER OASIS NO OPEN CAMPAIGN BUT FAILED TEST	714
A	Won't Latch	INSTALL SPECIAL ORDERED PART,RIGHT FRONT SEAT BELT BUCKLE PART WAS SPECIAL ORDERED.NOT LATCHING	562

A	Won't Latch	RIGHT SEAT BELT BUCKLE WONT LATCH	760
A	Won't Latch	RIGHT SEAT BELT BUCKLE WONT LATCH	760
A	Won't Latch	CUST STATES DRIVERS SEATBELT BUCKLE WONT LATCH AT TIMES	337
A	Won't Latch	DRIVERS SEAT BELT WONT BUCKLE PART IS HERE	734
A	Won't Latch	SEAT BELT WILL NOT LATCH	214
A	Won't Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.	817
A	Won't Latch	DRIVER SIDE SEAT BELT WILL NOT LATCH	817
A	Won't Latch	S40 CUSTOMER STATES THAT DRIVER SEAT BELT WONT LATCH	972
A	Won't Latch	S26 CUST STS LEFT FRONT SEATBELT WILL NOT LATCH SOP ROW#329734 MI 18880 1 14 02	407
A	Won't Latch	CUST STATES DRIVERS SEAT BELT WILL NOT LOCK	818
A	Won't Latch	QUALITY CHECK INITIALS SEAT BELT ON DRIVERS SIDE DOES NOT BUCKLE S40	210
A	Won't Latch		818
A	Won't Latch	S40 SEATBELT CUST STATES THEDRIVERS SEATBELT WILL NOT HOLD LATCH	972
A	Won't Latch	CUSTOMER STATES SEATBELT BUCKLE WILL NOT HOLD	757
A	Won't Latch	C.S LEFT FRONT SEAT BELT INOP. CH ADVISE	407
A	Won't Latch	CUSTOMER STATES THAT RT FT SEATBELT WILL NOT LOCK IN BUCKLE	770

ROSA-811 130728

A	Won't Latch	CHECK LEFT FRONT SEAT BELT WONT LATCH TO BUCKLE	628
A	Won't Latch	DRIVER'S SEAT BELT BUCKLE WILL NOT HOLD T FH	910
A	Won't Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.	817
A	Won't Latch	S40 PER CUSTOMER THE DRIVERS SEAT BELT BUCKLE WON T RECIEVE THE MALE END INSTALL SOP PARTS TECH #805	512
A	Won't Latch	DRIVERS SEATBELT IS INOP	602
A	Won't Latch	CUSTOMER STATES PASSENGER SIDE FRONT SEAT BELT WILL NOT LATCH CHECK AND ADVISE	805
A	Won't Latch	DRIVERS SEATBELT WILL NOT LATCH	864
A	Won't Latch	PASS SIDE SEAT BELT BUCKLE WONT LATCH	949
A	Won't Latch	RT FT SEATBELT WILL NOT LATCH	281
A	Won't Latch	SEAT BELT BUCKLES DONT LATCH	727
A	Won't Latch	RF SHOULDER HARNESS WILL NOT BUCKLE	915
A	Won't Latch	CK DRIVER SEATBELT WILL NOT HOLD	601
A	Won't Latch	LEFT FRONT SEAT BUCKLE WONT LATCH	931
A	Won't Latch	PASSENGERS FRONT SEAT BELT BUCKLE WILL NOT RECIEVE BELT.	360
A	Won't Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.	817
A	Won't Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.	817
A	Won't Latch	S40 SEATBELT WOULD NOT LATCH	618

A	Won't Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.	817
A	Won't Latch	SEAT BELT DOES NOT LATCH LEFT FRONT	228
A	Won't Latch	DRIVERS SIDE SEATBELT NOT LOCKING IN	702
A	Won't Latch	LF & MIDDLE REAR SEAT BELTS WONT LATCH	*
A	Won't Latch	*SEAT BELTS BUCKLE WONT LATCH FRONT DRIVERS SIDE S40 OTHER RESTRAINT CONCERNS L:	757
A	Won't Latch	DRIVERS SEAT BELT WILL NOT LOCK.	706
A	Won't Latch	(S40) CK PASS FRONT SEATBELT WILL NOT LATCH	601
A	Won't Latch	DRIVERS SEAT BELT BUCKLE WILL NOT LATCH.	858
B	Won't Stay Latched	DRIVERS FRONT SEAT BELT WILL NOT STAY LATCHED	850
B	Won't Stay Latched	S25 SEATBELT WONT STAY LOCKED	405
B	Won't Stay Latched	LEFT SEAT BELT WILL NOT STAY LATCHED	386
C	Unlatches/Releases	LEFT SIDE SEAT BELT KEEPS RELEASING	418
C	Unlatches/Releases	DRIVERS SEATBELT BUCKLE COMES UNDONE PART IN STOCK SEE TED PASS. FRONT IS FAILING ALSO	941
D	Unlatches While Driving	CK FRONT SEAT BELT BUCKLES RELEASE WHILE DRIVING.	281
C	Unlatches/Releases	SEATBELT WILL NOT LATCH AND STAY HOOKED ALL THE WAY IT POPS BACK OUT.	708
C	Unlatches/Releases	CUSTOMER STATES DRIVERS SEAT BELT UNLATCHES AT TIMES.	714
C	Unlatches/Releases	PASSENGER SEAT BELT DOES NOT HOLD	419
X	Other	CUSTOMER STATES PASSENGER FRONT SEATBELT WONT WORK	405

C	Unlatches/Releases	CUST STATES SEAT BELT BUCKLES COMED UNDONE	805
D	Unlatches While Driving	CUST STATES WHILE DRIVING DRIVERS SEAT BELT CAME UNLATCHED BY ITSELF	225
D	Unlatches While Driving	LF SEATBELT BUCKLE POPS OUT DRIVING	702
R	Recall Performed		805
R	Recall Performed	CUST REQS RECALL 01S21 PASS BELT	805
R	Recall Performed	PERFORM RECALL #01S21	562
R	Recall Performed	PERFORM RECALL #01S21	562
R	Recall Performed	PERFORM RECALL #01S21	562
R	Recall Performed	PERFORM RECALL #01S21	562
R	Recall Performed	PERFORM RECALL 01S21,SEAT BELT BUCKLE RECALL.	562
R	Recall Performed	PERFORM RECALL #01S21	562
R	Recall Performed	01S21 SEAT BELT CAMPAIGN	936
R	Recall Performed	PERFORM 01S21 RECALL SEATBELT	818
R	Recall Performed	A99 PERFORM 00S21 SEAT BELT BUCKLE	936
R	Recall Performed	01S21 RECALL SEAT BELT	936
R	Recall Performed	A99 PERFORM 00S21 SEAT BELT BUCKLE	936
R	Recall Performed	RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 1H	941
R	Recall Performed	INSPECT PER 01S21 RECALL INSTRUCTIONS	225
R	Recall Performed	DRIVERSIDE AND PASSENGER SIDE SEAT BELT BUCKLES INOP	702
R	Recall Performed	RECALL 01S21 SAFTEY RECALL SEAT BELT BUCKLES	310

STOCK UNIT IS INVOLVED.	R	Recall Performed	DRIVERS SIDE SEATBELT BUCKLE FAILED 01S21 INSPECTION	901
	R	Recall Performed	PERFORM RECALL 01S21 LEFT BUCKLE PASSED, RIGHT BUCKLE FAILED	209
	R	Recall Performed	PERFORM RECALL 01S21 LEFT BUCKLE PASSED, RIGHT FAILED	209
	X	Other	FRONT SEAT BELTS VERY HARD TO BUCKLE	831
	X	Other	FRONT SEAT BELT IS INOP	913
	X	Other	CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT RETRACT PROPERLY	506
	X	Other	CUSTOMER STATES SEAT BELT BUCKLE ON DRIVER SIDE IT JAMMED	361
	X	Other	SEAT BELT NOT WORKING PROPERLY	909
	X	Other	SEAT BELTS NO WORKING CORRECTLY	281
	X	Other	SEAT BELTS INOP	281
	X	Other	SEAT BELT BUSKLE INOPERATIVE	713
	X	Other	CUST STATES R F SEAT BELT TWISTED OR BUCKLE TURNED WRONG WAY	972
	X	Other		305
	X	Other	BOTH FRONT SEAT BELT BUCKLES INOP	727
APROX TIME: 0.4 HRS JOB STARTEDV 7.68.7 ON 01 23 02	X	Other	CUST STATES THE DRIVER SIDE SEAT BELT BUCKLE IS INOP	582
	X	Other	CUST STATES DRIVERS SIDE SEATBELT TWISTED SOP IS IN	910
	X	Other	CUSTOMER STATES BOTH FRT SEAT BELT BUCKLES WONT WORK	381

	X	Other	PASS SEAT BELT HARD TO BUCKLE	310
	X	Other		818
	X	Other	SEAT BELT BUCKLE NOT ENGAGING SOMETIMES ON P SIDE FRONT	817
	X	Other	CUST STATES THE SEATBELT LIGHT COMES ON INTERMITTANTLY, WHEN THE SEATBELTS ARE ON. CHECK AND ADVISE	858
	X	Other	DRIVERS SIDE SEAT BELT DOESNT WORK PROPERLY	919
	X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	818
	X	Other	CHECK SEATBELTS INOP	843
	X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	818
	X	Other		757
	X	Other	SEAT BELT NOT WORKING	727
	X	Other	(PASS SIDE SEAT BELT BUCKLE	404
	X	Other	TECH 125	
	X	Other	INSPECT SEAT BELT BUCKLE FOR PROPER RETENTION	520
	X	Other	SEAT BELT DEFECTIVE	919
	X	Other	CUSTOMER REPORTS WHEN AT A STOP IN GEAR AND DRIVERS SEAT BELT ATTACHED. SEAT BELT WARNING LIGHT AND WARNING CHIME WILL SOUND AT TIMES	909
	X	Other	CUST STATES SEAT BELT BUCKLE STICKS	770
	X	Other	CUSTOMER STATES FRONT PASSENGER SEAT BELT DOES NOT LATCH PROPERLY	805
	X	Other	CUSTOMER STATES THAT RT SIDE BELT INOP	817
Y, RETEST AND OK	X	Other	A88 C S SEAT BELT LIGHT DOESNT COME ON AT TIMES	504
	X	Other	CUSTOMER STATES DRIVERS SEAT BELT INOP SOP	581

X	Other	RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12	941
X	Other	INSTALL SPO FRONT PASS. SIDE SEAT	409
X	Other	RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 7T	941
X	Other	REPLACE SEAT BELT MISSING BUCKLE ON PASS SIDE	818
X	Other	RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12	941
X	Other	DRV SEAT BUCKLE INOP	*
X	Other	LEFT SEATBELT IS INOP	931
X	Other	DRIVERS SEAT BELT WORKS ERRATICALLY	318
X	Other	CUSTOMER STATES SEAT BELT BINDING	603
X	Other		770
X	Other	CUSTOMER STATES THE RIGHT FRONT PASS. SIDE SEATBELT IS JAMMED UP,SOP # 715179.	703
X	Other	PASS SIDE SEAT BELT IN OP	781
X	Other	SEAT BELT ALARM GOES OFF WHEN SEAT BELT IS LATCHED	949
X	Other	INSPECT SEAT BELT BUCKLE FOR PROPER RETENTION	520
X	Other	CUSTOMER REQUESTED TO CHECK SEAT BELT FUNCTION	919
X	Other	CUSTOMER STATES:SEAT BELT NOT WORKING PROPERLYT BELTS	908
X	Other	CHECK LEFT FRONT SEAT BELT DOES NOT OPERATE PROPERLY	708
X	Other	DRIVERS SIDE RIGHT SEAT BELT MISSING	631
X	Other	S.O.P 155721 BEL & BKLE ASY FRT ST LH, LEFT FRONT SEAT BELT	818
X	Other	OTHER INTERIOR TRIM TROUBLES NO SEAT BELT IN VH NEED ONE ORDERED	515
X	Other	RT SEAT BELT BUCKLE BROKEN	*
X	Other		530

X	Other	DRIVERS SEAT BELT WONT RETRACT PROP SOP IS IN SOP ORDERED RO 277003	505
X	Other		818
X	Other	PASS SIDE SEAT BELT FAIL	818
A	Won't Latch	DRIVER'S FRONT SEAT BELT NOT LATCHING ALL THE TIME.	204
A	Won't Latch	L/F DRIVER'S SEAT BELT WONT ENGAGE	813
A	Won't Latch	PASS SIDE SEAT BELT BUCKLE DOES NOT LATCH..SOP IN 8899	714
A	Won't Latch	DRIVER SEAT BELT WONT FASTEN	*
A	Won't Latch	RT FT SEAT BELT WILL NOT BUCKLE	319
A	Won't Latch	PASS SEAT BELT WONT LOCK	*
A	Won't Latch	RIGH FRONT SEAT BELT BUCKEL WILL NOT LATCH	*
A	Won't Latch	DRIVERS SEAT BELT WILL NOT LOCK IN BUCKLE	*
A	Won't Latch	PASSENGER SEAT BELT WONT LATCH	*
A	Won't Latch	DIAGNOSE AND ADVISE CUSTOMER STATES THAT THE DRIVERS SEAT BELT WILL NOT BUCKLE SHOULDERS HARNESS WILL NOT LOCK INTO BUCKLE	607
A	Won't Latch	SOP SEAT BELT PART	330
A	Won't Latch	CUSTOMER STATES DRIVERS FRONT SEAT BUCKLE WILL NOT BUCKLE	641
X	Other	CUSTOMER STATES AIR BAG LIGHT ON	573
X	Other	CHECK FOR AIR BAG LIGHT IS STAYING ON.	412
X	Other	SRS LIGHT FLASHING DIAGNOSE & REPL. RF SEATBELT BUCKLE ASSY	613
X	Other	LUMIERE AIR BAG ALLUME BUCKLE COTE GAUCHE ENCLENCHE PAS	514
X	Other	VERIFIER POUR SEAT BELT DU CHAUFFERU QUI NE CLENCHÉ PAS BIEN	460
X	Other	REPORT ON AIR BAG LIGHT ON	519

	X	Other	S.O.P. SEAT BELT	631
KLE CLEARED CODE RETESTED VERIFIED REPAIR 8 3610	X	Other	CUST STATES THAT SOMETIMES AIR BAG LIGHT HAS BEEN COMING ON AND STAYING ON, THEN AT TIMES LIGHT COMES ON THEN GOES OUT. LIGHT IS OUT AT TIME OF WRITE UP PLEASE CHECK	734
W SEAT BUCKLE MT REMOVED RIGHT FRT SEAT AND REPALCED X SEAT BUCKLE		Other	CK AIR BAG LITE FLASHING	701
	X	Other	AIR BAG LIGHT ON	*
	X	Other	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE INOPERATIVE	336
	X	Other	DRIVER SIDE SEAT BELT DOES NOT LATCH PROPERLY	818
	X	Other	CUSTOMER STATES THE SEAT BELT IS MISSING	718
	X	Other	CK PASS SIDE FRONT SEAT BELT INOP	401
WITH SEAT TRACK. 42 1661203	X	Other	S39 CUST STATES AIRBAG LIGHT STAYS LIT, ADVISE	561
	X	Other	AIR BAG LIGHT ON	309
	X	Other	AIR BAG LT FLASHES	*
	X	Other	CUSTOMER STATES SEAT BELT LITE CHIMES AND FLASHES INT WHEN SEAT IS ON OR WHEN TURNING	303
	X	Other	CUST STATES DR FRT SEAT BELT BUCKLE INOP	419
	X	Other	AIR BAG LIGHT ON	*
	X	Other	AIR BAG LIGHT IS ON	919
	X	Other	AIR BAG LAMP FLASHER	*
	X	Other	AIR BAG LIGHT ON	605

X	Other	CUSTOMER STATES DRIVERSIDE SEAT BELT MISSING FELT ADVISE	216
X	Other	R F SEAT BELT BUCKLE INOP	*
X	Other	AIR BAG LIGHT IS ON	715
X	Other	DRVR SEAT BELT BUCKLE JAMMED	*
X	Other	REMOVE LF SEAT BELT BUCKLE FOR RECALL 01S21	808
X	Other	RR AIRBAG LIGHT CAME ON & STAYED ON ALL DAY ON WEDNESDAY OF LAST WEEK.PLEASE CHECK.	218
X	Other	AIRBAG LIGHT IS ON	414
X	Other	CUSTOMER STATES AIR BAG LIGHT KEEPS FLASHING AND WILL NOT GO OUT SOMETIMES	410
X	Other	CUST STATES AIRBAG LIGHT COMES ON AND FLASHES FOR THE LAST COUPLE OF DAYS	410
X	Other	CUSTOEMR STATES AIR BAG LIGHT STAYS ON	609
X	Other	AIRBAG LIGHT FLASHES 5 2	403
X	Other	AIR BAG LITE ON S39 01	610
M.	A	Won't Latch	
		REPAIR FOR DRIVERS SEAT BELT WONT LATCH	780
		PASSENGERS SIDE ...FRONT SEAT BELT WILL NOT CLIP WITHOUT HOLDING TH	705
		CS: PASS SIDE SEAT BELT DOESNT LATCH	973
		BOTH FRONT SEAT BELTS LATCHING INTER.	970

A	Won't Latch	(S26) TECH 2133 OWNER STATES LF SEAT BELT BUCKLE DONT LATCH	808
A	Won't Latch	SEAT BELT BUCKLE WONT HOLD	479
A	Won't Latch	CUST STATES DRIVERS SEAT BELT SOMETIMES WILL NOT LATCH OR UN LATCH. CHAECK ALL SEATBELTS.	718
A	Won't Latch	CK L FRT SEATBELT WONT HOLD	973
A	Won't Latch	CUSTOMER STATES DRIVERS FRONT SEAT BELT BUCKLE WILL NOT LATCH	217
A	Won't Latch	DRIVERSDIE SEATBELT BUCKLE DOES NOT LATCH	702
A	Won't Latch	S25 CK LEFT FRONT SEATBELT BUCKLE WONT LATCH	281
B	Won't Stay Latched	REPAIR PASS. SEALTBELT TO STAY FASTENED.	519
R	Recall Performed	RECALL 01S21S ALL OK	216
X	Other	SEAT BELT REPLACED	402
X	Other	CHECK FOR AIRBAG LIGHT FLASHING(CODE52),THEN STAYS ON,NOT ON TODAY	403
X	Other	REPAIR CAUSE OF AIRBAG LIGHT STAYING ON HAD FLASHED TWICE THEN 5 TIMES	519
X	Other	CUSTOMER CONSERN SEAT LATCH STICKY	204
X	Other	CHECK CAUSE OF AIR BAG LIGHT KEEPS COMING ON. 404 0.4 0.4	780
X	Other	DIAG. FOR AIRBAG LIGHT STAYING ON	604

X	Other	RECEIVED SEAT BELT BUCKLE (S40)	514
X	Other	SEAT BELT GAUCHE DURE A ATTACHER ET ENLEVER	819
X	Other	DRIVERS SEAT BELT BUCKLE STICKY TO RELEASE	705
X	Other	AIR BAG LIGHT KEEPS FLASHING	204
X	Other	PROTECTEUR CEINTURE AVANT GAUCHE DEFECT// REINSTALLE LE TRIM DE BOUCLE	450
X	Other	VERIFIER LUMIERE AIR BAG FLASHE REF 259144 B O ARRIVEE	460
X	Other	LA CEINTURE AVANT GAUCHE BLOQUEE/AVERTISEUR SONORE NE FONC PAS.	418
X	Other	01S21, FIXATION DES BOUCLES DE CEINTURES DE SECURITE	418
X	Other	CEINTURE NE TIE PAS	418
X	Other	LIGHT BLINKED AND NOW ON CONSTANT REPLACE DRIVER SEAT BELT TO CORRE	613
X	Other	AIR BAG LIGHT COMING ON	805
X	Other	SEAT BELT WARNING LIGHT STAYING ON (G29)	306
X	Other	DRIVERS SEAT BELT NOT WORKING PROPERLY SOP	410
X	Other	CHECK AIR BAG LIGHT ON	517
X	Other	SEATBELT REAR PASS DOESNT LATCH	218
X	Other	CUSTOMER STATES RESTRAINTS LOOSE NOT ATTATECHNICIAN STATES LOCK PAWL BINDS	203
X	Other	C S AIRBAG LIGHT IS ON, LIGHT HAS BEEN ON FOR ABOUT 3 WEEKS	516
X	Other	CUSTOMER STATES DRIVER SIDE SEAT BELT BUCKLE RELEASE VERY	716
X	Other	INSTALL S O REPLACEMENT SEAT BELT BUCKLE. THIS IS TO CORRECT AIR BAG LIGHT STAYING ON ALL THE TIME.	301

	X	Other	CUSTOMER STATES DRIVERS SIDE SEAT BELT IS MISSING FELT PROTECTOR STRIP	715
	X	Other	L SEAT BELT BUCKLE STUCKS	*
	X	Other	AIR BAG LIGHT ON S O PART	201
	X	Other	CUST STATES ABS LIGHT IS ON	215
	X	Other	INSPECT VEHICLE FOR AIR BAG LIGHT BEING ON.	609
	X	Other	S38 CHECK FOR AIR BAG LIGHT ON	972
	X	Other	AIR BAG LIGHT ON SOP IN	972
	X	Other	CUSTOMER STATES THE AIR BAG LIGHT IS FLASHING, REPORT	925
	X	Other	AIRBAG LIGHT IS ON.	317
	X	Other	AIR BAG LIGHT COMING ON S39	903
	X	Other	DRIVERS SEAT	915
WITH NEW ONE & REINSTALLED ALL PARTS REMOVED	X	Other	CUSTOMER STATES THE SEATBELT LIGHT STAYS ON AFTER SEATBELTS ARE FASTENED.	703
	X	Other	3RD SEAT BELT IS BURIED IN SEAT	261
	X	Other	CUSTOMER STATES THAT SEAT BELT IS INOP	503
	X	Other	AIRBAG LIGHT FLASHES WHILE DRIVING	860
	X	Other		843

X	Other	AIRBAG LIGHT STAYS ON	479
X	Other	DRIVER SEAT BELT BUCKLE INOP	*
X	Other	SEAT BELT CHIME NOT COMING ON.	978
X	Other	AIR BAG LIGHT COMES ON SOMETIMES	308
X	Other	S40 DRIVERS SIDE SEAT BELT BUCKEL RATTLES WHILE DRIVING AND WHILE DRIVING WITH BELT LATCHED THE CHIME AND WARNING	248
X	Other	AIR BAG LIGHT ON	*
X	Other	AIR BAG LIGHT IS ON	215
X	Other	AIR BAG LIGHT ON	*
X	Other	AIR BAG LIGHT STAY ON	*
X	Other	DRIVERS SIDE SETA RECEIVER INOP CCS25 SOP IS HERE	615
X	Other	CK CODE WAS PULLED ON 121401 B2436 PASSSIDE SEAT BELT BUCKLE	717
X	Other	CS AIR BAG LIGHT ON PARTS IN	252
X	Other	CHK. AIR BAG LIGHT FLASHES	815
X	Other	CK AIRBAG LIGHT ON	843
X	Other	CHECK AIR BAG LIGHT FLASHING	978
X	Other		203
X	Other	DRIVER SIDE SEAT BELT WILL NOT HOOK	573

	X	Other	CUSTOMER STATES AIR BAG LIGHT WAS FLASHING, NOW IT IS STAYING ON	319
	X	Other	DRIVER SEAT BELT LATCH INOP	479
	X	Other	SEATBELT DO NOT WORK PROPERLY	352
	X	Other	PASS SEAT BELT REL BUTTON STICKING INTERNLA REL COMPONET FIALUR	.
	X	Other		631
	X	Other	NEEDS R BELT	732
REINSTALLED NEW SEAT BELT, REROUTED WIRING PLUGGED IN, REBOLTED SEAT DOWN, WORKS NORMALLY ***LTS	X	Other	DRIVERS SIDE SEATBELT INOP. SOP PARTS HERE.	207
PER SHOPFOREMAN	A	Won't Latch	CUSTOMER STATES THAT THE PASS SIDE SEAT BELT DOES NOT LATCH PLEASE CHECK AND ADVISE (BUCKLES)	320
LED S.O.P. SEAT BELT BUCKLE W PYROTECHNIC DEVICE; DE ACTIVATED SRS, REMOVED LH SEAT ASSY FOR ACCESS TO RESTRAINT BUCKLE. REMOVED AND INSTALLED NEW BUCKLE, SECURED ELECTRICAL AND	A	Won't Latch	CUST STATES THAT DRIVERS SEAT SOMETIMES DOES NOT LATCH INTO RECIEVER	216
	A	Won't Latch	CHECK DRIVERS SEAT BELT LATCH BUCKLE WILL NOT CLASP SEAT BELT.	780
REINSTALL ALL REMOVED COMPONENTS AND RECHEC K FOR PROPER OPERATION , ALL OK USED MT TIME AS NO LABOR OP IN SLTS FOR 61203	A	Won't Latch	CUSTOMER STATES THAT THE SEAT BELT BUCKLE ON THE DRIVERS SIDE DOESNT CLIP.	701

HECKED.

A	Won't Latch	S40 L F SEAT BELT WONT LATCH	618
A	Won't Latch	S 28 CUSTOMER STATES THE PASSENGER SIDE SEATBELT WILL NOT LATCH IN AND LOCK	219
A	Won't Latch	CUSTOMER STATES SEATBELT INOP	413
A	Won't Latch	GUEST STATES DRIVERS SIDE SEAT BELT WILL NOT LATCH	801
A	Won't Latch	SEAT BELT BUCKLE WILL NOT LATCH	815
A	Won't Latch	REPAIR SEAT BELT	519
A	Won't Latch	CK DRIVERSEAT BELT WILL NOT LATCH	601
A	Won't Latch	SEAT BELT BUCKEL DONT LATCH	*
A	Won't Latch	SEATBELT WILL NOT LATCH	229
	Won't Latch	CUSTOMER STATES THE DRIVERS SIDE SEATBELT BUCKLE WILL NOT LATCH IN HOLDER AT ALL, PLEASE INSPECT AND ADVISE INT TRIM CODE ET	313
A	Won't Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH	714
A	Won't Latch	S SEAT BELT BUCKLE WONT LATCH BUCKEL HAS AN INTERNAL FAILURE	*
A	Won't Latch	RT FRT SEAT BELT DOES NOT LATCH	734
A	Won't Latch	DRIVERS SEAT BELT WILL NOT LATCH	308
A	Won't Latch	DRIVERS SEAT BELT WONT LATCH	419

LT FRT SEAT BELT AND
PRETENSIONER ASSEMBLY AND A
RETEST,OKAY.

A	Won't Latch	CUST STATES LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH.	360
A	Won't Latch	CUST STATES DRIVERS SIDE, SEAT BELT LATCH WILL NOT LATCH	423
A	Won't Latch	QCP S25 RT FT SEATBELT WONT BUCKLE	713
A	Won't Latch	DRIVER BUCKLE WONT LATCH AT TIMES	602
A	Won't Latch	CUST STATES PASS SIDE SEAT BELT WILL NOT LATCH EVERY TIME.	740
A	Won't Latch	CHECK FR PASS SEAT BELT BUCKLE UNABLE TO BUCKLE THE SEAT BELT	702
A	Won't Latch	PASS. SEAT BELT WILL NOT LATCH	806
A	Won't Latch	L F SEAT BELT WONT SNAP INTO BUCKLE	937
A	Won't Latch	CUST STATES SEAT BELT BUCKLE WILL NOT LOCK	315
A	Won't Latch	S40 P SEAT BELT WILL NOT LOCK (SOPHERE)	817
A	Won't Latch	BASE WARR C S DRIVER SEAT BELT BUCKLE WONT LATCH S26	520
A	Won't Latch	PASS. SEAT BELT DOES NOT CLASP	920
A	Won't Latch	DRIVERS SIDE SEATBELT WILL NOT LOCK INTO BUCKLE, 336	619
A	Won't Latch	DR SEAT BELT BUCKLE WILL NOT LATCH	913
A	Won't Latch	CUST STATS DRIVERS SEATBELT WONT LATCH	409
B	Won't Stay Latched	CUSTOMER STATES THAT PASSENGER RT.FRT.SEAT BELT BUCKLE WONT STAY LATCHED.	254
B	Won't Stay Latched	CHECK PASSENGER SEAT BELT. CUSTOMER STATES THAT IT DOESNOT STAY LOCKED	301
B	Won't Stay Latched	INTERIOR TRIM REPAIR CUST STATES SEATBELT WILL NOT STAY LATCHED,REVIEVD SOP	830
B	Won't Stay Latched	INTERIOR TRIM REPAIR CUST STATES PASS SEAT BELT WILL NOT STAY LOCKED	830

	C	Unlatches/Releases	CUSTOMER STATES THE DRIVER SEAT BELT COMES UNBUCKLED. INTER MITTENT. ADVISE.	918
	C	Unlatches/Releases	REPLACE PASSENGER FRONT SEAT BELT BUCKLE CAN PULL SEAT BELT OUT OF BUCKLE	858
	C	Unlatches/Releases	CUST SAYS SEAT BELT WONT STAY BUCKLED FOR WIFE BUT WILL FOR CHILD SEAT, COMES UNDONE AT DIFF. TIMES	602
	C	Unlatches/Releases	DRIVERS SIDE SEAT BELT WILL NOT LATCH KEEPS COMING UNLATCHED	281
	X	Other	AIR BAG LIGHT IS FLASHING WHILE DRIVING	402
	X	Other	CUST STATES AIR BAG LIGHT IS ON	419
	X	Other	CUSTOMER STATES AIRBAG LIGHT IS FLASHING	518
	X	Other		303
	X	Other	THE AIRBAG LIGHT IS STAYS ON ON START UP IT BLINKS 4 TIMES THEN STOPS THEN DOES IT SEVEN TIMES THEN	734
LACED PRETENSIONER, REASSEMBLED AND RETESTED OK.	X	Other	CUSTOMER STATES SEATBELT LIGHT IS ON WHILE DRIVING DWITH SEAT BELT ON	989
	X	Other	CHECK FOR PASS SEAT BELT IN OPP.(FEMALE END) PART IN	204
	X	Other	AIR BAG LITE ON	330
	X	Other	CHECK PASSENGER SEATBELT BUCKLE INOP	613
ERATION, OK.	X	Other	SEAT BELT CONCERNS (COIL UNCOIL CONCERNS)	716
	X	Other	SEAT BELT MINDER IS INOP	507

	X	Other	CHECK AND ADVISE FOR SEAT WARNING SIGNAL WONT SHUT OFF (S25)	902
	X	Other	DE ACTIVATE KEY CHIME AND SEAT BELT WARNING.	610
	X	Other	AIR BAG LIGHT STAY ON	*
HING. CHECK OPER OF SWITCH AT C3014 AND INTERNAL SWITCH IN BUCKLE. THERE WAS NO APARENT SHORTS IN HARNESS. SHORT IS INTERNAL TO DRIVERS SEATBELT BUCKLE ASSEMBLY. REPLACED. OPERATING PROPERLY NOW	X	Other	CUSTOMER STATES THAT SEAT BELT WILL NOT GO OUT TILL AFTER ABOUT 2 OR 3 MINS THEN WILL COME BACK ON AND THEN STAYS	540
	X	Other	AIR BAG LIGHT ON	*
	X	Other	SUBLET CUST STATES HAS AN AIR NOISE DRIVERS DOOR AND DOOR HARD TO CLOSE CINDY WILL SHOW	614
	X	Other	DRIVERS SIDE SEAT BELT IS INO. CCT90	248
	X	Other	SOP FOR SEAT BELT BUCKLE AIR BAG LIGHT WAS ON.	809
	X	Other		*
RS SEAT AND REPLACE SEAT BELT BUCKLE PRETENSIONER ASSEMBLY. CLEAR CODES AND RETEST, OKAY. (28) PERFORM QUALITY CHECK.	X	Other	S39 AIR BAG LIGHT ON, OWNER STATE	808
	X	Other	CHECK AIR BAG LIGHT ON	336

FECTIONE, R&I LEFT FRONT SEAT, R&R BUCKLE PRE TENSIONER, CLEARED CODE FROM RCM, TESTED FOR PROPER OPERATION	X	Other	AIR BAG LIGHT IS ON AND FLASHING	281
CODE B1877 LEFT PRETENSIONER CIRCUIT OPEN, REPLACED LEFT FRONT SEATBELT	X	Other	CHECK AIR BAG LITE STAYS ON	808
	X	Other	VEHCILE FORNT RH SEAT BELT BUCKEL INOP	*
	X	Other	PASS SEAT BELT BUCKLE INOP	252
	X	Other	CUSTOMER STATES THAT AIR BAG LIGHT FLASHES 46 THEN STAYS ON SOLID	614
	X	Other	DRIVER SIDE FRONT SEAT LOOSE	619
	X	Other	AIR BAG LIGHT ON	*
	X	Other	DR SEAT BELT HARD TO LATCH PARTS ORDERED	806
	X	Other	S39 A	504
	X	Other	AIRBAG LIGHT FLASHES 4 6	352
R BENCH SEAT FOR ACCESS	X	Other	CUSTOMER STATES THAT THE AIRBAG LIGHT IS FLASHING	767
	X	Other		*

	X	Other	ADVISE ON RT FT SEATBELT BUCKLE INOP	313
	X	Other	DRIVER SIDE SEATBELT INOP. SOP	805
	X	Other	AIR BAG LGHT FLASHING	*
	X	Other	AIR BAG LIGHT ON	*
	X	Other	DRIVER SEATBELT WILL NOT LOCK.	910
	X	Other	STS AIRBAG LIGHT WAS FLASHING 3 TIMES THEN 4 TIMES THEN STAYED ON	407
	X	Other	CUST STATES AIR BAG LIGHT ON.	812
	X	Other		*
	X	Other	SEAT BELT INOP CAN T BUCKLE DRIVERS SEAT BELT	936
	X	Other	CK AIRBAG LIGHT IS FLASHING ON OFF	919
	X	Other	S40 PASS SIDE SEAT BELT INOP CUST STATE	954
	X	Other	AIRBAG LIGHT ON	*
EST REINSTALL CARPET	X	Other	CK AIR BAG LITE ON	423
	X	Other	AIR BAG LIGHT ON	*
	X	Other	SEATBELT INOP ON DRIVER SIDE	770
	X	Other	AIRBAG LIGHT ON	*
	X	Other	SEAT BELT CHIMES SEAT BELT LIGHT FLASHES EVEN WITH SEAT BELTS BUCKLED	513

RTS TO POWER AND GROUND TIME TO TEST CIRCUIT IN PRETENSION LATCH (WHEN MOVED SHOWS OPEN IN LATCH EVEN WHEN LATCHED) TIME TO REPLACE PRETENSIONER LATCH TIME TO RR DRIVERS SEAT TO	X	Other	G29 SEAT WARNING CHIMES STAY ON	972
	X	Other	AIRBAG LIGHT FLASHES	281
	X	Other	AIRBAG LIGHT COMES ON, AND STAYS ON AT TIMES	214
	X	Other	AIR BAG LIGHT ON SOLID.	541
	X	Other	1 AIR BAG LIGHT ON	541
CKLE PRETENSIONER. CLEAR CODE AND RETEST, OKAY. (28) PERFORM QUALITY CHECK.	X	Other	S39 PASSENGER AIR BAG LIGHT SWITCH WAS AND AIR BAG LIGHT ON DASH WAS FLASHING, OWNER STATE	808
	X	Other	CUST STATES AIR BAG LIGHT FLASHING OFF AND ON WHILE DRIVING, AT TIMES LIGHT WILL STAY ON	210
	X	Other	S29 AIR BAG LIGHT IS FLASHING CODE 64 WHILE DRIVING OFF AND ON	504
O REMOVE DRIVERS SEAT TO ACCESS BUCKLE. RECHECKED OPERATION. OK.	X	Other	SEAT BELT COIL UNCOIL TROUBLES	248

	X	Other	S39 AIR BAG LIGHT FLASHES	818
	X	Other	CUSTOMER STATES AIR BAG LIGHT STAYS ON AT TIMES WHILE DRIVING	210
	X	Other	CUST STATES AIR BAG LIGHT FLASHING ON AND OFF CHECKED AIR BAG SYSTEM REPLACED PASS SIDE SEAT BELT BUCKLE	910
	X	Other	THE SEAT BELT CHIME WILL SOUND AT ALL TIMES, EVEN IF THE SEATBELTS ARE FASTNED	619
REMOVED LEFT FRONT SEAT TO TRAXCED OUT AND REPLACED LEFT FRONT PRETENSIONER ASSY. CLEARED CODES AND RETESTED.	X	Other	QUALITY CHECK INITIALS: CK AIR BAG LIGHT STAYS ON S39	210
	X	Other	AIR BAG LIGHT STAYS ON	337
I L F SEAT FOR ACCESS, RETESTED WITH NO FURTHER PROBLEMS, NGS SETUP & TEST, X CHECKED & CLEARED ANY AIR BAG CODES.....	X	Other	DRIVERS SIDE BUCKEL INOP	617
	X	Other	CUSTOMER STATES AIR BAG (SRS) WARNING LIGHT FLASHES 4 TIMES THEN 7 TIMES AND THEN WILL STAY ON	714
	X	Other	AIR BAG LIGHT ON. SOP PARTS	305
	X	Other	CUSTOMER STATES AIRBAG LIGHT STAYING ON	941
	X	Other	CUSTOMER STATES THAT THE AIR BAG LIGHT IS ON SOP ARE HERE	931

	X	Other	CUST STATES THE AIR LIGHT IS ON	210
	X	Other	S39 AIR BAG LIGHT ON	858
	X	Other	CUST. STATES AIR BAGS AND GIVING A CODE OF 47 NO LIGHT IS ON RIGHT KNOW.....A85	330
	X	Other	C S SHE CAN SEE AIR BAG AND AIR BAG LIGHT IS GOING ON AND OFF	804
	X	Other	CUST STATES AIRBAG LIGHT IS ON INSTALL SOP USE SPO 02114004	805
	X	Other	CUSTOMER STATES AIR BAG LIGHT COMES ON INTERMITTEN	843
	X	Other	S39 AIR BAG LIGHT IS ON.	214
	X	Other	AIRBAG LIGHT IS ON	878
OWNER RESISTANCE HIGH. 15.2OHMS 8 REPLACED DRIVER SEAT BELT PRE TENSIONER. 9 REACTIVATE SRS SYSTEM. 10 RETEST SRS SYSTEM. 11 0.1IF OASIS,	X	Other	S39 CK SRS LIGHT STAYS ON WHILE DRIVING AT TIMES, CUSTOMER STATES	808
NGER SEATS. 5 REPLACED DRIVER AND PASSENGER SRS SEAT BELT PRETENSIONERS. 6 REINSTALL DRIVER AND PASSENGER SEATS. 7 REACTIVATE SRS SYSTEM. PROVE OUT SRS SYSTEM. 8 RETEST SRS	X	Other	S39 CK AIR BAG LIGHT FLASHES , CUSTOMER STATES	808

AND RECHECKED DONE	X	Other	CUST STATES AIR BAG LIGHT GOES ON OFF CHECK AND ADVISE	916
LE, RETEST OK. CAUSAL PART 1061203 CONDITION CODE X2.	X	Other	SEAT BELT WARNING STAYS ON WHEN SEATBELT IS IN	936
	X	Other	CUST STATES THAT THE AIR BAG LIGHT IS ON	407
	X	Other	ADVISE ON SEAT BELT NOT LATCHING PROPERLY	715
	X	Other	C S SEAT BELT ALARM GOES OFF WITH SEAT BELT BUCKLED	502
	X	Other	CUSTOMER STATES AIR BAGLIGHT ON	304
	X	Other	CHECK AIR BAG LIGHT ON	319
	X	Other	CUST STATES DRIVERS SEAT BELT BUCKLE INOP	858
	X	Other	AIR BAG LIGHT FLASHES	864
	X	Other	CSUTOMER STATES SEAT BELT BROKEN	850
	X	Other	CHK AIR BAG LIGHT FLASHING	859
	X	Other	REPLACE DRIVERS SIDE SEAT BELT BUCKLE	920
	X	Other	AIR BAG LIGHT IS ON	909
	X	Other	CUST STATES THE AIR BAG LIGHT KEEPS COMEING ON AND STAYING ON	512
	X	Other	CUSTOMER STATES AIR BAG LIGHT IS ON	512
	X	Other	CUSTOMER STATES SEAT BELT WARNING CONTINUES TO BEEP EVEN AFTER SEAT BELT IS BUCKLED.	507

	X	Other	DRIVERS SIDE SEAT BELT INOPERABLE FOUND AT TIME OF PDI	281
	X	Other		334
	A	Won't Latch	S40 DRIVERS SEAT BELT WONT BUCKLE DIAG \$36.00	313
	A	Won't Latch	SEAT BELT INOP	*
	A	Won't Latch	DRIVER SEAT BELT WONT LATCH	256
COULD NOT LATCH CORRECTLY,CHECKED AND LUBED RAILS.REINSTALLED SEAT AND ASSY CHECKED SEAT ADJUSTING ALL FUNCTIONS WORKING CORRECTLY.NEW LATCH OPER ATION OK.	A	Won't Latch	DRIVERS SEAT BELT INOP WONT LATCH	317
	A	Won't Latch	CUSTOMER STATES DRIVER SIDE SEAT BELT WILL NOT LATCH	540
	A	Won't Latch	CUSTOMER STATES PASS SIDE SEAT BELT WILL NOT LOCK	302
	A	Won't Latch	DRIVER SEAT BELT WILL NOT HOLD AT TIMES	216
	A	Won't Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH SOP	870
	A	Won't Latch	C S SEAT BELT NOT CLICKING TOGETHER	919
	A	Won't Latch	PASS SEAT BELT BUCKLE MALFUNCTION BUTTON STICKS AND WILL NOT ALLOW BELT TO LATCH IN UNLESS BUTTON IS PUSHED DOWN	216
	A	Won't Latch	DRIVER SIDE SEATBELT WONT LATCH.	805
	A	Won't Latch	SEATBELT WILL NOT LATCH AT ALL, RECALL?	419
	A	Won't Latch	RH SEAT BELT BUCKLE WONT LATCH..NOT INVOLVED IN 01S21 RECALL	218
	A	Won't Latch	REPLACE LEFT LEAT BELT BUCKLE WONT HOLD	836
	A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	818

A	Won't Latch	RIGHT FRONT SEAT BELT WILL NOT CATCH AT TIMES	817
A	Won't Latch	CUST STS DRVR SIDE FRONT SEAT SEAT BELT WONT LATCH	954
A	Won't Latch	DRIVERS AND PASSANGER SIDE SEAT BELTS WILL NOT LATCH PROPERLY	818
A	Won't Latch	CUSTOMER STATES SEAT BELT WONT BUCKLE	217
A	Won't Latch	SEAT BELT BUCKLE RETENTION	503
A	Won't Latch	DRIVERS SIDE AND PASSANGER SIDE SEAT BELTS WILL NOT LATCH PROPERLY	818
A	Won't Latch	CHECK SEAT BELT BUCKLE	281
A	Won't Latch	DRIVERS SIDE SEAT BELT WONT LATCH AT TIMES.	602
A	Won't Latch	CUSTOMER STATES THAT THE R F SEATBELT WILL NOT LATCH	970
A	Won't Latch	DRIVERS SEAT BELT WILLNOT BUCKLE 3 36	619
A	Won't Latch	FRONT PASS SEAT BELT WONT LATCH	805
A	Won't Latch	CUSTOMER STATES THAT SEATBELT DOESNT ALWAYS LATCH	414
A	Won't Latch	SEAT BELT BUCKELS WONT LATCH ON PS AND DS BUCKELS	541
A	Won't Latch	CUSTOEMR STATES THE DRIVERS SIDE SEAT BELT IS NOT LATCHING INTO PLACE.....S40	318
A	Won't Latch	CHECK SEAT BELT RIGHT SIDE WILL NOT LATCH.	918
A	Won't Latch	C S DRIVER SAFETY BELT DOES NOT LATCH SOMETIMES	512
A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	818
A	Won't Latch	CUSTOMER STATES DRIVER SIDE SEAT BELT LATCH DOESN T ALWAYS LATCH	505

	A	Won't Latch	DRIVERS SEATBELT NOT LATCHING TO BUCKLE OR RETRACTING CHECK AND ADVISE	403
	A	Won't Latch	CK LEFT SEAT BELT	956
	A	Won't Latch	DRIVERS SEAT BELT WONT LATCH, NOT ON RECALL, DIXIE SAYS SHOULD HAVE PART IN STOCK	316
PROPER OPERATI ON AFTER REPAIR,	A	Won't Latch	C S PASS FRONT SEAT BELT WILL NOT LATCH SOMETIMES CK . .	417
	A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	818
	A	Won't Latch	DRIVERS SEAT BELT WONT LATCH	505
	A	Won't Latch	CUST SAYS DRIVERS SEAT BELT DOES NOT LATCH	972
	A	Won't Latch	S28 CUSTOMER STATES; SEAT BELT LATCH IS INOP ON DRIVER SIDE	972
	A	Won't Latch	THE DRIVERS SEATBELT WILL NOT LATCH. INSTALL S O PART	636
	A	Won't Latch	CUST STATES PASS SIDE SEATBELT, BROKEN WILL NOT LATCH	760
CLEAR CODES & RETEST SYS	A	Won't Latch	THE LEFT FRONT SEAT BELT WILL NOT LATCH.	313
	A	Won't Latch	S28....CHECK LT FRONT SEAT BELT BUCKLE DOES NOT LATCH	818
	A	Won't Latch	DRIVERS SEAT BELT BUCKLE WONT LATCH INTER ADVISE	928
	A	Won't Latch	CUSTOMER STATES CANNOT LATCH DRIVERS SEAT BELT BUCKLE	715
	A	Won't Latch	DRIVERS SEAT BELT WONT BUCKLE	760

A	Won't Latch	DRIVERS SIDE FRONT SEATBELT BUCKLE WONT CLASP OR HOLD WARNING LIGHT AND CHIME WONT COME ON	218
A	Won't Latch	RT FRT SEAT BELT WONT LATCH.	909
A	Won't Latch	DRIVERS SEAT BELT WONT LATCH	713
A	Won't Latch	CUST STATES LEFT FRONT SEAT BELT WONT BUCKLE SOP HERE.	559
B	Won't Stay Latched	CK FOR DRIVERS SEAT BELT WONT STAY LATCHED.	903
B	Won't Stay Latched	CUSTOMER STATES SEAT BELT BUCKLE WILL NOT STAY LATCHED	850
B	Won't Stay Latched	RIGHT SEAT BELT WILL NOT STAY BUCKLED	405
B	Won't Stay Latched	DRIVERS SEAT BUCKLE WONT STAY LATCHED	281
B	Won't Stay Latched	CUSTOMER STATES PASSENGER SIDE SEATBELT DOES NOT STAY LATCHED	702
B	Won't Stay Latched	PASSENGER SIDE SEAT BELT BUCKLE IS NOT STAYING LATCHED IN	402
B	Won't Stay Latched	CHECK PASSENGER SIDE SEATBELT WILL NOT LATCH	281
B	Won't Stay Latched	LEFT SEATBELT WONT STAY LATCHED	780
B	Won't Stay Latched	DRIVERS SEAT BELT WILL NOT STAY LATCHED	815
B	Won't Stay Latched	CUST STATES THE DR SEAT BELT WILL NOT STAY LATCHED	651
B	Won't Stay Latched	DRIVERS SEAT BELT INOPERATIVE	901
C	Unlatches/Releases	CUSTOMER STATES DRIVERS SIDE SEATBELT COMES UNLATCHED. CHEKC AND ADVISE	812
C	Unlatches/Releases	REPAIR PASSENGER SEAT BELT BUCKLE WONT LATCH OR WILL UNBUCKLE *****SOLD UNIT*****	714

ING PART OF SRS SYSTEM.
CLEAR CODES. RETEST. ALL
OKAY. 8626

R	Recall Performed	P05 VEHICLE IS PAST DATE CODE BUT DRIVERS BUCKLE FAILS	314
R	Recall Performed	PERFORM 01S21 RECALL SEATBELT	818
R	Recall Performed	PERFORM 01S21 RECALL SEATBELT	818
R	Recall Performed	BASE(S40) RF SEAT BELT FAILS	520
R	Recall Performed	RECALL 01S21 SEATBELT (INSPECTION	308
R	Recall Performed	INSPECT FOR SEAT BELT BUCKLE RECALL	904
R	Recall Performed	CHECK SEAT BELTS SAME CONDITION AS 01S21	281
R	Recall Performed	PERFORM 01S21 RECALL SEATBELT	818
R	Recall Performed	PERFORM 01S21 RECALL SEATBELT	818
R	Recall Performed	RECALL 01S21 LEFT AND RIGHT	809
R	Recall Performed	REPLACED SEAT BELT BUCKLE	402
R	Recall Performed	RECALL 01S21	956
R	Recall Performed	REPLACE RT FRT SEAT BELT BUCKLE FAILED BUCKLE TEST	602
R	Recall Performed	CUSTOMER STATES THAT THE PASSENGER SIDE SEAT BELT FAILS	303
R	Recall Performed	RECALL 01S21	559
R	Recall Performed	PERFORM 01S21 RECALL SEATBELT	818
R	Recall Performed	CEHCK SEAT BELTS WERE TESTED WITH TOOL FOR RECALL AND FAILED	916
X	Other	AIR BAG LIGHT ON	828

R OPEN CIRCUIT REACTIVATE
 SYSTEM MONITOR PID WHILE
 WIGGLING HARNESS FROM
 MODULE TO PRETENTIONER X
 FAULT DUPLICATED R AND R
 DRIVER PRETENTIONER
 REINSTALL SEAT VERIFY REPAIR

	Other	AIR BAG LIGHT COMES ON INTERMITTENT SOMETIMES FLASHES SOMETIMES ON OTHERS NOT	941
X	Other	CUST STATES AIRBAG LIGHT FLASHES AND THEN STAYS ON (INTERMITTENT)	716
X	Other	AIR BAG LIGHT FLASHES ON AND OFF	662
X	Other	CHECK FOR FRONT SEATBELT NOT WORKING RIGHT	207
X	Other	CUST STATES THE AIR BAG LIGHT WILL FLASH WHEN ENGINE STARTED AND STAY ON WHILE DRIVING INTERMITTANTLY	407
X	Other	AIR BAG LAMP IS ON	937
X	Other	AIRBAG LIGHT IS ON	904
X	Other	REPLACED BELT AND TENS	978
X	Other	CHECK AIRBAG LIGHT KEEPS COMING ON	252
X	Other	CK AIR BAG LT IS ON & FLASHING	919
X	Other	AIR BAG LIGHT ON	803
X	Other	SEAT BELT BUCKLE LOOSE	732
X	Other		256
X	Other	AIR BAG LIGHT STAYING ON	506

ENT INTO PID DATA AND
 CHECKED RESISTANCE OF BOTH
 DRIVERS AND PASS.

PRETENSION ERS. BOTH READ X
 2.1 OMS. WIGGLED DRIVERS
 WIRE AND DID NOT CHANGE
 RESISTANCE. REMOVED
 DRIVERS 80 BENCH SEAT

ER CIRCUIT RE SISTANCES
 DRIVERS SIDE AT 11.3 OHMS.
 REMOVED DRIVERS SIDE SEAT.
 REPLACED SEAT BUCKLE PRE X
 TENSIONER & REASSEMBLED.
 CLEARED CODE & ROAD TESTED
 OK. RERAN RCM SELF

	Other	C.S AIR BAG LIGHT WAS FLASHING UNTIL THIS MORNING.1	216
X	Other	AIR BAG LIGHT FLASHES	716
X	Other	AIR BAG LIGHT FLASHING	334
X	Other	SEAT BEAT NOT WORKING PROPERLY L5Z 1061202AAA..	727
X	Other	Q CHECK FOR PASSENGER SIDE SEATBELT NOT WORKING PROPERLY	207
X	Other	AIRBAG LITE ON	757
X	Other	AIRBAG LIGHT STAYS ON	614
X	Other	CUSTOMER SAYS AIR BAG LIGHT COMES ON SOMETIMES FLASHES SOMETIMES	541
X	Other	LF DRIVERS BUCKEL OO DE ACTIVATE AIR BAG SYSTEM	.
X	Other	AIR BAG LIGHT ON INTER, FLASHES INTER AND SOLID AT OTHER TIMES, ADVISE	301
X	Other	REPLACE SEAT BELT	910
X	Other	CHECK CAUSE DRIVERS SIDE SEAT BELT NO WORK	616

SIONER, RETEST PASSED,
ROADTESTED OK

X	Other	CUST SAYS A BAG LITE IS COMING ON & FLAHES 4 THEN 6 THEN STAYS ON	270
X	Other	CHECK FOR DRIVER SIDE SEAT BELT LATCH STICKS	865
X	Other	CUST STATES AIR BAG LITE FLASHES	407
X	Other	C S AIR BAG LIGHT WAS FLASHING THEN ON SOLID ADVISE	607
X	Other	S39,CUST SAYS AIR BAG LIGHT WOULD FLASH ON DASH,NOW LIGHT STAYS ON ALL THE TIIME	305
X	Other	SPECIAL PARTS FOR SEAT BELT HAS ARRIVED PLEASE INSTALL DRIVER SIDE	416
X	Other	AIR BAG LIGHT ON	840
X	Other	C S DRIVERS SEAT BELT DOES NOT WORK PROPERLY	631
X	Other	A85 CUST STATES AIR BAG LIGHT COMES ON	727
X	Other	CUST SAYS AIR BAG LIGHT FLASHING ON AND OFF THEN AIR BAG LIGHT STAYS ON CONSTANTLY	972
X	Other	AIRBAG LIGHT CAME ON, CHECK CAUSE	734
X	Other	CUSTOMER STATES AIRBAG LIGHT IS FLASHING	310
X	Other	CUSTOMER STATES: AIRBAG LIGHT ON WAS FLASHING NOW ON ALL THE TIME	760

X	Other	S39 CUSTOMER STATES AIR BAG LIGHT STARTS BLINKING AND THEN STAYS ON.	958
X	Other	S39 AIR BAG WARNING LIGHT TROUBLES	949
X	Other	SEAT BELT BUCKLE RETENTION	503
X	Other	AIR BAG LIGHT FLASHES WHEN DRIVING. RECHECK 112	414
X	Other	SEAT BELT IN INOP	509
X	Other	JPASSENGER SEAT BELT WONT RELEASE	262
X	Other	CUST STATES THE AIR BAG LIGHT COMES ON AT TIMES.	281
X	Other	CUST. STATES AIR BAG LIGHT COMING ON	512
X	Other	AIRBAG LIGHT IS ON	903
X	Other	CUSTOMER STATES AIR BAG LIGHT CAME ON YESTERDAY. SOMETIMES IT WILL FLASH. SOMETIMES STAYS ON SOLID. LIGHT WAS NOT	309
X	Other		808
X	Other		808
X	Other	REPAIR FOR RIGHT SEATBELT FAILURE TRIM H T	608
X	Other	REPLACE BROKEN SEAT BELT ASSY (OR ET)	952
X	Other	SEAT BELT BUCKLE NOT WORKING PROPERLY	281

1 AND POINT TEST B1881 ALSO INSTALL THE SIMULATOR TO PERFORM PINPOINT, FOUND BOTH CIRCUIT GOOD REPLACE BOTH PRETENSIONER. HAS TO REMOVE BOTH FRONT SEAT TO GAIN ACCESS TO PRETENSIONERS.

ME CODE ON DRIVE
 SIDE,PERFOMED DIAGNOSTIC
 PIN POINT TEST DRIVE SIDE
 BUCKLE CONNECTOR FOUND
 OPEN CIRCUIT. REPLACED NEW
 DRIVE SIDE SEAT BELT BUCKLE
 AND CLEAN MEMORY CODE AND
 PERFOMED ON

X	Other	AIR BAG LIGHT IS FLASHING	670
X	Other	SEAT BELT BUCKLE FAILED	520
X	Other	S39.....OWNER REPORTS INTERMITTENT AIR BAG LIGHT COMES ON INTERMITTENTLY	407
X	Other	INSPECT SEAT BELT BUCKLE	804
X	Other	AIRBAG LIGHT FLASHES ON AND OFF	512
X	Other		818
X	Other	SEAT BELT DING NOISE WITH SEAT BELT IN AND DOOR SHUT, UNHOOK AND LATCH AGAIN AND IS OK FOR AWHILE	503
X	Other	S39, AIR BAG LIGHT ON INSTALL SOP SEAT BELT	727
X	Other	SEAT BELT BUCKLE	872
X	Other	CUSTOMER STATES THE AIRBAG LIGHT FLASHES THEN GOES SOLID. SOP HERE 631	251
X	Other	AIR BAG LIGHT FLASHING REPL	908
X	Other	AIR BAG LIGHT FLASHES.	402
X	Other	SEAT BELT BUCKLE NOT WORKING CORRECTLY	503

	X	Other	AIR BAG LIGHT IS ON ALL THE TIME.S39	231
	X	Other	1 CUSTOMER STATES AIR BAG LIGHT FLASHING	714
	X	Other	AIRBAG LIGHT FLASHES AT TIMES S39	972
	X	Other	SUPPLEMENTAL RESTRAINT SYSTEM LIGHT IS ON AIR BAG LIGHT ON INTER.	830
	X	Other	SEAT BELT INOP	909
	X	Other	SEAT BELT INOP	909
	X	Other	SEAT BELT DOES NOT WORK PROPERLY	702
	X	Other	AIR BAG LIGHT FLASHING AT TIMES AND NOT COMING ON AT OTHER TIMES	909
	X	Other	SEATBELT TROUBLES	626
	X	Other	CUSTOMER STATES PASS. SIDE SEAT BELT STUCK	501
	X	Other	SEAT BELTS RETRACT SLOWLY	208
	X	Other	CUST STATES, AIRBAG WARNING LIGHT FLASHES WHILE DRIVING	305
	X	Other	CUST STATES AIR BAG LITE STARTS FLASHING AND THEN STAYS ON STEADY	909
WORKING PROPERLY.	X	Other	AIR BAG LIGHT IS ON	662

ECK OK.

X	Other	AIR BAG LIGHT COMES ON INTERMITTENTLY	813
X	Other	CHECK AIR BAG LIGHTISON	*
X	Other	AIR BAG WARNING LIGHT TROUBLES	972
X	Other	PASSENEGER SEATBELT NOT WORKING, INTERM. CHECK AND ADVISE	619
X	Other	SEAT BELT BUCKLES INOP	760
X	Other	CUSTOMER STATES THE AIR BAG LIGHT WILL COME ON AND STAY ON. SOMETIMES IT DOES NOT COME ON AND OTHER TIMES IT WILL COME	530
X	Other	REPAIR DRIVER'S SEAT BELT INOP	903
X	Other	RF SEAT BELT BUTTON STUCK	419
X	Other	DIAG AND REPORT ON AIR BAG LITE FLASHING,FLASHED 4 THEN 6 TIME AND DID THAT 5 TIMES.THEN SOLID.	604
X	Other	CUST STATES DRIVER SIDE SEAT BELT INOP	414
X	Other	SEAT BELT BUCKLE INOP	760
X	Other	WF S38 AIR BAG LIGHT ON	405
X	Other	DIAG AND ADVISE CUST STATES AIR BAG LIGHT FLASHES WHILE DRIVING.....46.....(S38)	714
X	Other	QCP S38 AIR BAG LIGHT ON AND HORN INOP	713
X	Other	S38 CUST STATES AIR BAG LIGHT ON KEEPS COMING ON OFF	210

X	Other	FACTORY WARRANTY C S DRIVERS SEAT BELT INOP INTERMITT	602
X	Other	REPAIR FRONT SEAT BELT LATCHES IN OP	651
X	Other	CUSTOMER STATES SEAT BELT INOP	504
X	Other	SEAT BELT BUCKLE INOP	760
X	Other	AIR BAG LITE IS ON.	562
X	Other	CUST STATES PASS SIDE SEAT BELT DOESN T CLIP ALL THE WAY	815
X	Other	S39 AIRBAG LIGHT STAYS ON	713
X	Other	AIR BAG LIGHT STAYS ON AT ALL TIMES	303
X	Other	CUSTOMER STATES THAT THE PASSENGER SIDE SEAT BELT FAILS	303
X	Other	CUSTOMER STATES THAT PASSENGER SIDE SEATBELT FAILS	903
X	Other	CUSTOMER STATES THAT BOTH SEATBELTS FAIL	303
X	Other	SEAT BELT BUCKLE INOP	760
X	Other	REMOVE SEAT BELT FOR SOLD UNIT AND TRANSFER TO STOCK	851
X	Other	BOTH SEATBELTS INOP.	303
X	Other	DRIVERS SEAT BELT LATCH IS BROKEN	952
X	Other	SEATBELT CHIME KEEPS SOUNDING	414

A JUMPER TO IT AND VERIFIED
 HAVING A FAULTY SEAT BELT
 BUCKLE TENSIONER. REPLACED
 FAULTY SEAT BELT BUCKLE
 TENSIONER AND CLEARED
 CODES. NORMAL OPERATION AT
 THIS TIME MT AUTH #

X	Other	S39 AIR BAG WARNING LIGHT TROUBLES	949
---	-------	------------------------------------	-----

X	Other	DRIVER&PASSANGER SEAT BELTS WILLNOT LATCH PROPERLY	818
X	Other	AIRBAG LIGHT ON	228
X	Other	CUSTOMER STATES THAT AIRBAG LIGHT IS ON.	541
X	Other	CUST STATES AIR BAG LIGHT COMES ON WHEN HITTING A BUMP, GOES OUT WHEN ENG IGN IS CYCLED, AIR BAG LIGHT FLASHES AT TIMES	941
X	Other	CK AIRBAG LIGHT ON	940
X	Other	CUSTOMER STATES THAT THE AIR BAG LIGHT COMES ON AND OFF EVERY TWO DAYS	817
X	Other	DRIVERS SEAT BELT BUCKLE INOP	714
X	Other		405
X	Other	DRIVERS SEAT BELT RECEPACLE INOPERATIVE	409
X	Other	H19 CUST STATES AIR BAG LIGHT COMES ON WHEN DRIVING	727
X	Other	CHECK FOR SEAT BELT IS INOP	503
X	Other	DRIVERS SEA BELT IN OP	248
X	Other	S38 CUSTOMER STATES AIR BAG LIGHT ON FLASHING CODE 47	561
X	Other	AIR BAG LIGHT FLASHING	254

X	Other	CHECK AIR BAG LIGHT BACK ON IN DASH, ADVISE CODE 46, ADVISE	214
X	Other	THE AIR BAG LIGHT COMES ON AND OFF EST AND ADVISE	808
X	Other	CUSTOMER STATES ABS LIGHT ON	858
X	Other	AIR BAG LIGHT ON	972
X	Other	AIR BAG LITE ON	850
X	Other	C STATES THAT WHEN SEATBELT IS FASTENED AFTER A FEW BLOCKS OF DRIVING THE SEATBELT CHIME WILL SOUND AND YOU MUST WIGGLE SEAT BELT TO STOP CHIME. CHECK AND ADVISE.	402
X	Other		478
L NOT FAIL REMOVE CARPET TRACE WIRES TO RCM NPF REMOVE RF SEAT PULL AND TWIST LOOM AND CONNECTO R X STILL WILL NOT FAIL ORDER PRETENSIONER INSTALL PRETENSIONER RE TEST	Other	DRIVER SIDE AIR BAG LIGHT STAYS ON.	536
X	Other	AIBAG LIGHT IS FLASHING (4 THEN 6)	808
X	Other	AIRBAG LIGHT COMES ON AT TIMES , WORST COLD	210
X	Other	AIR BAG LIGHT WILL COME ON AT TIMES AND WILL STAY ON A COUPLE OF DAYS **** PARTS ARE IN FOR TECH 243 ****	770

E ASSY., FOUND OPEN AT
 PRETENTIONER, REPAIR OPEN.
 OK NOW. CLEAR CONT. DTCS.
 PERFORMED FINAL QUICK
 TEST.

X	Other	AIR BAG LIGHT ON	972
X	Other	AIR BAG LIGHT IS ON S39	979
A	Won't Latch	CUST STATES DRIVER SIDE FRONT SEAT BELT NOT BUCKLING	201
A	Won't Latch	CUST STATES DRIVERS SIDE FRONT SEAT BELT DOES NOT BUCKLE	201
A	Won't Latch	DRIVERSIDE SEAT BELT WILL NOT SNAP IN ALSO CK ALL SEATBELTS	.
A	Won't Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH AT TIMES	410
A	Won't Latch	S25 DR SEATBELT WONT FASTEN	313
A	Won't Latch	CUSTOMER STATES THE DRIVERS SIDE FRT SEAT BELT DOES NOT LOCK IN POSITION	732
A	Won't Latch	R F BELT BUCKLE WONT FASTEN	*
A	Won't Latch	PASS FRONT SEAT BELT WILL NOT BUCKLE	414
A	Won't Latch	S25 PASS FRONT SHOULDER BELT WILL NOT BUCKLE PER CUST	727
A	Won't Latch	CLIENT STATES RIGHT FRONT SEAT BELT WILL NOT LATCH	850
A	Won't Latch	PASSENGER FRONT SEAT SHOULDER BELT DOES NOT BUCKLE INTO THE BUCKLE.	714
A	Won't Latch	CUSTOMER STATES DRIVERS SEATBELT WILL NOT BUCKLE	334
A	Won't Latch	PASS SIDE SEAT BELT WILL NOT LATCH	878
A	Won't Latch	CUST STATES THAT THE PASS SEAT BELT WILL NOT LATCH	704
A	Won't Latch	STATES DRIVER SEAT BELT DOESNT LATCH	628

	A	Won't Latch	CUSTOMER STATES DRIVERSIDE SEAT BELT WONT CLIP.	606
	A	Won't Latch	PASS SEAT BELT WILL NOT LOCK	559
461202 CC28 QC328	X	Other	S39 AIR BAG WARNING LIGHT TROUBLES	405
	X	Other		630
	X	Other		*
	X	Other		*
	X	Other	CUST STS DRIVERS SEATBELT BUCKLE IS INOP.	818
	X	Other	INSTALL SOP FRONT SEAT BELT ASSY	718
	X	Other	REPLACE BOTH FRONT SEAT BELTS WHICH WERE REMOVED FOR GUEST VEHICLE RO 129413.	619
	X	Other		206
	X	Other	CUSTOMER STATES AIR BAG LIGHT IS ON	201
	X	Other	A85 AIR BAG LIGHT GOES ON WHILE DRIVING THEN GOES OFF	305
	X	Other	CUST SAYS PASS SIDE SEATBELT IS NOT WORKING	685
	X	Other	CUSTOMER STATES THAT D S SEATBELTS DOES NOT WORK.	270
EPLACE SEAT BELT SWITCH RETESTED OK	X	Other	S39 CUST STATES AIR BAG LIGHT COMES AT TIMES HAVE TO TURN OFF IGNITION AND LIGHT GOES OFF	954
	X	Other	AIR BAG LIGHT STAY ON	*

	X	Other		*
	X	Other	CHECK DRIVERS SIDE SEAT BELT WONT LOCK AND UNLOCK	757
	X	Other	ABS LIGHT IS ON	515
	X	Other	L F SEAT BELT INOP	*
	X	Other	CHECK FOR DRIVER SEAT BELT NOT WORKING PROPERLY	918
	X	Other	CUST STATES AIR BAG LAMP FALSHING 51	201
KLE. RE ACTIVATE SYSTEM AND RETEST, OK	X	Other	AIR BAG LIGHT COMES AND GOES	703
	X	Other	CUSTOMER STATED THE SEATBELT IS INOP.	214
	X	Other	DRIVERS SIDE SEATBELT IS STILL STICKING WHEN RELEASING.HAS TO PULL HARD TO RELEASE BUCKLE	352
	X	Other	CUST STATES AIRBAG LIGHT ON	904
	X	Other	AIR BAG LIGHT ON	*
. RERUN FINAL QUICK TEST, PASS (OKAY).	X	Other	CUSTOMER STATES AIR BAG LIGHT STAYS ON AT ALL TIMES WHILE DRIVING, VERIFIED FLASHING BEFORE STAYING ON AT ALL TIMES IN DRIVE (FLASHED CODE 51	562
	X	Other	CK RT SEAT BELT BUCKLE IN OP.	815
	X	Other		718
	X	Other		718