

**HONEYWELL INTERNATIONAL, INC.  
CONSUMER PRODUCTS GROUP**

**SAFETY RECALL!!**

**FRAM G3727 FUEL FILTERS – Manufactured in Mexico from October 18, 2005 through March 21, 2006**



**Country of Origin**

**Date Code**

*Honeywell is recalling FRAM<sup>®</sup> G3727 Fuel Filters that were manufactured in Mexico from October 18, 2005 through March 21, 2006 by one of our suppliers. The affected filters are marked with (i) a date code X52911 through X60801 sequentially or code X600141 and (ii) a Mexico country of origin. The code and country of origin markings appear on the filter housing, as shown above. FRAM G3727 Fuel Filters not bearing a date code in this range or that were manufactured other than in Mexico are not affected by this recall.*

*The subject filters were not manufactured to Honeywell specifications and, as a result, the O-ring may not seat correctly on the fuel line. This condition may cause an inadequate seal at this connection, potentially leading to a fuel leak (i.e., wetting or dripping) and possible vehicle fire.*

*If you own the affected product, please return it to the retailer or installer from whom you purchased the filter for a replacement filter.*

**QUESTIONS? CALL 1-800-890-2075 (option 1)**

**MONDAY THROUGH FRIDAY, 8:00 AM TO 4:45 PM, EST**