

RECEIVED
NVS-215



2006 JUL 24 A 10:13

10166 Olney St, El Monte, CA 91731
626-618-2026 (Tel) 626-452-9225 (Fax)

OFFICE OF
DEFECTS INVESTIGATION

SAFETY RECALL NOTICE

Dear AJ Motorsport Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

AJ Motorsport has decided that certain combination lamps listed below that were manufactured to replace OEM combination lamps originally equipped with amber reflex reflectors fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 108, "lamps, reflective devices, and associated equipment."

FMVSS No. 108 requires all OE motor vehicle replacement lamps to meet or exceed all OE specifications, which includes a required amber side reflex reflector. This amber side reflex reflector was found to be absent in the following lamps:

	AJ Motorsport Part No.	Years, Make, Model, Description
1	AI9195C-4	91-95 Acura Legend Corner Lamp
2	CCAM9302C-E	93-02 Chevy Camaro Corner Lamp
3	CCI9196C	91-96 Chevy Caprice Corner Lamp
4	CF99C-E	99-05 Chevy Full Sized Corner Lamp
5	CS98B-E	98-04 Chevy S10 Bumper Lamp
6	DD9702C-E	97-03 Dodge Dakota Corner Lamp
7	FF9702C-E	97-02 Ford F150 Corner Lamp
8	FP9397B-GTSE	93-97 Ford Probe Bumper Lamp
9	FR01C	01-05 Ford Ranger Corner Lamp
10	FT9679C	96-97 Ford Thunderbird Corner Lamp
11	HA9497C-E	94-97 Honda Accord Corner Lamp
12	HC9295C-2-JC	92-95 Honda Civic Corner Lamp
13	HDS9397C-E	93-97 Honda Del Sol Corner Lamp
14	IR9197C	91-97 Isuzu Rodeo Corner Lamp
15	JC9701B	97-01 Jeep Cherokee Corner Lamp
16	JC9701C	97-01 Jeep Cherokee Bumper Lamp
17	JL02B	02-04 Jeep Liberty Bumper Lamp
18	ME9091C	90-91 Mitsubishi Eclipse Corner Lamp
19	MM9396C	93-96 Mitsubishi Mirage Corner Lamp
20	PF9397B	93-97 Pontiac Firebird Bumper Lamp
21	TO9800C	98-00 Toyota Corolla Corner Lamp
22	TT01-C-CHR	01-04 Toyota Tacoma Corner Lamp
23	TTUN00C	00-04 Toyota Tundra Corner Lamp

Absence of this amber side reflex reflector may cause other drivers to misinterpret or misjudge proximities with oncoming or outgoing motor vehicles, which may result in vehicle crash, personal injury, or even death.

In order to resolve this matter, AJ Motorsport will refund, at no cost to you, any of the non-compliant combination lamps in the aforementioned recall list. Simply contact our sales team and request for an RMA number and we will arrange for the non-compliant lamp to be returned to us for a full refund of the purchase price. If any cost to you was incurred prior to this recall concerning non-compliant lamps, you may be eligible for reimbursement. For more information please call 1-626-618-2026.

If you provide any of these lamps to independent dealers or distributors, please forward a copy this notice to them within five days of receipt to help aid us in recalling these non-compliant combination lamps.

If you believe that we have failed or are unable to remedy this non-compliance issue without charge or within a reasonable amount of time, you may write to the Administrator of National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, D.C. 20590 or call their Vehicle Safety hotline at 1-888-327-4236 (TTY; 1-800-424-9153); or go to <http://www.safercar.gov> more information.

We apologize for any inconvenience this action may have caused you. Here at AJ Motorsport, our main concern is your safety and the safety of all motor vehicle drivers on the road.

Sincerely,

Jack Hsu
Owner, AJ Motorsport