



# **Mack Trucks, Inc.**

# **Safety**

# **Recall**

# **ALERT**

**Date:** August 23, 2006 **Number:** SRA-534-001  
**To:** All U.S. & Canadian Distributors  
**Attention:** Service Manager, Warranty Manager, Parts Manager, Dealer Principal  
**From:** Regulatory Affairs Department  
**Subject:** Non-Compliance Recall, SC0314, Front Glad Hand Option

**Non-Compliance Recall Summary:**

On certain Mack CV model vehicles manufactured from May 2004 through May 2006 with the “front glad hand” option1, the performance criteria, specified in US Regulation 49 CFR 571.121 section 5.7.1, cannot be achieved with the spring brake-modulating valve that is installed on the truck.

The number of vehicles affected is approximately 108 (US only).

**Dealer's Responsibility:**

All non-compliance Recalls, which affect new or used inventory, must be performed before the vehicle is sold or leased.

Additionally, Dealers should make their personnel aware of the non-compliance recall. In the event that a dealer has a vehicle included in the non-compliance recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

**Release Schedule:**

- Repair Instructions are tentatively scheduled for release no later than September 19, 2006.
- The vehicle list is posted on the Trucks Dealer Portal.
- Owner Notices are scheduled to be mailed on September 29, 2006.

**Questions:**

Contact the Regulatory Affairs Department at [vtna.regulatoryaffairs@volvo.com](mailto:vtna.regulatoryaffairs@volvo.com) if you have questions.