



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

December 27, 2006

ELVIE J. FREY, SR.
PRESIDENT
SUNNYBROOK RV INC.
201 14TH STREET
MIDDLEBURY IN 46540

NVS-215paw
06V-482

Subject: FUEL TRANSFER PUMP LEAK/GPI

Dear MR. FREY:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
SUNNYBROOK/TITAN/2006

NHTSA Campaign Number: 06V-482

Mfg's Report Date: November 8, 2006

Components: FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Potential Number of Units Affected: 87

Summary:

ON CERTAIN FIFTH WHEEL TRAVEL TRAILERS EQUIPPED WITH GREAT PLAINS FUEL PUMPS, DUE TO INSUFFICIENT EPOXY ADHESIVE APPLIED AT THE TIME OF INSTALLATION AT THE FACTORY, A FUEL LEAK CAN OCCUR AT THE PUMP'S INLET VALVE.

Consequence:

IN THE PRESENCE OF AN IGNITION SOURCE, A FIRE CAN OCCUR.

Remedy:

SUNNYBROOK RV IS WORKING WITH GREAT PLAINS INDUSTRIES TO HAVE THE FUEL PUMPS REPLACED (PLEASE SEE 06E-016). OWNERS MAY CONTACT GPI AT 1-316-686-7361 OR SUNNYBROOK RV AT 1-574-825-5250.

Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Notification to owners as required by 49 CFR Part 577 must be sent by the vehicle manufacturer(s). Therefore, you are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@dot.gov or delia.lopez@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

for 
George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement