



U.S. Department
of Transportation

MAR - 1 2007

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

MR. GARY GREIB
MANAGER, PRODUCT INVESTIGATIONS
AND SAFETY AFFAIRS
DELPHI
5825 DELPHI DRIVE
TROY, MI 48098-2815

NVS-215kjs
07E-015

Subject: AFTERMARKET FUEL PUMP MODULES

Dear MR. GREIB:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BUICK/SKYLARK/1996-1998
CHEVROLET/CAVALIER/1996-1998
DELPHI/FG0049-11B1/9999
DELPHI/FG0170-11B1/9999
DELPHI/MU269/9999
DELPHI/MU55/9999
OLDSMOBILE/ACHIEVA/1996-1998
PONTIAC/GRAND AM/1996-1998
PONTIAC/SUNFIRE/1996-1998

NHTSA Campaign Number: 07E-015

Mfg's Report Date: February 21, 2007

Components:

FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Potential Number of Units Affected: 43

Summary:

CERTAIN DELPHI AFTERMARKET FUEL PUMP MODULES / MODULE RESERVOIR ASSEMBLIES (MRAs) THAT WERE SOLD FOR USE ON THE ABOVE LISTED VEHICLES. DURING PRODUCTION THE MRAS VENT AND FUEL RETURN TUBES WERE REVERSED. THIS CONDITION CAN RESULT IN THE VEHICLE NOT RUNNING CORRECTLY (IDLE ROUGH AND/OR STALL) DUE TO AN OVERLY RICH FUEL BLEND OR THE VEHICLE'S EVAPORATIVE EMISSION CARBON CANISTER MAY LEAK FUEL.

Consequence:

A STALLED VEHICLE CAN INCREASE THE RISK OF A VEHICLE CRASH. A FUEL LEAK CAN RESULT IN A FIRE.

Remedy:

DELPHI WILL NOTIFY OWNERS AND REPLACE THE DEFECTIVE MRAS FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING MARCH 2007. OWNERS CAN CONTACT DELPHI AT 1-877-335-7443.

Notes:

THIS RECALL ONLY PERTAINS TO AFTERMARKET DELPHI FUEL PUMP MODULES AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON VEHICLES MANUFACTURED BY GENERAL MOTORS CORPORATION. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV).


Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Delphi must file a sample of the envelope which you intend to use to mail the recall notice to owners. The words "SAFETY", "RECALL", "NOTICE" in any order must be printed on the envelope in larger font than the customers name and address.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227 or by email at KELLY.SCHULER@DOT.GOV. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

A handwritten signature in black ink, appearing to read "G. Person", with a long horizontal flourish extending to the right.

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement