



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

SEP 17 2007

1200 New Jersey Avenue, SE
Washington, DC 20590

MS. MARCIA ALBRIGHT
VICE PRESIDENT AND GENERAL MANAGER
CEQUENT ELECTRONICS PRODUCTS
101 SPIRES PARKWAY
TEKONSHA, MI 49092

NVS-215kjs
07E-066

Subject: 90 DEGREE 7-WAY RIGHT ANGLE ADAPTORS/TOW ASSEMBLIE

Dear MS. ALBRIGHT:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

CEQUENT/5197410 /9999
CEQUENT/5197411/9999
CHEVROLET/SILVERADO/1999-2007
DODGE/RAM/2000-2007
FORD/F150/1997-2007
FORD/F250/1997-2007
FORD/F350/1999-2007
FORD/F450/1999-2007
FORD/F550/2004-2007
FORD/F550 SUPER DUTY/1999-2003
FORD/F550 SUPERDUTY/2004
GMC/SIERRA/1999-2006
GMC/SIERRA CLASSIC/2007

NHTSA Campaign Number: 07E-066

Mfg's Report Date: August 24, 2007

Components:

EQUIPMENT:ELECTRICAL

Potential Number of Units Affected: 175

Summary:

CERTAIN CEQUENT 90 DEGREE 7-WAY RIGHT ANGLE ADAPTORS SOLD BY DISTRIBUTORS IN TOW PACKAGES FOR AFTERMARKET SALES TO TOW 5TH WHEEL RV TRAVEL TRAILERS. DUE TO INCORRECT WIRING OF THE HARNESS, THE TRAILER LIGHTS MAY NOT OPERATE PROPERLY.

Consequence:

IF THE TRAILER LIGHTS ARE NOT WORKING PROPERLY, A VEHICLE CRASH CAN OCCUR.

Remedy:

ALL OF THE DEFECTIVE TOW PACKAGES ARE STILL AT THE DISTRIBUTOR LEVEL AND HAVE NOT BEEN SOLD TO ANY CONSUMERS.

Notes:


THIS RECALL ONLY PERTAINS TO AFTERMARKET CEQUENT TOW PACKAGES AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON DAIMLERCHRYSLER, GMC, OR FORD VEHICLES. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Since all the affected units have not been sold to consumers, no further action is required by Cequent. However, in order for us to complete our file, please provide one quarterly report when all tow packages have been corrected so we may close this issue.

Your contact for this recall will be Kelly Schuler, who may be reached by phone at 202-366-5227 or by email at KELLY.SCHULER@DOT.GOV. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement

Cc: Chris Grigorian
Arent Fox, Kintner, Plotkin & Kahn
1050 Connecticut Avenue, NW
Washington, DC 20036-5339