

**GM SERVICE AND PARTS OPERATIONS**  
**DCS1854**  
**URGENT - DISTRIBUTE IMMEDIATELY**

Date: September 19, 2007

Subject: Upcoming Product Safety Recall 06230  
and Special Coverage Adjustment 07203  
Fuel Tank Inlet Check Valve

Models: 2001-2004 Pontiac Montana and Aztek  
2002-04 Chevrolet Venture  
2002-04 Buick Rendezvous

To: All Chevrolet, Pontiac, and Buick Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Service Manager,  
Used Car Manager, Parts Manager and Warranty Administrator

In the near future, General Motors will be releasing Product Safety Recall 06230. Involved are some 2001-2004 Pontiac Montana and Aztek vehicles and some 2002-2004 Chevrolet Venture and Buick Rendezvous vehicles. Specifically, the vehicle population is:

- Rendezvous and Aztek vehicles built in May 2003 and registered anywhere in the U.S.;
- Venture and Montana vehicles built in June through August 2002 and registered anywhere in the U.S.; and
- 2001-2004 Pontiac Montana and Aztek vehicles and 2002-2004 Chevrolet Venture and Buick Rendezvous vehicles registered in Nevada, Arizona, Virgin Islands, Puerto Rico and Hawaii.

On some of these vehicles, a fracture of the fuel tank inlet check valve (ICV) may allow fuel vapors to pass through and allow droplets of fuel to accumulate on the side of the fuel tank. To correct this condition, dealers will replace the fuel tank. A total of 20,594 vehicles are involved.

This information was previously shared with all involved dealers via GM Administrative Message #WIR20070412 dated August 9, 2007.

GM also intends to provide "special coverage" for certain vehicles that were not included in this recall but have experienced the ICV failure described above. Special Coverage Adjustment 07203 will be released with Product Safety Recall 06230 in the near future.

Until these field actions are released, we are requesting dealership management to review on a case-by-case basis any situation where a customer presents an involved vehicle exhibiting this condition.

END OF MESSAGE  
GM SERVICE AND PARTS OPERATIONS