



December 10, 2007

**VIA E-MAIL  
RECEIPT CONFIRMATION REQUESTED**

**07V-585  
(2 pages)**

Mr. George H. Person  
National Highway Traffic Safety Administration  
Office of Defects Investigation  
1200 New Jersey Ave SE  
Washington, DC 20590

Re: Keystone RV Company  
Defect and Non-Compliance Report

Dear Mr. Person:

Keystone RV Company ("Keystone") has decided that a defect which relates to motor vehicle safety exists in the recreational vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

- A. Recall Population and Vehicle Identification. The recall population includes the following product brands manufactured by Keystone.

<u>Product Brand</u>	<u>Number of Vehicles</u>
2007 Everest Fifth Wheels Production Dates: 10/26/2006 – 4/3/2007 VIN Range: 4YDF320207E771020 - 4YDF320227E771729	75
2008 Everest Fifth Wheels Production Dates: 5/31/2007 – 9/27/2007 VIN Range: 4YDF320248E770034 - 4YDF320288E770473	44
2007 Challenger Fifth Wheels Production Dates: 9/22/2006 – 3/29/2007 VIN Range: 4YDF32S297E750776 - 4YDF32S227E751543	62
2008 Challenger Fifth Wheels Production Dates: 5/30/2007 – 10/11/2007 VIN Range: 4YDF32S278E750020 - 4YDF32S238E750550	42

RECEIVED

2007 DEC -17 A 10:35

The total number of vehicles subject to this recall campaign is: 223

Mr. George H. Person

December 10, 2007

Page 2

- B. Description of Defect. The vehicles subject to this recall campaign may have been manufactured with the LP line for the slide room too close to the tire. This causes an increased risk of property damage and fire.
- C. Basis for Determining that a Defect Exists. A delivery driver reported the LP line contacted the tire and damaged the LP line. All Everest model 320T and Challenger model 32SAT are included in the recall population.
- D. Remedying of Defect. The remedy is to reroute the LP line away from the tire.
- E. Owner Notifications. Keystone will notify the owners of the recreational vehicles by letter beginning on December 17, 2007 pending NHTSA approval. A final copy of the owner letter will also be provided to NHTSA, along with the dealer repair procedures.
- F. Quarterly Reporting Requirements. Keystone will be filing quarterly reports in connection with this recall campaign.
- G. Campaign Number. Keystone's identification code for this recall is 07-096.

If you need any additional information regarding this recall campaign, please feel free to contact me at 574-537-3925.

Sincerely,

Garett Carolus  
Keystone RV Company  
Technical Manager