

# SAFTY RECALL CAMPAIGN

ALL 2005-2007 GT 650-S-R AND GV650 MODELS

FUEL CAP INSPECTION / MODIFICATION

Dear Hyosung Owner:

This notice is being sent in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Hyosung Motors America has decided that a defect which relates to motor vehicle safety exists in certain 2005-2007 50 state GV650, GT650, GT650S, GT650R motorcycles for fuel tank venting issues, leading to either fuel leaks or fuel starvation. An indication of the venting problem is the sound of high pressure releasing when the fuel cap is opened

Our records indicate that you own or have owned one of the above stated models and that your unit did not receive this service procedure at assembly or pre delivery service.

Federal regulations require any lesser receiving this recall notice must forward a copy of this notice to the lessee with in 10 days

## **WARNING**

A fuel leak combined with a source of ignition could cause a fire.

Fuel starvation could cause loss of engine power resulting in an accident.

Hyosung motors America recommends that you not operate your vehicle until it is checked and or repaired by an authorized dealer. This service will be provided free of charge. Upon receiving this letter schedule an



appointment with your closest Hyosung dealer to have your motorcycle inspected and or repaired. The repair should take less than 30 minutes to complete.

For a listing of dealers, visit [www.hyosungmotorsusa.com](http://www.hyosungmotorsusa.com) or call 770-447-5571 for assistance.

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov> <<http://www.safercar.gov/>>.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Hyosung Motors America at 770-447-5571.

Thank you for choosing Hyosung.