

SAFETY RECALL NOTICE

Dear <CustomerName>:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Your <Year> model year <vehicle_series> <Vehicle_Name>, VIN <VIN>, is involved in safety recall 08V-251.

WHAT IS THE CONDITION?

The manufacturer, Isuzu Motors Limited, has decided that a defect, which relates to motor vehicle safety, exists in certain 2006 AND 2007 model year <Vehicle_Series> <Vehicle_Make> vehicles produced between June 2006 and March 2007 with a diesel engine. Diesel fuel may seep or leak from the fuel pipe at the upper or lower fuel port on the diesel fuel supply pump. Fuel leakage in the presence of an ignition source presents a risk of fire.

WHAT WE WILL DO

To correct this condition, your Isuzu dealer will inspect the fuel supply pump for the above condition. If no seepage or leakage is detected, the fuel pipe fittings will be tightened to the improved torque specification on 30 N-m. If seepage or leakage is detected, the fuel supply pump will be replaced with a new one. This service will be performed for you at **no charge**.

WHAT YOU SHOULD DO

To limit any possible inconvenience, and in order to ensure that the necessary parts are obtained, we recommend that you contact your <Vehicle_Make> dealer as soon as possible to schedule an appointment to bring your vehicle in to have this work performed. Present this Owner Notification Letter at the time of your appointment or refer to Campaign Service Bulletin CB08-J-001. Isuzu estimates that the inspection will take approximately 20 minutes to perform. If the fuel supply pump requires replacement, an additional 2 hours will be required. However, additional time may be necessary depending on how appointments are scheduled and processed at your dealership. To locate the nearest <Vehicle_Make> dealer you can visit our website at www.isuzucv.com and click on the dealer locator icon and enter your zip code or state. Should you not have access to a computer terminal please contact our Customer Relations Department at the number listed below.

Isuzu Commercial Truck of America
Customer Relations
1-866-441-9638

If, after contacting your <Vehicle_Make> dealer or the National Office with any problems, you still are not satisfied that we have done our best to remedy this condition without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience which this action may cause you.

Sincerely,

Isuzu Commercial Truck of America

Important: If you have sold or traded your Isuzu vehicle, please enter the owner's name and address, if known, on the attached "Change of Information" postcard, tear off at both perforations, and drop it in the mail. Postage has already been paid. We will contact the new owner.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. Lessor means a person or entity that is the owner, as reflected on the vehicle title, of any five or more leased vehicles.