

**Acura Recall Voice Alert to Customer**

**NHTSA ID: 12V-222**

**Date: June 15, 2012**

Acura recently mailed to you an important safety recall notice regarding your 2007 or 2008 TL. This notice explains that a problem potentially exists with your power steering feed hose that may cause it to leak, possibly causing smoke and increasing the risk of fire. The notice also outlines what you need to do, including how to obtain the recall repair, free of charge, at any authorized Acura dealer. If you need help finding an Acura dealer, or do not receive the notice within five days, please call 1-800-382-2238, and select option 4. Thank you.