



Safety Recall Campaign #R84001/NHTSA Recall #12V-409

August 29, 2012

Dear CODA Owner,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. CODA Automotive (CODA) has decided that a defect, which relates to motor vehicle safety, may exist in certain model year 2012 CODA vehicles and has initiated a voluntary recall.

Our records indicate that your vehicle is included in the population of vehicles listed in the recall. CODA has determined that the roof-mounted side curtain airbag(s) on your vehicle may not have been properly installed. In the event of a side impact that requires the deployment of a side curtain airbag, an improperly installed side curtain airbag may not deploy as intended and thereby increase the risk of injury.

CODA dealers will inspect and correct the installation as needed, at no cost to you. The time required to inspect your vehicle will be about 25 minutes. Should a correction be needed, the required time would be about 1 hour and 15 minutes. However, depending on your dealer's work schedule, the time required may vary. Please note that no part replacement should be required.

Your safety is of great concern to us. Please contact your local authorized CODA dealer at your earliest convenience to schedule an appointment for this inspection and mention Recall Campaign #R84001. Your dealer is prepared to answer any questions you may have regarding this recall. If, however, you require further assistance, please call CODA at 855-GO-4-CODA.

If you believe that CODA or your dealer has failed to, or is unable to, perform this procedure without charge and within a reasonable amount of time, please call us at 855-GO-4-CODA. You may also submit a complaint to the Administrator of the National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

CODA holds itself to the highest safety standards and continually strives to offer the most reliable product for its customers. We apologize for any inconvenience this may cause.

Sincerely,

Michael Robinson
Director, Product Safety and Regulatory Compliance

2340 Fairfax Avenue, Los Angeles, CA 90016, 1-855-GO-4-CODA (1-855-464-2632)
codaautomotive.com



Registered Trademark of CODA Automotive, Inc., Los Angeles, California, USA