

June 26 , 2013

>>Customer Name<<

>>Date<<

>>Adress<<

>>Country<<

SUBJECT: Fuel Tank may Leak

Ref: NHTSA # 13V-185

TEMSA Service Bulletin # TS-S36

Attention Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Temsa Global has decided that a defect which relates to motor vehicle safety exists in certain model year 2011-2013 TS35C motorcoaches. Due to a production process error, the fuel tank may develop a leak. A fuel leak in the presence of an ignition source may result in a fire. Please see the enclosed TEMSA Service Bulletin TS-S36 for further information and remedy action.

Temsa is conducting a recall to remedy the Fuel Tank. The recall work will be provided at no cost to you. Temsa records indicate that you are the owner or operator of the following vehicle(s) included in this recall:

>>Units_Number<<

Temsa strongly urges you to have the recall work performed on your vehicle(s) as quickly as possible. You may contact CH Bus Sales at 407-271-8935 if you have any questions about this recall campaign. Approximate repair time for each effected vehicle is given in the Technical Service Bulletin TS-S36.

If you have sold or otherwise transferred the vehicle(s) identified above, please contact CH Bus Sales at 407-271-8935 with all of the information you have regarding the current owner/operator of the vehicle(s).

Federal law requires any lessor who receives a notification of a determination of a safety related defect or noncompliance pertaining to any leased motor vehicle shall send the notice to the lessee within 10 days.

After contacting your dealer, if you are still not able to have the defect remedied without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC. 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

YOLGECEN MAH,
TURHAN CEMAL BERIKER BULV,
NO:561
01323 ADANA, TURKEY



TEMSA GLOBAL
SANAYİ VE TİCARET A.Ş

We regret the inconvenience this may cause you, but urge you to implement the recall procedures with respect to your vehicle(s) as soon as possible for your added safety and satisfaction.

Sincerely,

Muhammet CAN
International Customer Services Manager

Enclosure : Service Bulletin # TS-S36

YOLGECEN MAH,
TURHAN CEMAL BERIKER BULV,
NO: 561
01323 ADANA, TURKEY