



Kyle Bowker

Office of Defects Investigation

U.S. Department of Transportation

National Highway Traffic Safety Administration

1200 New Jersey Avenue SE

Washington, DC 20590

Re: PE13-019

Dear Mr. Bowker:

7/31/13

Agility Fuel Systems is pleased to provide the following submissions in response to NHTSA's request for additional information for the above reference preliminary investigation. Please find attached the following documents:

1. Agility Fuel Systems Response to NHTSA Preliminary Evaluation
2. Youngdo Failure Mode Description
3. 8D Corrective Action Request (CAR)
4. Old Side Mount Strap Cycle Issue ENR-015 Test Report
5. Freightliner Side Mount Installation ENP-051

Also, Agility has enclosed the requested Youngdo valve components and a flash drive with all requested production, incident, and warranty data as well as electronic copies of all of the above documents.

If you have any questions, or if there is any additional information or clarifications that Agility can provide, please let me know.

Sincerely,

A handwritten signature in black ink, appearing to be "Ron Eickelman".

Ron Eickelman

President

Sincerely,

A handwritten signature in black ink, appearing to be "Yoshio Coy".

Yoshio Coy

Direction of Product Support

(Signed by Yoshio Coy on behalf of Ron Eickelman)