



FORKS RV, INC.  
EST 1991

11280W-US 20  
SHIPSHEWANA, IN 46565

---

PHONE – 574-825-7467

[www.forksrv.com](http://www.forksrv.com)

FAX – 574-825-1118

This is in response to the request for information pertaining to Safety Recall EQ 13-004, which was first sent out to us on June 20, 2013 and then subsequently on July 29, 2013 (of which neither correspondence reached us), until email version of the stated correspondence was successfully received on August 15, 2013.

We were able to trace the potentially one (1) member of the targeted population reported to have come through our Stream of Dometic Awnings (produced in the stated limited period of February 13, 2013 to April 9, 2013) to Owners' Jim and Sue Steiner of 11300 E Shore Dr., Whitmore Lake, MI 48189.

Following up on contact from within this organization to alert the owners about the Recall campaign that Dometic had launched, the above named owners made direct contact with Dometic. In reaction to that end customer and Product manufacturer contact, Dometic dispatched an assigned technical field representative to the Customer's Trailer (VIN 1F9SDB326ES217007) to implement what action was necessary and due, if any, on June 22, 2013. Please permit me to submit a copy of that work order (attached) to substantiate the statement just made. It is worth noting that this remedial action proceeds when the first correspondence from the DOT was dispatched to FRV.

We screened all of our 2013 Awning procurement from Dometic, not limiting our review process to the stipulated period of February 13, 2013 to April 9, 2013 and came to the factual conclusion that of the 16 issued "prefixes" to be scrutinized only one of the listed "prefixes" i.e. "915" was relevant to our acquisitions, all the other starting serial numbers turned out to be irreconcilable with/to our rather lean stock.

We have come to the conclusion that no further action on our part is required and would hereby disclose our intent to conduct no recall specifically pertaining to this pertinent safety concern to which has been assigned the identification EQ 13-004. Thanks for your vigilance and guidance which addressed my questions and ultimately guided me to this point of closure. Respectfully,

Bubu C. Zaney,

Assistant Parts, Warranty and Service Administrator.