



RECEIVED

By Recall Management Division at 10:46 am, Nov 04, 2013

Bombardier Recreational Products Inc.
726 Saint-Joseph Street
Valcourt, Québec, Canada J0E 2L0

www.brp.com

13V-386 - Amended

October 29, 2013

By email only

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE, W45-306
Washington, DC 20590

Re: AMENDED Defect Information Report Pursuant to 49 CFR Part 573 – Tandem Master Cylinder Manifold Inlet- Fire Hazard- Model Year 2013 Can-Am® Spyder® roadsters RT series and ST series

Dear Ms. Lewis:

Please find an amendment to our August 27, 2013 report. Only section 573.6 (c) (3) changes.

We realized that the number of vehicle potentially affected provided in August was only the total number for RT series. The correct total number should have included ST and RT series. However, all those vehicles were correctly included in our recall deployment at the time.

- **573.6 (c) (3) Number of Vehicles Potentially Affected:**
Approximately 5042 vehicles.

AMENDED October 29, 2013:
Approximately 8072 vehicles .

If you have any questions, please contact the undersigned.

Sincerely yours,

BRP
Marie-Claude Simard
Manager, Product Safety
Legal Department
T. 450-532-6195
marie-claude.simard@brp.com

Ski-Doo
Lynx
Sea-Doo
Evinrude
Johnson
Rotax
Can-Am