



*MAZDA MOTOR CORPORATION*

3-1, Shinchi, Fuchu-cho, Aki-gun  
Hiroshima 730-8670, Japan

TEL : +81-82-287-4591  
FAX : +81-82-287-5219

January 29, 2014

Our Ref. No. FQ140129-01

Recall Management Division (NVS-215)  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue, SE  
Washington, DC 20590

Re: Submission of Quarterly Report for the Fourth Quarter of 2013

In accordance with the provisions of Section 573.7, Part 573, Title 49, we enclose the quarterly report on the following Recall Campaign ID Number.

- |             |  |              |
|-------------|--|--------------|
| (1) 12V-357 | 2001-2008 TRIBUTE Engine Cover Modification            | (5th report) |
| (2) 13V-130 | 2003-2004 Mazda6 and 2004 RX-8 Front Passenger Air Bag | (3rd report) |
| (3) 13V-425 | 2009-2013 Mazda6 Door Latch Mounting Screws            | (1st report) |

If there are any questions regarding this report, please contact David Robertson of Mazda North American Operations at (313) 594-7778.

Sincerely yours,

*S. Fujiyama*  
Shunichi Fujiyama  
Manager  
Field Quality Group  
Field Quality Department  
Mazda Motor Corporation

Enclosed: Quarterly Report

cc: Mazda North American Operations Irvine Office  
Mazda North American Operations Allen Park Office

*zoom-zoom*

Safety Recall Quarterly Report Information  
Required per 49 CFR Part 573.7

Report Date: January 28, 2014 Calendar Quarter: The Fourth quarter of 2013

Safety Recall Quarterly Report from October 1, 2013 through December 31, 2013

Manufacturer: Mazda Motor Corporation

Recall Subject: 2009-2013 Mazda6 Door Latch Mounting Screws

1. NHTSA Safety Recall Campaign Number: 13V-425  
Mazda Recall Campaign Code Number: #70131

2. The date notification to purchasers began: October 29, 2013  
The date notification of purchasers was completed: October 29, 2013

3. The Total Number of Items Involved: 161,352 units  
Number of Items Returned from Inventory or Remedied Prior to Sale: 35 units

4. Total Number of Receiving Corrective Action: 47,362 units

Repair Procedure	Number
Inventory Return	35
Inspection Only	44,344
Repaired/Replaced	2,983
<b>Total</b>	<b>47,362</b>

5. Items Determined to be Unreachable

Total Number Exported: 0 units

Total Number Stolen: 0 units

Total Number Scrapped: 1,025 units

Total Number Unable to Notify: 3,260 units

Total Number Otherwise Unreachable:

Vehicle sold, name/address not provided 273 units  
Do not own a Mazda 17 units  
Blank reply card returned 100 units

**Total** 390 units