

Vehicle Safety Recall Quarterly Status Report

Required per 49 CFR Part 573.7

Report Date: January 30, 2014 **Calendar Quarter:** Fourth

Safety Recall Quarterly Report from October 1, 2013 **through** December 31, 2013

Manufacturer Name: Suzuki Motor Corporation

Report Author: Luis Hernandez **Phone:** (714) 996-7040 Ext. 2203

Recall Subject: Replacement of Front Brake Master Cylinder on certain GSX-R600/R750/R1000 models

1. NHTSA Safety Recall Campaign Number: 13V-449

Suzuki Campaign Number: 2A31, 2A32, 2A33, 2A34, 2A35, 2A36

2. (a) The date notification to purchasers began: November 18, 2013

(b) The date notification of purchasers was completed: November 18, 2013

3. The Total Number of Vehicles Involved: 210,228

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 14,506

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & Not Requiring Remedy: 0

Total number of vehicles involved in the recall and inspected, but determined to not require remedial or recall repair work.

5. Vehicles Determined to be Unreachable

Number Exported: 1802

Number Stolen: 544

Number Scrapped: 332

Number of Undeliverable Notification Letters: 18,312

Number Otherwise Unreachable: 0

Describe Other: _____