

Equipment Safety Recall Quarterly Report Information

Report Date: April 16, 2014

Calendar Quarter (circle one): January 1 – March 31

April 1 – June 30

July 1 – September 30

October 1 – December 31

Manufacturer (name, address, phone): Unknown; this product was purchased from/thru Yuan-Liang Machine Co. Ltd. which placed the order through their China manufacturers.

Yuan-Liang Machine Co. Ltd., No. 35, Lane 2, Sec. 3, Ya Hwan Rd, Taya Shiang, Taichung, Hsien, Taiwan, R.O.C.

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Kuryakyn Holdings, LLC

Robert Hinton

454 County Road V V, Somerset, WI 54025

Phone (715) 247-3576 Fax: (715) 247-5978 E-mail: bob@kuryakyn.com

Subject equipment (type of equipment, part/model number, and any other information necessary for identifying the equipment):

Kuryakyn Handlebar Risers/Setbacks for GI1800 (Kuryakyn part number 7437), sold between

April 3, 2013 and July 1, 2013.

1. NHTSA Safety Recall Campaign Number: 13E-037

Manufacturer's assigned campaign number (where applicable): N/A

2. (a) The date notification to purchasers began: September 4, 2013 (Interim letter)

(b) The date notification of purchasers was completed: September 16, 2013

(c) The date notification to dealers and distributors began: July 1, 2013 (Stop-Sale letter)

(d) The date notification of dealers and distributors was completed: September 16, 2013

3. The total number of items of equipment involved: 232 (in-stock at retailers' locations and those already sold to consumers as of announcement of recall)

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 30 (number of retrofit kits mailed direct to consumers by Kuryakyn before April 1, 2014)

(b) Total number inspected, but determined NOT to require the remedy: 0

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: 0

Theft: 0

Scrapping: 0

Failure to receive a notification of the recall: 0

Other reasons (specify below): 326*

*Total number of retrofit kits mailed to retailers and distributors before April 1, 2014.

NOTE: If a consumer or retailer/distributor requested a retrofit kit, one was mailed to him/her. Therefore, the total from responses 4 and 5 will exceed the quantity recorded in response 3.

Total number of items of equipment unreachable for inspection: Unknown

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 218

REVISED – 2013 Report

Equipment Safety Recall Quarterly Report Information

Report Date: April 16, 2014

Calendar Quarter (circle one): January 1 – March 31

April 1 – June 30

July 1 – September 30

October 1 – December 31

Manufacturer (name, address, phone): Unknown; this product was purchased from/thru Yuan-Liang Machine Co. Ltd. which placed the order through their China manufacturers.

Yuan-Liang Machine Co. Ltd., No. 35, Lane 2, Sec. 3, Ya Hwan Rd, Taya Shiang, Taichung, Hsien, Taiwan, R.O.C.

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Kuryakyn Holdings, LLC

Robert Hinton

454 County Road V V, Somerset, WI 54025

Phone (715) 247-3576 Fax: (715) 247-5978 E-mail: bob@kuryakyn.com

Subject equipment (type of equipment, part/model number, and any other information necessary for identifying the equipment):

Kuryakyn Handlebar Risers/Setbacks for GL1800 (Kuryakyn part number 7437), sold between April 3, 2013 and July 1, 2013.

1. NHTSA Safety Recall Campaign Number: 13E-037

Manufacturer's assigned campaign number (where applicable): N/A

2. (a) The date notification to purchasers began: September 4, 2013 (Interim letter)

(b) The date notification of purchasers was completed: September 16, 2013

(c) The date notification to dealers and distributors began: July 1, 2013 (Stop-Sale letter)

(d) The date notification of dealers and distributors was completed: September 16, 2013

3. The total number of items of equipment involved: 232 (in-stock at retailers' locations and those already sold to consumers as of announcement of recall)

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 12 (number of retrofit kits mailed direct to consumers by Kuryakyn before October 1, 2013)

(b) Total number inspected, but determined NOT to require the remedy: 0

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: 0

Theft: 0

Scrapping: 0

Failure to receive a notification of the recall: 0

Other reasons (specify below): 317*

*Total number of retrofit kits mailed to retailers and distributors before October 1, 2013.

NOTE: If a consumer or retailer/distributor requested a retrofit kit, one was mailed to him/her. Therefore, the total from responses 4 and 5 will exceed the quantity recorded in response 3.

Total number of items of equipment unreachable for inspection: Unknown

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 218

Note: Report revised on April 16, 2014 to exclude promotional items that were mistakenly reported on line 5 of the original report.

REVISED – 2013 Report

Equipment Safety Recall Quarterly Report Information

Report Date: April 16, 2014

Calendar Quarter (circle one): January 1 – March 31

April 1 – June 30

July 1 – September 30

October 1 – December 31

Manufacturer (name, address, phone): Unknown; this product was purchased from/thru Yuan-Liang Machine Co. Ltd. which placed the order through their China manufacturers.

Yuan-Liang Machine Co. Ltd., No. 35, Lane 2, Sec. 3, Ya Hwan Rd, Taya Shiang, Taichung, Hsien, Taiwan, R.O.C.

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Kuryakyn Holdings, LLC

Robert Hinton

454 County Road V V, Somerset, WI 54025

Phone (715) 247-3576 Fax: (715) 247-5978 E-mail: bob@kuryakyn.com

Subject equipment (type of equipment, part/model number, and any other information necessary for identifying the equipment):

Kuryakyn Handlebar Risers/Setbacks for GL1800 (Kuryakyn part number 7437), sold between April 3, 2013 and July 1, 2013.

1. NHTSA Safety Recall Campaign Number: 13E-037

Manufacturer's assigned campaign number (where applicable): N/A

2. (a) The date notification to purchasers began: September 4, 2013 (Interim letter)

(b) The date notification of purchasers was completed: September 16, 2013

(c) The date notification to dealers and distributors began: July 1, 2013 (Stop-Sale letter)

(d) The date notification of dealers and distributors was completed: September 16, 2013

3. The total number of items of equipment involved: 232 (in-stock at retailers' locations and those already sold to consumers as of announcement of recall)

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 25 (number of retrofit kits mailed direct to consumers by Kuryakyn before January 1, 2014)

(b) Total number inspected, but determined NOT to require the remedy: 0

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: 0

Theft: 0

Scrapping: 0

Failure to receive a notification of the recall: 0

Other reasons (specify below): 326*

*Total number of retrofit kits mailed to retailers and distributors before January 1, 2014.

NOTE: If a consumer or retailer/distributor requested a retrofit kit, one was mailed to him/her. Therefore, the total from responses 4 and 5 will exceed the quantity recorded in response 3.

Total number of items of equipment unreachable for inspection: Unknown

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 218

Note: Report revised on April 16, 2014 to exclude promotional items that were mistakenly reported on line 5 of the original report.