

## Equipment Safety Recall Quarterly Report Information

Report Date: June 5, 2014

Calendar Quarter (circle one): January 1 – March 31

April 1 – June 30

July 1 – September 30

October 1 – December 31

Manufacturer (name, address, phone): KONI North America, LLC

1961-A International Way, Hebron, KY 41048

(859) 586-4100

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Sarah Wilson, Esq., Counsel for KONI by, Covington & Burling LLP, 1201 Pennsylvania Ave.,

NW, Washington, DC 20004, swilson@cov.com, (202) 662-5397, FAX: (202) 778-5397

Gordon Benson, 1961-A International Way, Hebron, KY 41048, gordon.benson@itt.com,

(859) 499-0343, FAX: (859) 334-3340; (800) 209-3350

Subject equipment (type of equipment, part/model number, and any other information necessary for identifying the equipment):

Type of Equipment: Shock Absorbers

Part/Model Numbers: 8245-1146L, 8245-1146R, 8245-1201L, 8245-1201E, 8245-1203L, 8245-1203R

Inclusive Dates of Manufacture: January 2008 through April 2013

1. NHTSA Safety Recall Campaign Number: 13E-023

Manufacturer's assigned campaign number (where applicable): N/A

2. (a) The date notification to purchasers began: May 16, 2013

(b) The date notification of purchasers was completed: May 16, 2013

(c) The date notification to dealers and distributors began: May 16, 2013

(d) The date notification of dealers and distributors was completed: May 16, 2013

3. The total number of items of equipment involved: 39

**NOTE:** The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 8

(b) Total number inspected, but determined NOT to require the remedy: 0

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: 8

Theft: 0

Scrapping: 2

Failure to receive a notification of the recall: 19

Other reasons (specify below): 2

~~Customer had contacted with us. Replacements were sent to customer. Old units have not been received and likely not coming back. Multiple tries have been attempted to reach other customers following all leads possible but have all either hit dead ends (disconnected numbers, businesses no longer in service) or not receiving call backs.~~

---

Total number of items of equipment unreachable for inspection: 31

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 14 (not included in 39 total)