



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 8, 2014

Mr. Matthew Welch
Homologation Engineer
Morgan 3 Wheeler Limited
Pickersleigh Road
Malvern Link
Worcestershire WR142LL

NVS-215SM
14V-384

Subject: Missing Brake Failure Warning Lamp/FMVSS 122a

Dear Mr. Welch:

This letter serves to acknowledge Morgan 3 Wheeler Limited's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MORGAN/3W/2012-2014

Mfr's Report Date: July 1, 2014

NHTSA Campaign Number: 14V-384

Components:

SERVICE BRAKES, HYDRAULIC:SWITCHES:BRAKE WARNING

Potential Number of Units Affected: 235

Problem Description:

Morgan 3 Wheeler Limited (Morgan) is recalling certain model year 2012-2014 3W motorcycles. The affected motorcycles were manufactured without a lamp that illuminates only when the brake fluid level is low. As such, these vehicles do not conform to Federal Motor Vehicle Safety Standard No. 122a, "Motorcycle Brake Systems."

Consequence:

Without a warning to the operator that the motorcycle has low brake fluid and that the brakes may fail as a result, there is an increased risk of a crash.

Remedy:

Morgan will notify owners, and dealers will install warning lamp that warns of low brake fluid, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Morgan's US Agent at 1-505-570-1845.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah McShane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a large initial "J" and a long horizontal stroke at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement