



SAFETY RECALL NOTICE

<i>NUMBER</i>	TSB-ERT10	<i>TYPE</i>	ALERT		
<i>TITLE</i>	ERT10 AND ERT01 WARNING TRIANGLE RECALL NOTICE				
<i>REV</i>	A	<i>ISSUED</i>	8/25/2014	<i>REVISED</i>	-
<i>AFFECTS</i>	ALL ERT01 AND ERT10 WARNING TRIANGLES				
<i>INFORMATION</i>	<p>Buyers Products has decided that a noncompliance with FMVSS125 exists in the ERT10 and ERT01 Warning Triangles. Accordingly, a recall to address this issue is being initiated effective 8/25/2014. The noncompliance involves stability under high wind conditions which may result in the warning triangle deflecting excessively or moving under high winds. This may result in the triangle moving from it's intended location.</p> <p>Contact Buyers Products Customer Service at 440-974-8888 for an RMA# to return all ERT10 and ERT01 warning triangles. Customers with ERT10 and ERT01 warning triangles should be notified and refunded their purchase price. There are no replacement products at this time as the design is under engineering review.</p> <p>Please be reminded that it is a violation of Federal law for you to sell the equipment covered by this notification. Substantial civil penalties apply to violations of this law.</p> <p>Your assistance with this recall is appreciated. Buyers Products takes this matter very seriously and will work with our dealers to ensure that this is handled promptly.</p>				