

STARCRAFT

903 SOUTH MAIN STREET • P.O. BOX 460 • MIDDLEBURY, IN 46540 • TELEPHONE: (800) 945-4787 • WWW.STARCRAFTRV.COM

RECEIVED

By Recall Management Division at 9:00 am, Aug 19, 2014

August 18, 2014

Associate Administrator for Enforcement
Department of Transportation
National Highway Traffic Safety Administration
Office of Enforcement NVS-200 Room W45-306
1200 New Jersey Avenue S.E.
Washington, DC 20590

Dear Sir or Madam:

Pursuant to 49 CFR Part 573, Starcraft RV (“Starcraft” or the “Company”) is submitting this report to NHTSA concerning a recall campaign, which is being voluntarily initiated. Specific information is as follows:

573.6(c)(2)

Affected vehicles are certain 2015 Starcraft 16RB Launch travel trailers manufactured with the **Extreme Package Option**.

The affected vehicles were manufactured April 16, 2014 through April 21, 2014.

The recall population was determined from the manufacturing records for the Company’s manufacturing plants in Topeka, Indiana, which produced the affected recreational vehicles.

573.6(c)(3)

A total of 12 vehicles are subject to this recall.

Specific Vehicle Identification Numbers (VINs) are as follows:

1SABSHAH5F2JP5051 through 1SABSHAHXF2JP5062 F2JP5051 – F2JP5062

573.6(c)(4)

Starcraft is recalling 100 percent of the affected vehicles identified in the scope.

573.6(c)(5)

Starcraft has decided that certain 2015 Starcraft 16RB Launch travel trailers fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 120, "Tire selection and rims and motor home/recreation vehicle trailer load carrying capacity information for motor vehicles with a GVWR of more than 4,536 kilograms (10,000 pounds)". The cold tire inflation pressure should be 50 psi but instead 80 psi is printed on the Federal and Tire labels. All other information on the Federal ID Label is stated correctly.

573.6(c)(6)

Dealer contacted Jayco, August 18, 2014 that the PSI was noted incorrectly on the Federal ID and Tire label on a 2015 16RB Launch at his lot. During Jayco Investigation, was found that a data entry error occurred when noting the psi of the Launch travel trailers built with the Extreme package option.

573.6(c)(8)

The remedy for the affected vehicles is for Starcraft to reprint all the Federal ID Labels and Tire Labels noting the correct tire psi and Dealers to remove the incorrect labels and replace with the new labels showing the correct psi as 50lbs.

Starcraft is releasing corrected Federal ID and Tire labels to the Dealers and Retail owners on record prior to receiving a Recall number from NHTSA. Upon receipt of the recall number, Starcraft will provide all required documents under that assigned number. Starcraft is prepared to send the corrected labels on August 22, 2014. Retail notification letter is included with this 573 Report.

Thank you for your assistance,

Sincerely,

A handwritten signature in black ink that reads "Terri Tobias". The signature is written in a cursive, flowing style.

Terri Tobias
Regulatory Compliance Manager