



August , 2014

IMPORTANT SAFETY RECALL

Dear Final Stage Manufacturer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Spartan Motors Chassis, Inc. has determined that certain chassis and chassis cabs equipped with a hand throttle or pump control module supplied by Fire Research Corporation (FRC) may contain a safety related defect.

What is the problem?

Hand throttles and pressure governors, subject to this recall, may have have an issue witin the software that could cause a surge in engine speed, when the fire apparatus is in “pump mode.”

This increase in engine speed could cause an increase in water pressure at the end of a fire hose which could result in personal injury.

What should the final stage manufacturer do?

On the attached document, you will find a list of chassis or chassis cabs, which may have the suspect engines; Spartan Chassis has sold to you. If you agree the identified chassis, contains a safety defect, you are reminded of your responsibility to notify the National Highway Traffic Safety Administration (NHTSA) in accordance with 49CFR573. It is a violation of federal regulation to sell a vehicle subject to a safety recall without the recall first being remedied.

Contact a Spartan Motors Chassis, Inc. Customer Product Support group to schedule an appointment at your nearest Cummins distributor to have the fuel filter replaced at no charge.



1541 Reynolds Road Charlotte, MI 48813

SPARTANCHASSIS.COM

517.543.6400

For questions regarding warranty claims, please call ***Phone Number***.

We regret any inconvenience this situation may cause. Spartan Chassis is committed to customer safety and satisfaction.

Sincerely,