



Recall Campaign

NHTSA#: 14V-515

TC#: n/a

Job Code: 9901219

Flat Rate: 0.3 hr.

LABELS ARE ENCLOSED WITH THE NOTIFICATION

ACTION REQUIRED:

Replace incorrect carrying capacity label.

CANADA ONLY- replace the capacity portion of the carrying capacity label.

MODELS / UNITS:

2015 Jayco Seismic Fifth Wheels:

F19A 0062-0073

F19E 0059- 0064

F19F 0051-0061

KIT CONTENTS

Corrected label included with notification

TOOLS/MATERIAL REQ.:

Isopropyl Alcohol and shop rag

Instructions


Remove existing label(s)

1. There are (2) yellow carrying capacity labels. One is located on the outside off door side (road side) front of the unit, next to the Federal label. The second one is on the main entrance door. Remove the yellow label from both of these locations and discard them.
2. Using isopropyl alcohol and a shop rag, remove any adhesive residue from the surface where the original label had been. Allow the area to dry for at least 30 seconds.

Apply new label(s)

3. Remove the protective back from the new yellow carrying capacity label. Align the new label in the same location of the original label and apply it to the surface. Remove any air bubbles from the label. Repeat this process for the second label.

NOTE: Do not attempt to remove or adjust the label once it has come into contact with the surface. Doing so may damage the label or cause it not to adhere properly to the surface. IF A LABEL IS DAMAGED OR WILL NOT PROPERLY ADHERE TO THE SURFACE, A NEW LABEL MUST BE ORDERED.



US Cargo Carrying Capacity

Instructions - Canada Units ONLY


Remove existing label

1. Locate the existing carrying capacity portion of the Federal label on the outside off door side (road side) front of the unit. Remove the carrying capacity portion of the Federal label.

Apply new label

3. Remove the protective back from the new carrying capacity label. Align the new label in the same location of the original label and apply it to the surface. Remove any air bubbles from the label. Repeat this process for the second label.

NOTE: Do not attempt to remove or adjust the label once it has come into contact with the surface. Doing so may damage the label or cause it not to adhere properly to the surface. IF A LABEL IS DAMAGED OR WILL NOT PROPERLY ADHERE TO THE SURFACE, A NEW LABEL MUST BE ORDERED.



Canadian Cargo Carrying Capacity