



Harley-Davidson Motor Company, 3700 West Juneau Ave., PO Box 653, Milwaukee, WI 53201 414/342-4680

1

IMPORTANT SAFETY RECALL

JACOB KARPINSKI

This notice applies to your vehicle, VIN # 1HD1GNM28EC316467

Date 7/29/2014

Harley-Davidson Recall No. 0158

NHTSA Recall No. 14V-413

Dear Harley-Davidson Motorcycle Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that a defect which relates to motor vehicle safety exists in certain model year 2014.5 FXDL Dyna Low Rider motorcycles. We are notifying you because our records indicate that you own one of the affected motorcycles.

What is the Issue?

On motorcycles assembled with a top engine mount bracket assembly (P/N 16400026), excessive vibration can occur due to dealer or owner installation of certain performance (non-original equipment) Electronic Control Module (ECM) calibrations that allow the engine to operate above 5600 RPMs. This excessive vibration may cause the ignition switch to move from the "IGN" (ignition on) position to the "ACC" (accessory only) position, shutting the engine off. An unexpected engine shut-down while riding in traffic could lead to a crash. Harley-Davidson has initiated this recall to correct this condition in the affected motorcycles.

What Should You Do?

Please contact your authorized Harley-Davidson motorcycle dealer immediately and arrange an appointment to have your motorcycle repaired. Your dealer will confirm that your motorcycle is covered by this recall. If covered, the dealer will replace the engine mount bracket assembly and ignition switch knob with the components provided in the recall kit. The repair will take less than one hour to perform. To verify that the service has been completed, your dealer will ask you to sign a recall claim.

If you have sold your motorcycle and have an address for the current owner, it is important that you forward this notice to the new owner. Alternatively, you may contact us at the Harley-Davidson phone numbers listed below and provide us the contact information for your purchaser so that we may notify the new owner of this recall. Also, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

What If You Have Additional Questions or Concerns?

If you take your motorcycle to your dealer on a mutually agreed upon date and they are unable to perform the required service to your satisfaction, please contact Harley-Davidson Motor Company, Inc. for immediate assistance at 1-800-258-2464 in the U.S. or 1-414-343-4056 worldwide.

If you are still having difficulty getting your vehicle repaired in a reasonable time, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this may cause you, but we are initiating this action in the interest of your personal safety and satisfaction with our products. Thank you for your cooperation.

Sincerely,

Harley-Davidson Motor Company, Inc.
Recall 0158